

Douglas County Surveyor's Record of
Government Corners Renewed

31

T. S.

4

R. W. W. M.

ROKE-CHAPMAN CO., EUGENE, ORE. 21881

Closing Corner to Sections 7 & 18.

Found - Unmarked Stone & 3 BT's. per Gov't. Notes in good condition, faces overgrown.

I set Aluminum Tag on 7" Madrone, N.44 $\frac{1}{2}$ °E. 4.4 ft.

65

141

$\frac{1}{4}$ Section Corner to Sec. 18, West Side.

Old Corner Not Found.

I Set $\frac{3}{4}$ " Iron Pipe 30", 24" in ground.

Scribed: 13" D. Fir N.46 $\frac{1}{2}$ °E. 52.2 ft.

12" D. Fir S.24 $\frac{1}{2}$ °E. 25.3 ft.

66

140

Section Corner to Sections 7, 8, 17 & 18.

Found - Stone with Notches per Govt. Notes, but broken in two.

All BT's rotted out, but rotted Stumps for 3 Hemlocks present.

Scribe- 7" D. Fir N.73°20'W. 17.5 ft.

36" D. Fir N.64° E. 41.2 ft.

13" D. Fir S.42°40'E. 13.5 ft., with alum. tag.

14" D. Fir S.17° W. 42.5 ft.

67

$\frac{1}{4}$ Section Corner to Sections 7 & 18.

Old Corner Not Found.

I Set 6"x 8"x 12" Quartz Stone.

Scribe - 18" D. Fir S.74°W. 18.1 ft., Alum. Tag.

12" D. Fir N.45 $\frac{1}{2}$ °E. 21.6 ft.

68

136

$\frac{1}{4}$ Section Corner to Sections 18 & 17.

Found Fir Corner Tree and S. W. Fir BT. per Govt. notes in good condition.

Other O. B. T. rotted out.

Scribe - 10" Hemlock N. 17° E. 22.0 ft.

69

Center $\frac{1}{4}$ Corner for Section 18.

Set 1" Iron Pipe

Scribe - 10" D. Fir N.78°20'E. 9.2 ft.

12" D. Fir N.10 $\frac{1}{2}$ °W. 36.5 ft.

70

$\frac{1}{4}$ Section Corner to Sections 8 and 17, as determined by O. B. T's:

34" Fir S.29°E. 19.0 ft. dist. O. B.T.

40" Fir N.65°W. 36.0 ft. dist. O. B. T.

At Corner Point found 40" Fir mkd. on North face & Set 1" x 30"

Iron Pipe from which:

5" Cedar bears N.43°W. 23.0 ft. dist. mkd. $\frac{1}{4}$ S 8 B. T.

6" Cedar bears S.37°E. 38.4 ft. dist. mkd. $\frac{1}{4}$ S17 B. T.

4" Cedar bears N.37°E. 22.0 ft. dist. mkd. $\frac{1}{4}$ S 8 R4W B.T.

4" La. bears S.75°W. 18.5 ft. dist. mkd. $\frac{1}{4}$ S 17 B. T.

50" Fir bears S.64°E. 11.6 ft. dist. mkd. $\frac{1}{4}$ S17 B. T.

71

$\frac{1}{4}$ Section Corner to Sections 7 and 8, as determined by O. B. T's:

14" Fir S.47°E. 8.6 ft. O.B.T., fd. scribe.

At Corner Point found 40" Fir mkd. on East face &

Set $\frac{3}{4}$ " x 36". Iron Pipe from which:

24" Fir bears S.69°W. 29.0 ft. dist. mkd. $\frac{1}{4}$ S 7 B. T.

30" Fir bears N.85°W. 15.3 ft. dist. mkd. $\frac{1}{4}$ S 7 B. T.

80" Cedar " N.63°W. 25.0 ft. dist. mkd. $\frac{1}{4}$ S 7 B. T.

20" Fir bears N.32°W. 15.3 ft. dist. mkd. $\frac{1}{4}$ S 7 B. T.

Corner lies on Top of Side Ridge.

72

Section Corner to Sections 8, 9, 16 and 17, as determined by O.B.T's:

20" Hemlock bears S.20°E. 16.5 ft. dist. O.B.T., fd. scribe.

At Corner Point Set Truck Axle, flange up, from which:

9" Hemlock bears N.56°W. 42.0 ft. dist. mkd. S 8 T31S R4W B.T.

10" Hemlock bears N.16°E. 28.9 ft. dist. mkd. S 9 R4W B.T.

73

Robert M. Thompson
Surveyed for Sunny Valley Lumber Co.
July 12, 1959
Maps. File No. M 15 - 24

John H. Markham, Jr.
For Stomar Lumber Co.
Witnesses: R. G. Boyd &
O. A. Keatley - J. L. Markham
August 18, 1959
C. S. File No. 42/391