

Douglas County Surveyor's Record of  
Government Corners Renewed

T 31 T. S. R 4 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

164

Karen Cheney  
Gary Langlitz  
Doug. Co. Surveyors Office  
Oct. 7, 1976  
C.S. 59/24

Section corner Secs. 18, 17, 19, 20.

Found - An orig. 15" now 34" Fir, bears N.63°E., 24.1 ft. Alive and well-  
with healed over double blaze.

An orig. 8" now 16" Hemlock, bears S.46°E., 9.6 ft. Alive and well  
with previously chopped blaze visible scribing "31S".

The SW and NW orig. hemlocks no longer here.

No sign of orig. 18"x10"x4" stone.

Set - A 1"x30" I.P. with brass cap mkd.

Douglas Co. Surveyor

T 31	S	R 4	W
S 18	S 17		
S 19	S 20		

We set said brass cap from orig. bearings and distances from aforesaid  
orig. fd. trees.

New BT's - A 26" D.Fir, bears N.48°W., 64.2 ft. Doubled blazed and scribed  
"T31S R4W S18 CS BT"

A 7" Yewwood, bears N.23°E., 20.3 ft. doubled blazed and scribed  
"S17 T31S R4W CS BT"

10/7/76

165

Section Corner for Secs. 12 and 13; and Secs. 7 & 18 of T.31-3.

Found - A Fir stump, 46" now 38" (barked) bears N.26 1/2°E., 47.5 ft. with  
well healed blaze. (O.B.T.)

28" now 30" Fir stump bears S.8°E., 85.6 ft. (Rec. 89.8 ft. possible  
O.B.T.) See Ren. #79.

I reset corner from references set April 19, 1974 by G. Langlitz & attached  
to field notes and filed in C.S. 59/40. References intersect within 0.07 ft.

Set - A 5/8" x 30" Iron rod with 1 1/2" alum. cap set 9" below ground,  
marked: "Douglas Co.

R	T 31	S	R
4	12	7	3
W	13	18	W

Surveyor

Set - A 3/4" x 30" bent iron pipe 21" in ground at edge of alum. cap, in a  
24" mound of stone to top of I.P.

New BT's- A 30" Incense cedar (used to reference corner in 1974) bears  
N.73 3/4°W., 200.2 ft. double blazed and scribed "T31S R4W S12  
C.S. BT".

A 12" D. Fir bears N.87°E., 92.4 ft. double blazed and scribed  
T31S R3W S7 CS BT"

A 5/8" x 30" I.R. with 1 1/2" alum. cap set 9" above ground mkd.  
"Douglas Co. B.O. Surveyor" bears N.35 1/4°W., 108.27 ft. (used  
to reference corner in 1974).

Note: Corner lies at end of road #31-4-13 in landing of a clearcut unit.

10/27/77

166

Section Corner for Secs. 13 and 24; and Secs. 18 & 19 of T.31-3

Found - 32" Fir, N.46°W., 15.3 ft. (Orig.)

14" Fir, N.62°E., 22.0 ft. Ren. #59

14" Fir, N.24°E., 3.6 ft. (Orig.)

25" Fir, S.58 1/2°E., 43.6 ft. (Orig.)

Set - 5/8" x 40" I.R. and Alum. cap.

New BT's- 14" Fir, S.42°W., 58.3 ft.

25" Fir, S. 74°E., 39.7 ft.

12/17/80

167

1/4 Corner for Sections 18 and 19.

Not Found - Original corner tree monument not found.

1/2" x 40" I.R. from Ren. #85 not found.

Found - A 1"x36" I.P. with brass cap stamped "County Surveyor" Office  
T31S R4W 1/4 S18 S19 1966". Ren. #122. Cap has been removed  
from corner position and placed at a position safe from road  
construction. As road construction has been completed:

We Set - a temporary marker at position of 1/4 corner by using references  
as noted in 1978 corner reference notes.(removed from C.S. 59/30  
and attached to these field notes)

Found - Orig. 14" Fir, N.34°W., 11.0 ft. is down, has partially healed  
double blaze.

Orig. SW BT NOT found.

A Cedar 8" now 14" with partially healed double blaze bears N.68°E.,  
22.0 ft. (bearing OK to face) Base of tree bears N.72 1/2°E.,  
22.0 ft. No other trees found from this renewal. Ren. #85.

CONT. NEXT PAGE - - -

R. B. Kimberling  
M. W. Cline  
Doug. Co. Surveyors  
Office  
Oct. 27, 1977  
C.S. 59/40

Howard Johnstone  
For: Roseburg  
Lumber Co.  
Dec. 17, 1980  
M 86 - 42

L.E. Monrean,  
Deputy, Doug. Co.  
Surveyors Office  
Witness: T. Plouff  
March 30, 1981  
C.S. 61/19