

County Surveyor's Record, Douglas County, Oregon

GOV'T. CORNERS RENEWED

T 31 S, R 5 W, WM.

Geo. J. Wendroth
 Dep. Co. Surv.
 March 1946
 N. E. Richardson
 Surv.
 Witness
 11-17-49
 N. W. Richardson
 Godfrey
 Witness
 14-22, 1930
 BB Irving - Surveyor
 Witnesses - R.L. Irving
 N.E. Richardson
 Godfrey
 14-22, 1930
 A. Boyer - Surv.
 Smick, Elliott
 & Church
 Oct. 14, 1944
 T. R. Eslinger
 Surveyor
 Nov., 1950
 CS 40/280
 Sept. 23, 1938
 CS 5/16/45

CHAINS

COR. 31-32-5-6-(N COR. 5&6)
 Set from Old B.T. stump. Set $\frac{3}{4}$ " iron pipe. 13 1
 Mark 12" Fir $\text{W } 27^{\circ}55'$ W 15.4 ft.
 12" Fir S $31^{\circ}40'$ E 21.3 ft.
 30" Fir N $32^{\circ}30'$ W 98.0 ft.
 7" Fir N $4^{\circ}20'$ E 43.8 ft.

TOWNSHIP COR.
 NW COR. SEC. 6 2
 Set by running West, East & North
 Set $\frac{1}{2}$ " iron pipe. 52
 Mark 26" Fir N $81^{\circ}28'$ E 16.0 ft.
 6" Cedar S $5^{\circ}35'$ E 41.6 ft.
 18" Fir N $26^{\circ}53'$ W 26.6 ft.
 26" Fir S $80^{\circ}00'$ W 44.5 ft.

COR. 1-2-11-12 SEE ALSO #6 3
 Set from O. B. T. which is a 30" Fir bearing S 40° W 35.6 ft.
 New reference points are
 18" Fir bearing S $16\frac{1}{2}^{\circ}$ W 177.60 ft.
 Tel. Pole #1710 bearing S $49\frac{1}{4}^{\circ}$ E 212.7 ft. 105

N.W. CORNER, SEC. 3 SEE ALSO #32 4
 Set a sandstone 4" x 6" x 30". Location identified from O.B.T.
 Scribe marks visible. S 38° W 20 lks. & O.B.T. N 83° W 18 lks.
 marks burned off. Check field notes. Trees formally stood
 SE and NE checking notes.
 16" Fir S $25\frac{1}{2}^{\circ}$ W 34.0 ft. S 4 T 31 S R 5 W CC CS BT. on bark
 16" Fir S 89° E 27.2 ft. S 3 T 31 S R 5 W CC CS BT. on bark

SW. CORNER SEC. 3 5
 24" Fir S 70° W 37.5 ft. S 9 T 31 S R 5 W CS BT.
 18" Fir N 31° W 39.0 ft. S 4 T 31 S R 5 W CS BT. 18
 12" Fir N 10° E 66.5 ft. S 3 T 31 S R 5 W CS BT.
 Original corner as described original notes.

SEC. COR. 1 - 2 - 11 - 12 SEE ALSO #3 6
 Set from OBT 30" Fir S 40° W 54 lks. (W side HWY)
 Set $\frac{3}{4}$ " iron bolt on E side paving, - new trees 105
 16" Fir S 24° E 98.3 ft.
 5" Live Oak N 63° E 66.7 ft. (on slope)
 12" Fir N 5° E 63.7 ft. (on slope)

NW COR. SEC. 4 7
 Located from original Laurel to NW (N 23 W 63 lks.) - SET BY A. FORD
 Set 4 x 4 post Fir CORNER NO. 42
 New Trees are
 8" Fir, N 63° E 24 ft.
 10" Fir S 35° W 11.5 ft.
 10" Fir S 83° E 14 ft. 7

SEC. COR. 20 - 21 - 28 - 29 34 8
 All B.T.'s found except Laurel N 25° E, 29 lks. (down and rotted.)
 Set $\frac{1}{2}$ " pipe flush with ground
 1 $\frac{1}{2}$ " x 40" Iron pin driven into ground with 10" exposed.
 Pin and pipe are side by side. SEE CS 40/280 FOR ADDL BT INFO. NOT INCLUDED ON THIS REPORT - dated

CORN. 29 - 32 9
 South B.T. fallen for line clearing.
 1" iron pin driven flush with the ground at the location of the
 cedar post.
 1 $\frac{1}{2}$ " x 45" iron pin driven into ground with 9" exposed.
 Pins are side by side. (old Cedar Post remains.) 77