

Douglas County Surveyor's Record of  
Government Corners Renewed

31 T. S. 5 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

Richard L. Templin, Jr.  
Sept. 3, 1957  
C. S. File No. 42/303

Section Corner common to Sections 9, 10, 15, & 16. 16  
Found - 38 inch Fir N.15°E., 62 lks., with faint axe marks on bark which was burned. No scribing visible. Knife scribe this tree in bark on root collar "BT" and set aluminum poster tag 4 x 5 5/8 inches ~~43~~  
southwest side of tree five feet above ground.  
Found - 6 inch dead Madrone S.70°E., 7 lks with partially healed face and portion of original scribed face with scribing.  
Rotted stub of 12 inch Chinquapin, N.35°W., 22 lks projecting 10 inches above ground.  
Madrone in S.W. quadrant not found.

1/4 Section Corner Common to Sections 9 and 16. 21 17  
Found - 6 inch Fir corner tree askew. Blaze healed & not opened.  
8 inch Fir, N. 22 lks., blaze healed and not opened.  
12 inch Fir S.4°W., 18 lks., blaze healed and not opened. Set aluminum poster tag on this tree 4 " X 5 5/8".

John H. Markham Jr.  
For Canyon Logging  
Witness: D.E. Brown  
Sept. 13, 1957  
C. S. File No. 42/312

Section Corner Common to Sections 3, 4, 9, & 10. 18  
as determined by Old BTs.  
At corner point found 3' pile of stones with scribed 3"x 3" post in center. I set a 1/2" x 20" iron rod at corner. 71  
Found: 2 bark scribed BTs which I tagged. Rev. #5  
Corner lies on top of high side ridge, on West edge of large burn. Airplane beacon bears N. 8°12'W. 1245.0' on 20°00' Var.

Geo. J. Wenderoth, Deputy  
May 23, 1958  
C. S. File No. 49/92

1/4 Section Corner between Sections 4 & 5. 19  
Found this corner & drove 1" Iron Pipe for Corner.  
26" Fir N.26°W. 7.9 ft., good.  
50" Cedar S.65°W. 36.1 ft., good.

1/4 Section Corner between Sections 4 & 9. 19-A  
Found this corner & drove 1" Iron Pipe for Corner.  
40" Fir N.65°W. 13.9 ft., good.  
43" Fir N.39°E. 19.8 ft., good.  
Note: See file for additional information.

FOUND CORNERS  
MAY, 1966  
J.M. POWELL.

Richard L. Templin, Jr.  
Sept. 1958  
C.S. File No. 42/389

S.E. Cor 36  
Township Corner Common to Twps. T31/R5; T31/R4; T32/R5; T32/R4. 20  
Found - 2" Iron Pipe (unmarked)  
24" Fir S.62 3/4°W. 39.5 ft., blaze healed.  
50" Fir Stump S.74 1/2°E. 25.5 ft., scribing visible.  
40" Fir Stump N.65°E. 20.0 ft., blaze healed.  
16" Fir Stump N.16°W. 54.0 ft., blaze healed.  
10" Fir N.79 3/4°E. 9.8 ft., scribing visible.  
Scribed: 6" Cedar N.27°W. 16.6 ft. mkd. S36 RE3024 BT.

Victor S. King  
Wit. Chester C. Jones  
For Bate Lumber Co.  
Feb. 5, 1959  
C. S. File No. 42/425

1/4 Corner to Sections 9 and 16. 90 21  
Found - 16" W. Fir S. 4°W. 18 lks. (since destroyed by logging). See Also Rev. #17  
6" W. Fir tree monument for the corner. Blown down but still green. I chopped into the north face & disclosed the scribing - 1/4 S -. I chopped off the top leaving about a 4' Stump as a memorial. The negative of the scribing is retained in our office.  
Set - 1 1/2" Iron Pipe 48" long 36" in the ground. 86  
Due to the fact that there are no trees to the South, I set 2 new Bearing Trees in Section 9.  
12" W. Fir N.64°W. 41.3 ft. scribed 1/4 S 9 BT  
12" Yew N.74°E. 38.5 ft. scribed 1/4 S 9 BT

1/4 Corner to Sections 32 & 33. 22  
Found - 8" Fir S.75°W. 18 lks. with scribing visible.  
Set - 1 1/2" Iron Pipe 3' long in a mound of stones from which I set the following new Bearing Trees: 78  
12" Fir S.38°E. 3.6 ft. scribed 1/4 S 33 BT  
24" Fir N.75°W. 16.0 ft. scribed 1/4 S 32 BT.