

Douglas County Surveyor's Record of
Government Corners Renewed

31

T. S.

5

R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21001

SECTION CORNER $\begin{array}{c|c} 20 & 21 \\ \hline 29 & 28 \end{array}$ T31S, R5W, WM

34

FOUND: 1 1/4" Iron Rod *REN. #8*
1 Original BT with scribing 14" Laurel
S.60°E. 18.5 ft.

SET:: The following new bearing trees.
12" Yew N.44°E. 43.7 ft. scribed S21, T31S, R5W,
T31S, R5W, BT.
16" Yew S.41 1/2°W. 62.7 ft. scribed S29,
T31S, R5W, BT.
Rescribed original BT S 28, T31S, R5W, BT.

MAY, 1966
CORNER FOUND O.K.
J. POWELL
L.L.

1/4 Corner 9/10 T31S, R5W, WM

35

FOUND: 2 Madrona BT set by Evans RE #2741 *REN. #11*
& 4" Fir Post, both since destroyed
by logging.

SET: 1-1/8" Iron Rod 36" long 14" in ground
in a small mound of stones.
Set the following new bearing trees:
8" Fir S.82°W. 40.3 ft. scribed 1/4 S 9,
T31S, R5W, BT.
48" Cedar S.53°E. 78.0 ft. scribed ,
1/4 S10, T31S, R5W, BT.

RE-RENEWED, SEE CORNER NO. 88

Victor S. King, Engineer
For Bate Lumber Company
October 30, 1959
C. S. File No. 51/56

SECTION CORNER $\begin{array}{c|c} 8 & 9 \\ \hline 17 & 16 \end{array}$ T31S, R5W, WM

36

FOUND: Original BT, 6" Dogwood S.21°E. 13 lks.
with the overgrowth showing scribed BT.
The overgrowth was so fragile that it would
deteriorate almost immediately in the
weather, so it is retained in our office
for evidence.

SET: 1" Pipe 36" long 24" in ground in a mound
of stones.

Set the following new BT's:
48" Fir N.29°W. 39.5 ft. bark scribed
S 8, T31S, R5W, BT.
12" W.Fir S.41 1/2°W. 10.7 ft. scribed S17,
T31S, R5W, BT.
18" Fir S. 64 1/2°E. 86.5 ft. scribed S16,
T31S, R5W, BT.
24" W.Fir N.69 1/2°E. 8.7 ft. scribed S 9, T31S
T31S, R5W, BT.

SECTION CORNER $\begin{array}{c|c} 17 & 16 \\ \hline 20 & 21 \end{array}$ T31S, R5W, WM

37

FOUND: This corner falls in an old burn. Corner
was set on the intersection of the original
Blazes, then when the corner was occupied I
turned off the correct bearings and distances
to 4 old Fir Stumps that fit the bearings &
distances to the 4 original bearing trees
perfectly. No scribing remained on any of
the old bearing trees.

SET: 3" Fir Post from which I set the following
new bearing trees:
6" Fir N.56°E. 10.4 ft. scribed S16,
T31S, R5W, BT.
3" Fir N.55°W. 18.3 ft. scribed S17,
T31S, R5W, BT.
22" Fir S.46°W. 20.8 ft. scribed S20,
T31S, R5W, BT.
6" Fir S.83°E. 39.6 ft. scribed S21,
T31S, R5W, BT.

RE-RENEWED, SEE CORNER NO. 79