

Douglas County Surveyor's Record of
Government Corners Renewed

T. 31 S. T. S. R. 5 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21861

104

John M. Powell
& Crew
7/28/67
C.S. File
No. 53/52

Section Corner to Secs. 33 & 34, T31-5W. & Sec. 3 & 4, T32-5W.
Found - U.S. Land Office Brass Cap, properly marked in 1955.
20" Fir windfall, N. $13\frac{1}{2}^{\circ}$ E. 38.3 ft., shows good scar.
30", now 33" Fir, S. $68\frac{1}{2}^{\circ}$ E. 48.8 ft., shows good scar.
33", now 35" Fir, N. 66° W. 48.2 ft., shows good scar.
No trace of S.W. BT., lies in skid trail.
New BT's: 21" D. Fir N. 1° E. 82.4 ft. mkd. T31S R5W S34 CS BT.
30" D. Fir S. 77° W. 46.6 ft. mkd. T32S R5W S4 CS BT.

MICROFILM TO HERE 10/67

105

James W. Byron
John M. Powell
Jan. 21, 1969
C. S. File
No. 54/76

Section Corner to Sections 1 - 2 - 11 - 12. Witness Corner #117
Set - Brass Cap for Wit. Cor. Mkd: T. 31 S. R. 5 W. County Surveyor's
W. C. Office
332' N. to S11 S 12 1969
New BT's: 8" D. Fir N. 48° W. 16.9 ft. mkd: W.C. T31S R5W S11 CS BT.
10" D. Fir N. 45° E. 30.4 ft. mkd: W.C. T31S R5W S12 CS BT.
Found - 5/8" R/W Pin (Sta. 188+64.57) S. 65° E. 26.35 ft.
Note - This corner lies 1.0 ft. south of R/W fence on south side
of Interstate 5. (See Ren. #6.)

1/21/69

106

John M. Powell
& Crew
C.S. File
No.
54/25

Section Corner to Sections 25 - 26 - 35 - 36.
Found - G.L.O. Brass Cap properly set & marked in 1955.
24" D. Fir, now dead, N. 47° E. 4.0 ft., pitched over, scribe visible.
32" D. Fir, now 32", S. 51° E. 36.3 ft., pitched over, scribe visible.
32" D. Fir, now dead, S. $62\frac{1}{2}^{\circ}$ W. 73.6 ft. pitched over, scribe visible.
23", now 29" D. Fir, N. $43\frac{1}{2}^{\circ}$ W. 17.8 ft., pitched over, scribe visible.
New BT's: 10" Hemlock N. 73° E. 43.6 ft. mkd: T31S R5W S25 CS BT.
12" Maple S. 55° W. 80.6 ft. mkd: T31S R5W S35 CS BT.

9/11/69

107

Gary L. Langlitz, County Surveyors Office
P. Earle
C.S. 56/43
Jan. 30, 1974
MARCH 71

Sec. Cor. Secs. 32 & 33; & Secs. 5 & 4 of T32-5.
Found - HLM Cadastral 1962 Brass cap, lying on ground near uprooted
tree. I remove Cadastral marker and
Set - Brass cap cemented in drillhole at the base of a small rock
outcrop at record bearing and distances from an original 12"
now 24" D. Fir, bearing S. 39° W., 64.7 ft. previously opened
with scribing "2S 5W" visible.
Brass cap mkd. Douglas County Surveyors T 31 S R 5 W
Office S 32 | S 33
1974 S 5 | S 4
T 32 S R 5 W

from which:

- 14" D. Fir, bears N. 11° E., 41.9 ft. (Rec. N. $14\frac{1}{2}^{\circ}$ E., 44.9 ft.)
scribing visible in partially healed blaze.
- 16" D. Fir, down, bears S. 30° E., 56.8 ft. (rec. S. 38° E., 52.8 ft.)
scribing "T32S R5W S4 BT" visible.
- 10" D. Fir, bears S. 66° W., 45.3 ft. (rec. S. $65\frac{1}{2}^{\circ}$ W., 40.9 ft.) with
healed blaze.
- 14" D. Fir, down, bears N. 50° W., 22.0 ft. (rec. N. 41° W., 19.1 ft.)
blze & scribifng visible.

New BT & bearing object:

- An "X" chiseled in a vertical rock face bears S. $24\frac{1}{2}^{\circ}$ E., 58.6 ft.
- A 22" D. Fir, bears N. 74° W., 45.4 ft. scribed "T31S R5W S32 CS BT".

Note: The NW O.B.T. called for in resurvey field notes, now down,
bears approx N. 38° W., 8 ft. (rec. N. 31° W., 8.6 ft.)

1/30/74