

Douglas County Surveyor's Record of  
Government Corners Renewed

T 31 T. S. R 5 R.W.W.M.

KOBE-CHAPMAN CO., EUGENE, ORE. 21981

cont. - - - -

(Witn. Cor. Secs. 1, 2, 11, 12)

New Accessory:

Doug. Co. Surveyors  
Office  
R. Smith-S. Flause  
Aug. 21, 1985  
C.S. 62/29

A Douglas Co. Brass stem in bridge deck (PTS-18) bears  
N.46°41'06"W., 622.38 ft. (grid)  
Note: Corner is approx. 250 ft. south of the south bound lanes of  
I-5, and 1 ft. south of the south R/W fence of I-5 on a  
steep north slope.

RE-RENEWED SEE CORNER NO. #120 117

8/21/85

Section corner for Secs. 23, 24, 25 and 26.

118

Found - A 1973 BLM disk set flush in concrete of old abandoned  
Hwy 99 road surface, cap properly marked.  
A 17" now 18" dia. D. Fir with a fully healed single blaze  
bears N.17°E., 63.8 ft. (Rec. N.15°E., 62.7 ft.)  
A 10" now 16" dia. D. fir with a fully healed single blaze  
bears S.55°E., 66.6 ft. (Rec. S.55°E., 67.3 ft. slope  
measurement.)  
A 13" now 18" dia. D. fir with a fully healed single blaze bears  
S.22°W., 62.4 ft. (agrees with rec.)  
A 19" now 22" dia. D. fir with a fully healed single blaze  
bears N.60°W., 80.0 ft. (Rec. N.60°W., 81.5 ft. face  
measurement.)

No new monument or accessories set.

Corner is approx. 400 ft. east of I-5 in old Hwy 99 concrete road surface.

10/28/85

Center 1/4 Corner for Section 11

119

Set - 2" x 30" Alum. pipe with alum. cap mkd. L.S. 536.  
New BTs-8" D. fir bears N.12°W., 30.5 ft. scribed "C 1/4 S11 BT".  
18" D. fir bears N.89°W., 39.5 ft. scribed "C 1/4 S11 BT".

12/87

W.C.

Section corner for Secs. 1, 2, 11 and 12.

120

CORNER REPORT ONLY

Position of section corner as determined by Byron (Ren. #105) and BLM in  
1973, were not looked for. Section corner falls on or near north bound  
lanes of I-5.

Found - A 1969 DCSO brass cap on an I.P. mkd. as in Ren. #117. See Ren-  
ewal for wit. corner bearing tree and bearing object information.  
(Bearings & distances taken from a calculated point of section corner.

True Bearings -

Found - 12" now 15" dia. I. Cedar with a partially healed single blaze  
scribing visible "SR5WS1 BT" bears N.17½°W., 243.5 ft. (Rec.  
N.19°W., 244.8 ft.) Per 1973 BLM Dependent Resurvey.  
21" now 24" dia. I. Cedar with a partially healed single blaze  
scribing visible "31S R5W S2 BT" bears N.41½°E., 199.9 ft.  
(Rec. N.40°E., 197.3 ft.) Per BLM 1973 D. Resurvey.

Control point PTS-18 was backsighted from wit. corner. BTs from 1973 BLM  
Resurvey and a 1" O.D. iron pipe (N 1/64 cor. betw. 11 and 12) from  
M22-10 are tied. A check of the grid bearing between N 1/64 cor. and  
wit. cor. agrees well with bearing on map in C.S File #54/76. A calc.  
corner position was determined by projecting a line beyond wit. cor. on  
same bearing found between wit. cor. and N 1/64 cor. (N.0°58'36"E.) a  
distance of 332.09 ft. (C.S. 54/76)

A section corner position of true north, 332.0 ft. from wit. cor. and an  
intersection of true bearings from BLM BTs showed the most agreement with  
the 1973 BLM position of section corner. This position of section corner  
seems to be in disagreement with position determined from map in C.S. 54/76.

9/26/88

1/4 Corner between Sections 16 & 17

Found - County Surveyor's Office brass cap dated 1966.

121

34" D. fir now 42" bears S.78°E., 34 ft.

Orig 40" D. fir now a stump.

Set - 5/8" x 54" iron rod and aluminum cap reference monument bears  
S.45°W., 10.0 ft.

Corner lies 250 ft. above Road 31-5-17.2, in a recent clearcut  
See Renewal # 84.

10/2/91

Douglas County  
Surveyors Office  
Randall Smith  
Stephen Flause  
Deputies  
Oct. 28, 1985  
C.S. 62/29

Glenn Baughman  
For: Howard & Ruth  
Moore  
December 1987  
RM 3-67 C.S. 63/58

Douglas County  
Surveyors office  
Randall Smith  
Stephen J. Flause  
Sept. 26, 1988  
C.S. 62/55

Mark Smalley L.S. 2354  
For: Roseburg Resources  
Sept. 1991  
C.S. 63/129