

Douglas County Surveyor's Record of  
Government Corners Renewed

31 T. S. 5 R. W. W. M.

ROKE-CHAPMAN CO., EUGENE, ORE. 21001

Mark Smalley LS 2354  
Roseburg Resources  
Sept. 1991  
C.S. 63/129

1/4 Corner between sections 17 and 18  
Found - Cadastral Survey brass cap dated 1966, leaning north  
26" fir S.82°W, 28.0 ft  
20" fir N.80°E, 39 links, is now a high stump  
New BT- 44" fir, N.82°E., 29.4 ft. scribed "1/4 S17 BT"  
Corner lies below the 31-6-12.3 road on the edge of a recent clearcut.  
9/91

122

Douglas County  
Surveyors Office  
Randall Smith  
Stephen Flause  
January 7, 1992  
C.S. File 64/23

Township Corner - SW Corner Section 31  
Found - 1966 Oreg. State Board of Forestry 3" brass cap on a 1½" O.D.  
Iron pipe protruding 7" above ground. Ren. #100  
1" O.D. Iron pipe protrudes 5" above ground. Ren. #56  
1" I.P. bears West, 13.3 ft. from OSBF BC/IP (agrees w/Ren. #100)  
55" now 58" dia.D.Fir with a fully healed single blaze on the  
NW trunk and bark scribed "LS 359" on North trunk, bears  
S.15°W., 13.8 ft. (Rec. S.15°W 11.5 ft., dist. to bark  
scribing)  
4" now 9" dia. 1½ ft. high Hemlock stump with a fully healed  
blaze, bears S.58°E., 28.3 ft. (agrees w/rec) Ren. No. 100  
6" now 12" dia. 1½ ft. high D.Fir stump with a fully healed  
single blaze, bears N.86°W., 54.5 ft. (agrees w/rec.  
New BTs - (Go to corner position as determined by Oreg. State Board of  
Forestry)  
8" dia. Hemlock double blazed and scribed "T31S R6W S36 CS BT"  
bears N.43°W., 12.1 ft.  
7" dia. Hemlock double blazed and scribed "T31S R5W S31 CS BT"  
bears N.75°E., 16.6 ft.  
Corner lies on a steep north facing slope.  
(See C.S. File 49/92 for correspondance on the establishment of the  
corner position.)

123

1/7/92

Bruce Shaner  
L.S. #430  
Jack Wright and  
Clem Berlier  
Juen 15, 1992  
C.S. 63/138

Section Corner for 22, 23, 26 and 27  
Found - 1955 BLM brass cap on 2" galv I P (Set steel fence post  
alongside.)  
35" D.Fir BT, face badly burned, bears S.40°E., (Rec. S.45°E.)  
19.8 ft.  
32" D.Fir BT, healed blaze bears S 12°E., (Rec. S.14°E.) 23.1 ft.  
21" D.Fir BT stump, badly burned, bears S.36°W.(Rec. S.31°W.)  
28.4 ft.  
36" D.Fir BT, healed blaze, bears N.68°W., 23.1 ft.  
19" D.Fir BT bearing S.25°W., 30.4 ft., now gone. Ren. No. 74  
18" Madrone BT, face overgrown, bears N.8°W., 21.8 ft. Ren. No. 74  
New BT - I marked a 12" D.Fir BT, "T31S R5W S27 BT", S.76°W., 41.8 ft.  
from corner.  
(No trees within reasonable distance in NE quadrant (Sec. 23) as is recent  
clearcut) Corner is about 650 ft. south of Mainline Access Road.

124

6/15/92

Bruce Shaner  
L.S. #430  
For: Richard  
McKenzie  
June 1992  
M 112 - 49

1/4 Corner for Secs. 15 and 22  
No evidence of orig. corner, so by proportional measurement I:  
Set - 3" brass cap on a 2" x 30" galv. Iron pipe marked "T31S R5W  
W.M., 1/4 S15|S22 RLS 430 1992"  
From which:  
10" D.Fir BT, I scribed "¼ S15 BT" bears N.30°E., 5.8 ft.  
12" D.Fir BT, I scribe "¼ S15 BT" bears N.6°W., 12.5 ft.  
6" D.Fir BT., I scribed "¼ S22 BT" bears South 24.4 ft.  
12" D.Fir BT, I scribed "¼ S22 BT" bears S.44°W., 21.0 ft.

125

6/92

Bruce Shaner  
L.S. #430  
For: Richard  
McKenzie  
April 1993  
M 116 - 64  
CS 63/149

1/4 Corner for Sections 21 & 28.  
Set - 2½" Brass cap on 1" x 30" Galv. iron pipe marked "SHANER ENGR.  
1/4 S 21, 28 RLS 430 1993".  
New Accessories -  
8" Douglas Fir BT, N 2°W 4.7', Scribed "1/4 S BT".  
10" Douglas Fir BT, N 43°E, 18.2', Scribed "1/4 S BT".  
6" Douglas Fir BT, S 15°E, 8.8', scribed "1/4 S BT".  
8" Douglas Fir BT, S 43°W, 13.4', scribed "1/4 S BT".  
Note - Set steel fence post on road at 600 feet West of 1/4 S.  
4/93

126