

County Surveyor's Record, Douglas County, Oregon

Gov't corners renewed

T 31 S, R 6 W., W. M.

BEST COAST PRINTING & BINDING CO. PORTLAND 13735

Ben B. Irving - County Surveyor

CHAINS

Ray G. Irving)
John Fee)
Chairmen

March 16, 1954
File 45/253

Section corner to secs. 32, 33, T 30 S, R 6 W, and 4, 5, T 31 S, R 6 W.
Location identified from O. B. Trees- 9
8 inch (now 30") Fir, S.60°W., 32 lks.
6 inch (now 20") Maple, N.80°W., 11 lks.
Blaze on Fir B. Tree, has been chopped ou and scribed letters BT and
part of upper scribe visible - Maple BT in place but not chopped
out.
Set 1 inch iron pipe with brass cap stamped
County Surveyor's
T 30 S, R 6 W
$$\begin{array}{c} 32/33 \\ \times \\ 5/4 \end{array}$$

T 31 S, 1954
Office.
12 inch Fir, S.71°W., 21.2 ft. scribed T 31 S, R 6 W., S 5 CS BT.
20 inch Maple - O B T., N.80°W., 7.3 feet, T 30 S, R 6 W.
4 inch Yew, S.19°E., 26.5 feet, T 31 S, R 6 W., S 4 CS BT.
Oak, N.36½°E., 80.6 feet, T 30 S, R 6 W., S 33, CS BT.

Section corner to secs. 20, 21, 28 and 29. 10
Three original B. T. s present from which corner was reset using
recorded distances and bearings.
Corner is a ½ inch iron pipe from which bears: 102
Fir 8 inches, bears N.40°E., 11.8 ft. scribed S21 T31SR6WMM.
(New B. T.)
Pine 36 inches, bears N.40°W., 65.3 feet rescribed S 20 T31S
R6W MM. (Original B. T.)
Fir 48 inches, bears S.80°E., 55.4 feet rescribed S 28 T31S
R6W MM. (Original B. T.)
Incense Cedar 38 inches bears S.74°W., 34.3 feet. S 29 T31S
R6W MM visible in bark. (Original B. T.)

¼ sec. corner between sections 28 and 29. 11
B. T. to Section 28 present. Scars very plain.
Reset corner with ½ inch pipe using recorded distance and bearing.
B. T.s are as follows: 103
Fir, 18 inches, East 5.3 ft. - Original B. T.
Incense Cedar 12 inches, S.60°30'W., 8.8 ft., scribed ¼ S 29
T31S R6W MM. - This is new B. T.

----- 28, 29, 32, 33 -----

Section corner to sections ~~27, 28, 33 and 34~~ (SW Cor. Sec. 28) 12
Found original corner post standing and in place. See Ren. #184
Replaced corner with a ½ inch iron pipe from which bears #107
Fir, 38 inches, N.15°E., 14.5 feet, scribed S 28 in bark.
(Original B. T.)
Fir, 32 inches, N65°W., 13.2 feet, scribed S 29 in bark. #18
(Original B. T.)
Fir, 10 inches, S.74°E., 16.5 feet, scribed S 33, T31S, R6W.,
W. M. B. T. - (This is new B. T.)
Fir, 10 inches, S.28°W., 23.2 ft., scribed S 32, T31S, R6W.,
W. M. - (This is new B. T.)

¼ corner between sections 4 and 5. 13
Found on laurel B. T. Scribe marks very plain. Tree has fallen
over. Reset corner from stump hole using recorded dist. and bearing.
Corner is a ½ inch iron pipe.
Marked 2 new B. T.s which are as follows :
Fir, 14 inches, N.33°W., 3.4 ft., scribed ¼ S 5 T31S R6W B. T.
Fir, 14 inches, S.48°10'W., 6.8 feet, scribed ¼ S 4 T31S,
R6W. B. T.

R. H. Gee
R. J. Henriksen
F. McCornack
December 29, 30, 1954.
C. S. File No. 41/338

RENEWED CORNER NO.