

Douglas County Surveyor's Record of  
Government Corners Renewed

31. T. S. 6 R. W. W. M.

MOKE-CHAPMAN CO., EUGENE, ORE. 21881

James W. Eyron, Deputy County Surveyor  
Milo Godfrey  
Clete Putnam  
June 1961  
C. S. File No. 52/25

Section Corner to Sections 25 - 26 - 35 - 36. 47  
Found - Orig. 24", now 36" R. Fir S. 65° E. 37.0 ft., shows old bark scribing "BT T31".  
Orig. 30", now 40" Fir N. 15° W. 8.6 ft., old face axed off, no scribing found. # 105  
Orig. 36", now 40" Fir S. 55° W. 52.8 ft., old face axed off, no scribing found.  
No trace of Original N.E. BT. found.  
This Corner renewed recently but not recorded. Original SW. and NW. BT's. rescribed. Also same person scribed a 7" Fir bears S. 31° E. 25.2 ft. and a 50" R. Fir bears N. 31° E. 46.7 ft.  
Set Brass Cap at Corner Mkd: County Surveyor's Office, 1961 

S26	S25
S35	S36

 T31S R6W  
New BT's: 6" R. Fir bears S. 23° W. 18.6 ft. scribed S35 CS BT.  
6" R. Fir bears N. 50° E. 79.7 ft. scribed S25 CS BT.

1/4 Section Corner to Sections 23 and 26. 48  
Found - 1" Drill Steel at corner and 36" now 40" Fir Snag west # 155  
No sign of old Original corner as placed new corner halfway between Section Corners both being found. Ren. # 16  
New BT's: 8" R. Fir bears S. 54° W. 49.7 ft. scribed 1/4 S26 CS BT.  
17" R. Fir bears N. 5° E. 48.6 ft. scribed 1/4 S23 CS BT.

1/4 Section Corner to Sections 27 and 26. 49  
Found - Orig. 42", now 46" Fir N. 86° W. 22.4 ft., shows good bark scribing "BT". Mar., 1984  
No trace of Orig. SE BT. found. F.d. OK. by Baughman M 96-32  
16" R. Fir bears S. 77° E. 12.4 ft., scribed by Kerr, 1961, shows good scribing "1/4 S26. We add CS BT. Ren. # 44  
Set Brass Cap at Corner Mkd: County Surveyor's Office, 1961  
1/4 S27/S26 T31S R6W  
New BT: 16" R. Fir bears S. 10° W. 25.5 ft. scribed 1/4 S27 CS BT.

Geo. J. Wenderoth  
Jan. 1962  
C.S. File # 49/92

1/4 Corner between Sections 25 and 36. 50  
No sign of old Original corner as placed new corner halfway between Section Corners both being found. # 152  
Placed 1" Iron Pipe for corner.  
Scribed: 10" Yew S. 77° E. 37.5 ft.  
10" Maple S. 78° W. 17.5 ft.

Howard Johnstone for Roseburg Lumber Co.  
C.S. File No. 51/163

1/4 Corner between Section 30, T31-6W. & Sec. 25, T31-7W. 51  
Found - Original Bearing Trees in good condition. # 136  
Set - 1" by 30" Iron Pipe  
May 28, 1962

James W. Byron, Deputy  
John Powell & Wm. Stoffel & M. Stone  
August 31, 1962  
C. S. File No. 52/25

Section Corner to Sections 13 - 14 - 23 - 24. 52  
Found - Orig. 8", now 10" Laurel S. 20° W. 13.2 ft., shows good scribing.  
Orig. 36", now 46" Fir S. 71° E. 18.5 ft., no scribing. # 165  
Orig. 40", now 50" R. Fir N. 32° E. 29.7 ft., shows scar.  
Do not find N. W. Bearing Tree.  
Set - Brass Cap at Corner Mkd: County Surveyor's Office, 1962 

S14	S13
S23	S24

 T31S R6W  
Note - Corner is 50 ft. South of Logging Road.  
New BT's: Rescribe O.B.T., now 46" R. Fir S. 73° E. 21.0 ft. S24 T31S R6W CS BT.  
8" R. Fir bears S. 72° W. 33.2 ft. scribed S23 T31S R6W CS BT.  
No trees near to Northwest. Oct. 1966 - Cor. A.K. J.M.P.

1/4 Corner for Sections 15 and 14. 53  
Found - Orig. 5", now Dead, Laurel S. 58° W. 2.6 ft., shows scribing. S. E. Bearing Tree, down.  
Set - Brass Cap at Corner Mkd: County Surveyor's Office, 1962  
1/4 S15/S14 T31S R6W  
New BT's: 14" R. Fir bears S. 38° E. 15.6 ft. scribed 1/4 S14 CS BT.  
13" R. Fir bears S. 28° W. 7.6 ft. scribed 1/4 S15 CS BT.  
Note - Corner is 80 ft. West of Logging Road.