

Douglas County Surveyor's Record of  
Government Corners Renewed

T. 31 S. T. S. R. 6 W. R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21851

James W. Byron, Deputy  
Mike Darby & J. Halterman  
Jan. & Feb. 1964  
C. S. File No. 53/40

1/4 Corner to Sec. 4, T31-6W. & Sec. 33, T30-6W.  
Found - Brass Cap at Cor. & all BT's, as recorded, See REN. #20  
except N. W. BT. which is now dead.  
New BT: 6" R. Fir bears S. 78° E. 28.0 ft. scribed 1/4 S4 CS BT.

Nov. 21, 1963

60

1/4 Corner to Sec. 1, T31-6W. & Sec. 36, T30-6W.  
Found - 2" I. Pipe at Base of [redacted] Tree, see Ren. No. 1.  
Now, 14" Cedar S. 43° W. 25.7 ft., shows good scars.  
N. W. Bearing Tree, now stump.  
New BT: 12" R. Fir N. 28° W. 17.9 ft. scribed 1/4 S36 CS BT.

Jan. 7, 1964

61

Geo. Wenderoth  
For C. & D.  
Lumber Co.  
C. S. File  
No. 49/92

TOWNSHIP CORNER  
R6W 

T31S
S36   S31
S 1   S 6
T32S

 R5W

Set - 1" Iron Pipe from which:  
Scribe - 52" Fir S. 35° 35' E. 13.6 ft.  
12" Hemlock S. 46° 12' W. 32.2 ft.  
16" Yew N. 79° 40' W. 97.4 ft.

Reported Feb. 1964

62

1/4 Corner to Sections 24 and 25.  
Found - No evidence of Original Corner.  
Set - 5/8" x 36" Iron Rod from which a:  
36" D. Fir, I scribed "T31S R6W S25 1/4 S BT", bears S. 70° W. 66.5 ft.  
8" Hemlock, I scribed, "1/4 S S24 BT", bears N. 36° W. 65.1 ft.

93

63

Section Corner common to Sections 24, 25, T31-6W. & Secs. 19 & 30, T31-5W.  
Set - 5/8" x 36" Iron Rod, from which a:  
44" D. Fir Stump, Orig. BT. with scribes visible, bears N. 62° W. 46.9'  
42" D. Fir Stump, Orig. BT. with old rotten face, bears S. 68° E. 33.0'  
Scribed - 48" D. Fir, I scribed "T31S R6W S25 BT", bears S. 45° W., 58.6 ft.  
14" D. Fir, I scribed "T31S R5W S19 BT", bears N. 46° E., 56.5 ft.  
12" D. Fir, I scribed "T31S R5W S30 BT", bears S. 20° E. 37.3 ft.

85

64

1/4 Section Corner common to Sec. 25, T31-6W. & Sec. 30, T31-5W.  
Found - No evidence of Original Corner.  
Note - As the corner I wanted to set fell in a 6 ft. wide stream, I set  
no corner, but from the corner location point a:  
34" D. Fir Stump, I scribe T31S R5W 1/4 S S30 BT", bears S. 35° E., 11.5 ft.  
36" D. Fir Snag, I scribe, "T31S R6W S25 1/4 S BT", bears N. 82° W., 38.1'

86

65

George J.  
Wenderoth  
Reported by  
B. Shaner  
Feb. 1964  
M 27 - 36

Section Cor. common to Secs. 25 & 36, T31-6W & Secs. 30 & 31, T31-5W.  
Found - 2" Iron Pipe. This Corner found by Shaner; See M 27 - 36.  
Original BT. stump with scribes "S25" visible bears N. 38° W. 10.6 ft.  
New BT's: 42" D. Fir with scribes visible, N. 86° W., 26.3 ft.  
18" Yew BT., Original BT, scribes visible, bears N. 31° E. 42.2 ft.  
38" D. Fir BT. with scribes visible bears S. 22° W. 63.2 ft.

66

Milo Godfrey, Deputy  
Wm. Stoffel, Mike Stone  
Mike Darby  
June, 1964  
C. S. File No. 52/25

Section Corner to Sections 16, 17, 20 & 21.  
Found - 14" (now 17") Laurel N. 50° E 30.4 ft. Scribing visible  
"31-6-16"

10" (now 12") Laurel S. 51° E 42.2 ft. Badly burnt.

20" (now 29") Laurel S. 40° W. 68.0 ft. "BT" visible -  
badly burnt.

18" (now 27") Laurel N. 60° W 69.3 ft. Scribing visible  
"31S R6W S 17"

Set - Brass Cap mkd: "County Surveyor's Office 1964 T 31 SR 6 W

17 | 16  
20 | 21

New BTS: 5" fir S. 46° E 36.3 ft. Mkd: S 21 CS BT.  
5" fir S 10° W 15.0 ft. Mkd: S 20 CS BT.

FD. O.K. 6/3/80  
BRUCE A. SHANER LS#430 RM3-32

67