

Douglas County Surveyor's Record of
Government Corners Renewed

T 31 S T. S. R 6 W R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

134

1/4 Corner for Secs. 11 and 12.

Found - 3" x 3" Cedar post 24" above ground scribed: 1/4 S11 on west face,
1/4 S12 on east face. Post in excellent condition.
34" D.Fir bears S.55°W., 14.0 ft. initials JM chopped into bark.
Also bears metal GLO location tag initialed by Murdock &
Haines 9-24-46. No visible scars.
Rotted out fir root collar, bears S.58°E., 11.2 ft.

Gary Langlitz, G.S.
P. Earle
Jan. 11, 1974
C.S. 56/43

I do not renew.

1/11/74

JWAK's

135

Sec. Cor. for Secs. 19 and 30; Secs. 24 and 25 of T31-7.

Found - 1 1/4" I.P. firmly set at sec. cor. as determined by Johnston
1962. See M 18 - 66. Ren. #41
6" now 10" D. Fir bears S.88°W., 30.6 ft. (Rec. 32.9 ft.). Tree
has well healed blaze. (single)
14" now dead, tipped out D. Fir bears S.63°E., 35.0 ft. Tree has
open double blaze scribed "T31S 6W S30 BT".
30" now 31" D. Fir bears N. 10°E., 54.5 ft. (rec. 55.1 ft.)
Tree has partially healed single blaze.
7" now 9" S. Pine bears N.55°W., 23.3 ft. (rec. 23.9 ft.)
Tree has well healed double blaze.

Set - I place 1"x30" I.P. with brass cap attached at sec. cor. as de-
termined by Johnston, stamped "Douglas County Surveyor"

	T 31 S		
R	S24	S19	R
7	S25	S30	6
W			W

1977

New BT - A S. Pine 15" bears S.69°E., 53.3 ft. Tree double blazed and
scribed "T31S R6W S30 CS BT."

Note - All bearings and distances measured are to center of base of tree.

1/3/77

Larry E. Menzies, Douglas County Surveyors Office
K. Cheney
P. L. Earle
Jan. 3, 1977
C.S. 59/29

136

1/4 Corner for Sec. 30 and Sec. 25 of T.31-7.

Found - 3/4" x 24" I.P. at corner firmly set. Ren. #51
3" x 3" squared wooden post.
Orig. 14" now 24" Fir bears N.48°E., 4.0 ft. (Rec. N.47°E.)
Tree has bark scribing "1/4 S BT".
A 30" Cedar now 32" bears S.47°W., 15.2 ft. (rec. S.42°W.) Tree
has partially opened blaze, scribing visible "1/4".

Set - 1" x 30" I.P. with brass cap attached at 1/4 corner cap stamped:
"Douglas County Surveyor"

	T 31 S		
R	1/4		R
7		6	
W	S25	S30	W

We place I.P. and wooden post beside brass cap. Cap is set in
mound of stone.

No new BT's necessary.

1/3/77

137

Section Corner for Secs. 29, 28, 32 and 33.

Found - A 1" x 36" I.P. with brass cap laying beside road and properly
marked, 1966 County Surveyors Office Ren. #107
A W. Fir 4" now 7" bears S.77 1/2°E., 74.8 ft. with well healed
blaze.
A D. Fir 4" now 8" bears N.38°E., 36.5 ft. with well healed
blaze.
A D. Fir, 4" now 7" bears N.4°W., 77.5 ft. (Rec. 76.4 ft.) with
visible scribing in partially healed blaze.
A 40" Fir stump bears N.81 1/4°W., 98.2 ft. (Rec. N.84°W., 89.4 ft.)
BT tag Rec. N.84°W., 98.2 ft. marked "T31S R6W S29 CS BT" in
partially healed blaze.

R. B. Kimberling
P. L. Earle
Doug. Co. Surveyor
Office
Aug. 1, 1977
C.S. 59/38

Reset - Brass cap stamped to read "T31S R6W S29 S28 S32 S33 Reset 1977 1966

No new accessories.. Corner is on south edge of gravel road.

8/1/77