

Douglas County Surveyor's Record of  
Government Corners Renewed

T 31 T. S. R 6 R. W. W. M.

KOME-CHAPMAN CO., EUGENE, ORE. 91891

152

Bruce Shaner, L.S.430  
Witnesses: Mark Ramp  
Brian Cameron  
Dec. 7, 1981  
C.S. 58/229

1/4 Corner for Secs. 25 and 36.  
Found - 1" I.P., now buried & broken in half, lower half in position and OK. Ren. #50  
10" yew BT, scribes visible, now uprooted and down, but in position, bears S.77°E., 37.5 ft.  
10" maple BT, S.78°W., 17.5 ft. now gone.  
Set - 2" x 32" I.P. with 2 1/2" brass cap in place of 1" iron pipe stamped Shaner Engineering T31S R6W W.M. 1/4 S25 S36 R.L.S. 430 1981. Reset 1" I.P. alongside brass cap.  
New BT's- 36" D. fir stump BT, scribed "1/4 S 36 BT" bears S.84°E., 38.0 ft.  
32" D. fir stump BT, scribed "1/4 S25 BT" bears N.24°W., 25.1 ft.  
Note - Corner is 150 ft. south of logging road, U.S.B.L.M. 31-6-26.0  
12/7/81

Gregory Quibell,  
Deputy, Doug. Co.  
Surveyors Office  
John Powell  
May 17, 1983  
C. S. 62/7

1/4 Corner for Sections 29 and 32 153  
Found - 1966 County brass cap improperly marked S 26/S 32. Ren. #92  
3/4" iron pipe alongside brass cap. Ren.#26  
Orig. 12" madrone, now 19" and uprooted with rotted out face visible on underneath side of tree, bears S. 25°E., 14.5 ft. to root hole.  
17" fir, Ren. #26, now 21" stump with good scar bears N. 56° W., 6.5 ft.  
32" cedar, Ren. #26, now 34" stump with good scar bears S.72°E., 19.0 ft.  
Set - I "X" out the 6 that was improperly stamped in "S 26" per Ren. #92 and stamp 9 alongside.  
New Accessories:  
Set spike marked "BO 1" in top of 36" cedar stump bears N.52°E., 34.1 ft. to spike.  
Set spike marked "BO 2" in top of 39" fir stump used for tail hold in recent logging, bears S.6 1/2°E., 40.0 ft. to spike  
Corner lies on ridge top running N.18°E., approx. 200 ft. north of road which goes to landing.  
5/17/83

L.E. Monrean,  
Deputy, Doug. Co.  
Surveyors Office  
Witness: J.M. Powell  
July 22, 1983  
C.S. 62/9

1/4 Corner for Section 1; and Sec. 36 of T.30-6 154  
Found - 1983 BLM brass cap monument set in stump of Fir marked by Cain in 1921 with 3/4" iron pipe set by Wenderoth along west side of stump. See Renewals #1, 61 and 141.  
From which:  
Douglas Co. Surveyors 1979 iron pipe and brass cap bears S.40 1/2°E., 15.5 ft.  
22" fir bears S.36°W., 26.9 ft. Tree is single blazed and scribed "1/4 S1 BT".  
5" fir bears N.23°E., 15.8 ft. Tree is single blazed and scribed "1/4 S36 B".  
Set - We remove the brass cap from the 1" iron pipe set by the County in 1979 and place a yellow plastic cap marked "Doug. Co. Surveyor" in the pipe for identification purposes.  
We remove scribing and tags from trees noted in Ren. #141 (1979 DCSO trees) as noted. Bearings and distances to the following defaced trees are from 1979 DCSO monument:  
16" fir bears west 26.1 ft.  
10" madrone bears N.66 1/2°W., 45.3 ft.  
12" fir bears N.40°E., 32.0 ft.  
18" fir bears S.8°E., 34.6 ft.  
The two BLM BTs referencing the 1983 BLM cap are now left intact.  
7/22/83

FD 3/86  
By: D. Bentz  
M/01-1

Randall Smith  
Deputy, Doug. Co.  
Surveyors Office  
Stephen Flause  
March 28, 1984  
C.S. 62/16

1/4 Corner for Secs. 23 and 26 155  
Found - 1" drill steel protruding 4" above ground. Ren. #16  
36" fir now a 40" dia. 25 ft. high snag, with two notches on east side and one notch on west side, bears N.84°W., 15.7 ft. (Rec. West 14.0' dist. is to east side of BT) Ren. #16  
8" R. fir now a 17" D. fir with a well healed singel blaze bears S.54°W., 49.7 ft. Ren. #48  
17" R. fir now a 24" D. fir with a well healed double blaze bears N.5°E., 48.6 ft. Ren. #48  
Set - Doug. Co. Surveyors Office disk on a 1" x 30" I.P. protruding 3" above ground with 1" drill steel alongside marked: "Douglas County Surveyors Office T31S R6W 1/4 S23 S26 1984"  
No new accessories. Corner lies on steep rocky east slope.