

Douglas County Surveyor's Record of  
Government Corners Renewed

T. 31 S T. S. R. 6 W. R. W. W. M.

FORE-CHAPMAN CO., EUGENE, ORE. 21881

Mark Smalley  
For: Roseburg Res.  
May-July 1992  
M 112 - 52

1/4 Corner for Section 6 and Section 31 of T.30-6.

161

Found BT's -

26" Pine bears N.38 $\frac{1}{2}$ °W., 99.0 ft. healed face

24" Maple bears S.62°E., 311.8 ft. found scribe. (rec. 283.8 ft.)

Set - 5/8" x 48" iron rod and alum. cap on line between section corners  
at call distance from NW BT. (SE BT did not match call dist.)

New Accessories -

27" Fir bears N.20°W., 118.4 ft. scribed "1/4 S31 BT"

25" Fir bears S.73°E., 223.0 ft. scribed "1/4 S6 BT"

7/92

Corner to Sections 27, 28, 33 & 34.

Found - 1970 Douglas County Surveyor's Office BC/IP

37" D.Fir, N.40°W., 31.0 ft. See renewal # 132

22" D.Fir, N.66°W., 28.1 ft.

40" D.Fir, S.80°E., 60.0 ft.

162

New Accessories -

10" D.Fir, S.17°E., 22.0 ft. scribed "S34 BT"

10" Madrone, N.29°E., 20.7 ft. scribed "S27 BT"

6" Pine, S.28°W., 64.4 ft. scribed S33 BT"

Note - Corner lies 500 ft. south of BLM Rd. #31-6-33.3 in the SW Corner  
of a unit logged this summer

Mark Smalley  
For: Roseburg Res.  
Sept. 1993  
C.S. 63/153

163

1/4 Cor. Secs. 24 & 25

Found - 2 $\frac{1}{2}$ " Brass cap on a 1" iron pipe, (Ren. #93) from which:

18" Hemlock (rec. 8"), face overgrown, bears N.33°W., (rec.  
N.36°W), 65.1'.

36" D.Fir stump, scribes vis., bears S.70°W., 66.5' to face.

20" W.Fir, (rec. 7"), face overgrown, bears N.85°E., 34.3' (rec.  
N.82°E., 34.9')

New Accessories -

12" D.Fir, Scribed "1/4 S25 BT" bears S.46°E., 17.0'

6' steel fence post, South 0.5'.

Note - Corner lies on steep North slope about 250' South of creek &  
logging road.

Bruce Shaner, L.S. 430  
For: Richard McKenzie  
John Wright - Clem Berlier  
Oct. 1993 M 117-76 C.S. 63/153

1/4 Cor. Secs. 13 & 24

Corner was surveyed in & set by proportioning, found distance & bearing with  
U.S. GLO records. See survey file, Douglas County Surveyor's Office.

Set - 5/8" Iron Rod with 1 $\frac{1}{2}$ " Aluminum cap, stamped "SHANER ENGR. RLS  
430", in steep, rocky cutbank of mainline logging road, (No way  
to install brass cap). From which,

10" D.Fir, scribed "1/4 S13 BT" bears N.35°E., 32.4'.

10" D.Fir, scribed "1/4 S13 BT" bears N.83°E., 40.6'.

14" D.Fir, scribed "1/4 S24 BT" bears S.38°E., 41.4'.

10" D.Fir, scribed "1/4 S24 BT" bears S.2 $\frac{1}{2}$ °W., 78.2'.

6' steel fence post, bears East, 0.5'.

Note - Corner is on west cutbank of U.S. B.L.M. Road # 30-6-35.0.

164

Cor. Secs. 13, 14, 23, & 24

Found - 2 $\frac{1}{2}$ " Brass cap on a 1" iron pipe (Ren. # 52) from which;

10" madrone, scribes visible, bears S.20°W., 13.2'.

46" D.Fir, scribes visible, bears S.73°E., 21.0'.

50" D.Fir, now blown down & gone, bears N.32°E., 29.7'.

12" D.Fir, face overgrown, bears S.72°W., 33.2'.

New Accessories -

6" Chinguapin, scribed, "T31S, R6W, S14, BT", bears N.3°W., 22.0'.

No trees near in NE Quadrant.

Note - Corner is 50' South of main logging & mining road.

165