

Douglas County Surveyor's Record of
Government Corners Renewed

T 31 S T. S. R 7 W. R. W. W. M.

Section Corner common to Sections 26 - 27 - 34 - 35.
Found - 24" Laurel S.33°E. 54 lks. (scribe visible)
44" Fir S.85°W. 20 lks. (stump)
28" Fir N.15°W. 14 lks. (stump)
Set - 4" x 4"x 48" Cedar Post
20" S. Pine N.80 $\frac{1}{2}$ °E. 35.5 ft.
14" S. Pine S. 8 $\frac{1}{2}$ °E. 20.0 ft.
4" Fir S.25 $\frac{1}{2}$ °W. 17.5 ft.
12" R.Cedar N.83 $\frac{1}{2}$ °W. 20.5 ft.

September 15, 1961

Howard W.
Johnstone
Ror Roseburg
Lumber.
C.S. File
51/163

$\frac{1}{4}$ Corner to Sections 8 and 17. 9
Found - Now 8" Live Oak that shows good scar for Corner Tree.
Now 10" Laurel N.20°W. 33.0 ft., shows good scribing "S"
on old and partly rotted face.
Orig. S.W. BT., now 12" Laurel.
Set - Brass Cap at Corner & at North edge of base of Cor. Tree.
Mkd: Brass Cap $\frac{1}{4}$ S 8 T31S R7W County Surveyor's
S17 Office, 1962
New BT: 21" R.Fir bears N.49°W. 18.5 ft. scribed $\frac{1}{4}$ S8 CS BT.

$\frac{1}{4}$ Corner to Sections 8 and 9. 10
Found - Both Original BT's. each is now down. S.E. BT. shows
good scribing "S" on old face.
Set - Brass Cap at Corner & Mkd: County Surveyor's Office, 1962
 $\frac{1}{4}$ S8/S9 T31S R7W
New BT's: 30" Pine bears N.27°W. 18.0 ft. scribed $\frac{1}{4}$ S 8 CS BT.
17" R.Fir bears N.44°E. 42.0 ft. scribed $\frac{1}{4}$ S9 CS BT.

$\frac{1}{4}$ Corner between Sections 25 and 36. 11
Found - 20" Fir N. 5°E. (now a snag, bark scribe visible)
24" Fir S.40°E. (faint bark scribe)
Set - 1" by 30" Iron Pipe
Scribed - 22" D. Fir N.59°E. 42.8 ft.
Rescribed the Orig. BT. S.40°E.

Section Corner for Sections 25 26 - 35 - 36. 12
Found - 4 good Bearing Trees, renewed in 1957, Ren #5
Set - 1" by 30" Iron Pipe.

$\frac{1}{4}$ Corner for Sections 26 and 35. 13
Found - Original Bearing Trees in good Condition.
Set - 1" by 30" Iron Pipe.

$\frac{1}{4}$ Corner between Sections 23 and 26. 14
Found - 12" Fir N.10°E. 5.3 feet.
Set - 1 $\frac{1}{4}$ " by 40" Iron Pipe
Scribed - 20" D. Fir S.76°W. 74.9 feet.
15" W. Fir N.76°E. 52.0 feet.

$\frac{1}{4}$ Corner between Sections 25 and 26. 15
Found - Live Oak N.32°W. 56.1 ft., good condition.
S. Pine S.18°E. 55.4 ft., now 60" snag.
Set - 1" by 30" Iron Pipe.
Scribed - 6" D. Fir S.70 $\frac{1}{2}$ °E. 11.0 feet.

Section Corner for Secs. 34 & 35, T31S-7W. & Secs. 2 & 3, T32-7W.
Found - 26" Fir N.54°W. 71.9 ft. (now 46", good condition)
8" Laurel N.12°E. 46.9 ft.
14" Laurel S.60°W. 4.0 ft. (stump)
Set - 1" by 36" Iron Pipe
Scribed - 16" B.Fir S.35°E. 44.4 ft.
14" D.Fir S.78°W. 65.0 ft.
12" D.Fir N.36°E. 53.6 ft.

James W. Bryon, Deputy Co. Surv.
Dale McFarland & John Powell
May 1, 1962
C. S. File No. 49/109

Howard W. Johnstone
Ror Roseburg Lumber Co.
May 28, 1962
C. S. File No. 51/163

RE-RENEWED, SEE CORNER NO. #104

RE-RENEWED, SEE CORNER NO. #39

RE-RENEWED, SEE CORNER NO. #107

RE-RENEWED, SEE CORNER NO. #103

RE-RENEWED, SEE CORNER NO. #44