

**Douglas County Surveyor's Record of  
Government Corners Renewed**

T 31      T. S.      R 7      R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

1/4 Corner for Secs. 25 and 36. #130 **104**  
 Found - A 1" Iron pipe bears S.40°E., 1.1 ft. from corner set from OBT stump  
 A 24" Fir stump bears S.40°E., 5.9 ft. with partially healed pitched  
 over blaze. Lower bark scribe "BT" visible (OBT used to set  
 corner). Ren. #12  
 A 22" D. Fir stump bears N.58°E., 42.5 ft. (Rec. N.59°E., 42.8 ft.  
 good to 1" I.P.) with well healed double blaze.  
 Set - A 1" x 30" Iron pipe with brass cap set 6" above ground marked:  
 "Douglas County Surveyor" T 31 S R 7 W  
 1977 S 25  
1/4 S 36

New BT - A 6" Chinkapin bears N.60°W., 85.4 ft. double blazed and scribed  
 "1/4 S25 CS BT".

Note - Corner is at SE corner of a stand of timber. Rd. #31-7-25.1 is  
 400 ft. north.

1/4 Corner for Sec. 3 and Sec. 34 of T30-7. 10/20/77  
FDOK BY Ron Quimby  
3/94 M119-21 **105**  
 Found - 1" Iron pipe in a mound of stone. Ren. #41

A 12" now 23" Sugar pine bears S.49°E., 49.0 ft. with a well  
 healed double blaze.

A 17" now 16" Incense Cedar bears S.43°W., 99.8 ft. with visible  
 scribing "1/4 S3 CS BT" in a partially healed double blaze.

Set - A 1" x 36" Iron pipe with brass cap set 9" above ground (in mound  
 of stone and iron pipe along side) marked "Douglas County  
 Surveyors" T30S R7W 1/4 S34 S3 T31S R7W 1977.

No new accessories

Note: Corner lies in old unit, 50 ft. north of tree line.

1/4 Corner for Secs. 7 and 18. **106**  
 Found - Iron pipe which had been pulled out of the ground. (Ren. #21)  
 42" D. Fir, bears N. 40° E., 14.0 ft.  
 30" D. Fir bears N. 12° E., 14.8 ft. (now a stump)

Set - 5/8" x 30" Iron rod.

Scribed: 9" D. Fir bears S. 9° W., 46.6 ft.

7/17/78

1/4 Corner for Sections 23 and 26 **107**  
 Found - 1 1/4" x 40" I.P. firmly set 30" in the ground. Ren. #15  
 Stump hole bears N.10°E., 5.0 ft. Possibly from orig. 12" Fir.  
 20" now 23" Fir bears S.76°W., 74.9 ft. with well healed double  
 blaze. This tree will be cut in future road building project. #15  
 15" now 19" Fir bears N.76°E., 52.0 ft. with well healed double  
 blaze. Ren. #15

Set - Since pipe is in good condition and firmly set I DO NOT set a  
 brass cap.

New BT's - An 11" Fir bears N.06°E., 51.8 ft. scribed 1/4 S23 CS BT in  
 double blaze.

A 10" Fir bears S.35°E., 60.4 ft. scribed 1/4 S26 CS BT in double  
 blaze.

A 9" Fir bears S.87°W., 44.2 ft. scribed 1/4 S26 CS BT in double  
 blaze.

All trees have DCSO bearing tree tags.

4/22/81

1/4 Corner for Sections 31 and Sec. 36 of T.31-8 **108**

Set - 5/8" x 36" I.R. and alum. cap.

BT's- 10" Oak, N.78°W., 41.6 ft.

11" Cedar, N.74°E., 22.7 ft.

8/18/81

Section corner for Secs. 27, 28, 33 and 34 **109**

Found - Iron pipe with brass cap marked Douglas County 1963. Ren. #35  
 20" cedar stump, N.50°E., 6.8 ft. scribe visible. (1964 resurvey)

17" fir, S.61°E., 10.0 ft. healed face. (Rec. #35, Sugar Pine)

22" pine, N.72°W., 48.8 ft. healed face. Ren. #35

1" I.P. bears S.3°E., 10.5 ft. (Rec. S.10°E per Ren. #35)

New BTs - 14" cedar, S.81°W., 31.1 ft.

7" fir, N.11°E., 24.5 ft.

1/83

R. B. Kimberling  
 M. W. Cline  
 Doug. Co. Surveyors  
 Office  
 Oct. 27, 1977  
 C.S. 59/40

Howard Johnstone  
 For: Roseburg  
 Lumber Company  
 July 17, 1978  
 C.S.58/175

Gregory Quibell,  
 Deputy, Doug. Co.  
 Surveyors Office  
 Karen Mosley  
 Ted Davis, BLM  
 April 22, 1981  
 C.S. 61/19

Howard Johnstone  
 For: Roseburg Lbr. Co.  
 August 18, 1981  
 M 88 - 62

Howard Johnstone  
 For: Roseburg Lbr.  
 Company  
 January 20, 1983  
 C.S. 58/188