

**Douglas County Surveyor's Record of
Government Corners Renewed**

T 31 T. S. R 7 R.W.W.M.

MOKE-CHAPMAN CO., EUGENE, ORE. 21821

110

1/4 Corner for Secs. 17 and 20
 Found - Original 7" now 7" Live Oak corner tree with good scar on North side. Brass cap set in 1970 by DCSO no longer in the ground. Ren. #91
 Orig. 14" fir now 14" with partially healed pitched over blaze bears S.32°W., 4.0 ft. Ren. #91
 Orig. 7" live oak, now 7" with previously opened now rotted face with no scribing visible, bears N.42°E., 10.6 ft.
 18" fir now 19" with partially healed pitched over blaze bears N.68°E., 26.0 ft. Ren. #91
 New Accessories:
 7" fir scribed "1/4 S17 CS BT" in double blaze bears N.85°W., 23.4 ft.
 8" live oak scribed "1/4 S20 CS BT" in double blaze bears S.64°E., 20.4 ft.
 5/8" x 30" iron rod with alum. cap marked "Douglas Co Surveyor BO 1" bears N.43°W., 10.0 ft.
 5/8" x 30" iron rod with alum. cap marked "Douglas Co Surveyor BO 2" bears S.55°W., 12.0 ft.
 Sketch in CS file. Line crossing tag on 20" ⁺ fir N.22°E., 200 ft. ⁺ to corner.

Gregory Quibell
 Deputy, Douglas Co.
 Surveyors Office
 John Powell
 Randy Smith
 February 3, 1983
 C.S. 62/7

2/3/83

111

Section corner for Secs. 8, 9, 17 and 16
 Set - 5/8" x 36" iron rod and alum. cap. Cap mkd. with "LS 498".
 BT's- 16" fir, N.44°E., 26.8 ft.
 15" fir, S.29°E., 30.0 ft.
 12" fir, S.56°W., 26.3 ft.
 20" fir, N.28°W., 31.0 ft.

Howard Johnstone
 For: Roseburg Lbr. Co.
 Dec. 20, 1982
 M 90 - 34

112

Center, Section 9
 Set - 5/8" x 36" iron rod and alum. cap. Cap mkd. with "LS 498".
 BT's- 5" alder, N.52°W., 10.9 ft.
 8" alder, N.4°E., 17.2 ft.

12/20/82

113

1/4 Corner for Sections 9 and 10
 CONDITION REPORT ONLY
 Found - Original corner tree, a 52" fir with well healed blaze on west side and "1/4 S9/S10" bark scribed on SW side.
 1 1/2" iron pipe with brass cap attached firmly set, partially under west side of corner tree. Cap mkd. "County Surveyors Office T31S R7W 1/4 S9/S10 1971. Ren. #92
 From Corner Tree:
 Orig. 16" oak now 18" with rotted hole in the area a blaze would have been located, bears S.88°E., 30.2 ft. (Rec. S.78°E., 34.3')
 Orig. 24" fir, now 41" with scribed "1/4 S" visible in previously opened blaze, bears N.88°W., 32.6 ft. (Rec. N.85°W., 36.3 ft.)
 12" fir per Ren. #92, now 12" with well healed double blaze, bears N.2°E., 30.3 ft. (Rec. 30.6 ft.)
 2 1/2" iron pipe with brass cap attached per 1974 resurvey marked "T31S R7W S9 RM 1974 33 ft. (Rec. says S10) and an arrow pointing to the corner, bears N.75°W., 29.2 ft. (Rec. N.75°E., 33 ft.)
 2 1/2" iron pipe with brass cap attached per 1974 resurvey marked "T31S R7W S9 RM 1974 33 ft." and an arrow pointing to the corner bears S.75°W., 29.0 ft. (Rec. 33.0 ft.)

Gregory Quibell, L.S.
 Deputy, Douglas Co.
 Surveyors Office
 Witness: Randy Smith
 February 14, 1983
 C.S. File 62/7

2/14/83

114

Center 1/4 corner for Section 6
 Set - 5/8" x 36" iron rod with aluminum cap marked "LS 498".
 BTs - 17" Cedar, N.31°E., 36.5 ft.
 12" Fir, S.83°E., 71.0 ft.

Howard Johnstone
 For: Roseburg Lbr.
 February 10, 1983
 M 93 - 55

2/10/83