

Douglas County Surveyor's Record of
Government Corners Renewed

T. 31 S. T. S. R. 8 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

17

Section Corner common to Sections 8 - 7 - 18 - 17.

Corner was found to be in poor condition.

Scribed - 2 BT's. & Mkd: as follows:

Set - 7/8" Hex drill steel 20" in the ground for the corner.

36" Fir S. 58 1/2° E. 23.2 ft. was ref. & scribed S17 R 4186 BT.

(Orig. BT. for this quad has fallen over & rotted out.)

20" Fir S. 45° W. 24.3 ft. was ref. & scribed S18 R 4186 BT.

(Orig. BT. for this quad. is in place but is a 12" Fir Snag with most the orig. bark scribing obliterated by old cruising chopping but the B.T. scribing is plainly vis. at base.)

The Orig. BT. in the SW quad. is now 36" and since it has grown so rapidly, all evidence of the Orig. bark scribing gone.

The Orig. BT. in the NE quad has old cruiser chopping marks which has nearly obliterated the Orig. bark scribing, but with close scrutiny, original marks found above chopping.

Bearing trees were referenced with compass and chain, magnetic declination used was 19 1/2° E.

Lorne V. Swearingen
For The Robert Dollar Co.
May 2, 1962
C. S. File No. 51/68

87

RE-NEWED, SEE CORNER NO.

T30S

Section Corner R8W S 36 | S 31 R7W

18

Found - Brass Cap at Corner & all Bearing Trees, as recorded, GLO notes, 1918.

S. W. Bearing Tree, now rotted stump

New BT: 6" R. Fir bears S. 29° W. 4.5 ft. scribed S1 T31S R8W CS BT.

Feb. 20, 1964

James W. Byron, Deputy
Mike Darby & J. Halterman
S. S. File No. 53/40

Fd. Ok. by
H. JOHNSTONE
DEC. 1981
SEE M 89-79

19

Set. Cor. to Secs. 12 & 13, T31-8W & Secs. 7 & 18, T31-7W.

Found - 3/4" Iron Pipe at Corner. See Map File M 23 - 68.

16", now 36" Pine N. 31° W. 55.4 ft., shows scar.

8" Pine, now _____, S. 16° E. 105.6 ft., shows scar.

16", now 26" Pine, S. 60° W. 88.4 ft., Tree had been opened for scribing 8".

Set - Brass Cap at Cor. Mkd: County Surveyor's Office 1966

R	T 31 S	R
8	S 12 S 7	7
W	S 13 S 18	W

New BT's: 13" D. Fir N. 44° W. 25.6 ft. mkd. T31S R8W S12 CS BT.

15" Pine S. 7° W. 19.9 ft. mkd. T31S R8W S13 CS BT.

10" Pine S. 37° E. 20.1 ft. mkd. T31S R7W S18 CS BT.

7" D. Fir N. 21° E. 33.2 ft. mkd. T31S R7W S7 CS BT.

John M. Powell
Frank Jones and Cliff Stone
Sept. 20, 1966
C. S. File No. 54/36

20

Sec. Cor. to Sections 11 - 12 - 13 - 14.

Found - 36" Fir, now Snag, N. 20° E. 4.6 ft., Tree has been opened, scribe visible "8" "S12"

60" Fir, now down, S. 70° E. 37.0 ft. (Bear. S.B. S. 63° E.)

12" W. Fir, now snag, S. 30° W. 54.8 ft., (bear to be S. 35° W.)

10", now 26" Fir N. 70° W. 17.8 ft. (find bear to be N. 65° W.)

Also fine 3/4" Iron Pipe at Corner.

Set - Brass Cap at Cor. Mkd: County Surveyors Office 1966

T 31 S	R 8 W
S 11	S 12
S 14	S 13

New BT's: 10" W. Fir N. 83° E. 33.0 ft. mkd. T31S R8W S12 CS BT.

9" Cedar S. 63° W. 27.5 ft. mkd. T31S R8W S14 CS BT.

8" W. Fir S. 49° E. 27.1 ft. mkd. T31S R8W S13 CS BT.

21

1/4 Corner to Sec. 13, T31-8W. & Sec. 18, T31-7W.

Found - 16", now 36" D. Fir, S. 42° W. 18.5 ft., some marks visible, I believe to be scribe marks. Also notch in bark below face which is common to Byar's work.

18" D. Fir, now down & burnt, S. 58° E. 46.2 ft.

Set - Brass Cap at Cor. Mkd: County Surveyors Office, 1966

T31S	R8W	1/4 S13/S18	R7W
------	-----	-------------	-----

New Bt's: 7" Live Oak S. 1° W. 20.2 ft. mkd. 1/4 S 13 CS BT.

9" Live Oak N. 5° E. 6.0 ft. mkd. 1/4 S18 CS BT.

John M. Powell
Frank Jones & C. Stone
Nov. 23, 1966
C. S. File No. 54/36