

**Douglas County Surveyor's Record of  
Government Corners Renewed**

T 31

T. S.

R 8

R. W. W. M.

ROKE-CHAPMAN CO., EUGENE, ORE. 21881

Howard Johnstone  
For: Roseburg, Lbr.  
Nov. 22, 1977  
M 5 - 49

1/4 Corner for Secs. 11 and 14.  
Set - 5/8" x 48" Iron rod and alum. cap.  
BT's - 6" Fir, N.48 1/2°E., 22.8 ft.  
12" Fir, N.21°W., 12.4 ft. Ren. #49  
11" Chinquapin, N.70°W., 6.6 ft. Orig. BT.

11/22/77

Greg Quibell  
Debbie Stewart  
Doug. Co. Surveyors Office  
Feb. 19, 1981  
C.S. 61/19

1/4 Corner for Secs. 7; and Sec. 12 of T.31-9  
~~Found~~ 1962 BLM brass cap in good condition buried in the ground approx 8", properly stamped.  
Stump of orig. 42" now 47" Fir BT with BLM BT tag bears West 13.2 ft. to the face.  
Stump of orig. 48" Fir BT (sec. 7) which has rolled over and slid down hill almost on top of the cap.  
Set - Boat spike in top of orig. Sec. 12 BT stump which is now 47". Spike bears West 14.5 ft.  
Boat spike in top of 48" Fir stump which bears N.38°E., 66.9 ft.  
Both stumps have new BT tags. No tree suitable for scribing are in the vicinity.

2/19/81

Howard Johnstone  
For: Roseburg Lbr.  
June 1, 1981  
M 87 - 74

Center 1/4 Corner for Section 28  
Set - 5/8" x 30" I.R. and alum. cap.  
BT's - 14" Fir, S.33°E., 14.3 ft.  
17" Fir, N.13°E., 22.5 ft.

6/81

Howard Johnstone  
For: Roseburg Lmbr.  
June 18, 1981  
M 8 - 62

1/4 corner for Sec. 36, & Sec. 31 of T. 31 R. 7.  
Set - 5/8" x 36" I.R. w/ aluminum cap.  
BT's - 10" Oak bears N.78°W., 41.6-ft.  
11" Cedar bears N.74°E., 22.7-ft.

8/18/81

Howard Johnstone  
For: Roseburg Resources  
June 4, 1987  
C.S. 63/26

Section corner for Sections 17, 18, 19 and 20.  
Found - 1967 County brass cap, pulled out of ground from logging, Ren.#36  
38" D. fir, N.39°E., 57.4 ft. OBT. Stump.  
24" D. fir, S.66°E., 9.2 ft. OBT. Shows scar. OK  
39" D. fir, S.58°W., 19.8 ft. OBT. Stump.  
12" Cedar, N.8°W., 26.5 ft. Gone  
7" W. fir, N.35°E., 15.3 ft. Gone  
9" Hemlock, S.46°W., 37.8 ft. Gone  
RESET - Brass cap at record distances from remaining BT and the stumps.  
New BTs - 44" D. fir stump, S.58°W., 20.6 ft. Alum. nail in top of stump.  
Scribed "BT" in vertical section of undercut.  
5" Hemlock, N.18°E., 45.3 ft. scribed "T31S R8W S17 BT" with tag.  
10" Hemlock, N.75°W., 85.7 ft. scribed "T31S R8W S18 BT" with tag.  
6" Hemlock, S.32°E., 22.9 ft. scribed "T31S R8W S20 BT" with tag.  
All timber around corner has been cut except in Sec. 20. Corner is on NW slope 400 ft. below access road #31-8-20.

6/4/87

Raymond Brown  
L.S. 2391  
May 23, 1991  
C.S. 63/129

1/4 Corner for Sections 28 and 33  
Found - Brass cap attached to a 1" iron pipe. Corner now has a 5" bend to the West, due to recent logging activity. I dug down around the I.P. & it appears to be in the orig. place, as I found traces of flagging at various levels in the dirt. Pipe at 12" down is straight into the ground. Ren. #70  
An orig. 57" now 66" D.Fir bears N.55°E., 26.8 ft. not 25.1 ft. with visible scribe "1/4 S28 CS BT" in unhealed blaze. Bt alive and well. NOTE: BT has 2 arrows chopped on its side, one at approx. center and one at a distance that would fit the 25.1 ft. recorded distance.  
Laurel BT has been destroyed by recent logging activity.  
Set - At corner, added rock mound 5" tall with 2 ft. dia. at base. Also placed a 6 ft. tall steel fence post, set 18" into ground, one foot North of corner.  
New BTs - A D. Fir, 4" dia. bears N.66°W., 24.2 ft. dist. mkd. "X BT".  
A Tan Oak, 7" dia. bears N.19°W., 17.7 ft. dist. mkd. "1/4 S28 BT".  
A Tan Oak, 11" dia. bears S.35°W., 356.3 ft. mkd. "1/4 S33 BT".  
11" Live Oak is closest tree in the Southwest quad.  
No trees in Southeast quad.  
Corner is approx. 300 ft. East from the end of BLM Rd. #32-8-4.2

82