

Douglas County Surveyor's Record of
Government Corners Renewed

T 31

T. S.

R 9

R. W. W. M.

FOKE-CHAPMAN CO., EUGENE, ORE. 97301

168

1/4 Corner for Sections 24 and 25.

Found - 1967 Douglas Co. brass cap lying on ground. Ren. #50
Orig. BT, a fir, 23 ins. diam. bears S.25°E., 79 lks. (52.1 ft.)
dist., with fragmentary scribe marks visible on mostly
healed blaze.
Orig. BT, a fir, 31 ins. diam., bears N.15°W., 51 lks. (33.8 ft.)
dist., with healed blaze. (1901 record is N.20°W., 57 lks.,
DCSO is N.15°W., 33.8 ft.)

Because the original record cannot be reconciled, I accept the point
determined by the Douglas County Surveyor's office as the corner point.

Set - Reset the iron post (1" x 30") 18" in the ground, to solid bed-
rock, in a small mound of stone, 1 1/2ft. base, 6 ins. high.

7/23/85

Terrence O.
Nickerson. L.S.
Bureau of Land
Management -
Medford District
July, 1985
C.S. 62/24

169

Section corner for Sections 16, 17, 20 and 21.

Found - 1967 Douglas County brass cap lying on the ground. Ren. #118
Orig. BT, a fir snag, 40 ins. diam., 25 ft. high, bears S.38°E.,
128 lks. dist. to face. (84.5 ft.) with scribe marks T31SR9
S21 visible on open blaze. (DCSO record of 85.6 ft. appears to
be to the side center of tree.)

Orig. BT, a fir, 45 ins. diam., bears S.45°W., 100 lks. dist.
to face (66 ft.) with healed blaze.

1967 BT's - A fir, 9" dia., bears N.26°E., 18.6 ft. dist., with healed blaze.

A fir, 11 ins. diam., bears S.45°E., 15.9 ft. dist., with
healed blaze.

A fir, 7 ins. diam., bears S.21°W., 29.5 ft. dist., with healed
blaze.

A fir, 16 ins. diam., bears N.53°W., 18.1 ft. dist., with
healed blaze.

Set - Reset the iron post (1" x 30") 18 ins. in the ground, to solid
bedrock, in a collar of stone, 2 ft. base, 6 ins. high. The
corner point fell in the middle of a large down fir log (6 ft.
diam.) I removed a section of this down log to monument the
corner position.

7/24/85

170

1/4 Corner for Sections 28 and 29

Set - 5/8" rebar with cap "Riley 705".

Found - Original stone with 1/4 on it.
OBT 18" yew, N.38°E., 37 lks. (face rotted)
Stump hole of the other OBT.

New BTs - 10" Fir, N.18°E., 9.0 ft. (1/4S28BT)

8" Fir, S.53°W., 21.6 ft. (1/4S29BT)

Gerald Riley
LS #705
For: Giustina Bros.
Nov. 1989
C.S. 63/61

NOTE:
SEE CORNER
REPORT BY COUNTY
CREW VISIT TO THIS CORNER
C.S. 64/3

11/26/89

171

Section corner for Secs. 17, 18, 19 and 20

Found - I find a 1/2" iron pipe set by Clifford Stephens at the cor.
of Secs. 17, 18, 19 and 20. Ren. #16

I also find the 1967 BLM brass cap (Rec. is 1967 County BC) Ren.
#85) lying on the ground nearby so I lay it against the 1/2"
pipe.

The Orig. 36" Fir BT, N.70°E., 34 links is now a 48" stump with
face grown over

The orig. 16" Fir BT, S.32°W., 57 links is now 26" with face
grown over.

New - I chop an "X" on the stump of the orig. 24" Cedar BT, N.60°W.,
57 links.

I scribe "S20 BT 378" on a 16" Fir, S.37°15'E., 31.5 ft. to
the center.

Jack E. LaFlamme
L.S. #378
For: Georgia Pac.
March, 1990
C.S. 63/104

172

1/4 Corner for Secs. 17 and 20

Set - I set a 5/8" iron rod with yellow plastic cap for the 1/4 Sec.
corner between secs. 17 and 20

From Which:

The orig. 30" Fir BT, S.5°E., 43 links which is now 40" with a
BT tag.

The orig. 24" Fir BT, N.54°W., 62 links has been bulldozed out.
A 3/4" I.P. bears N.82°E., 5.3 ft. from the corner. Ren. #18

I Scribe: "1/4 S17 BT 378" on a 6 ft. fir N.29°E., 12.7 ft. to the center.

I chop a low "X" on the Orig. BT. I also set an iron fence post 0.4 ft.
North of the corner.