

**Douglas County Surveyor's Record of
Government Corners Renewed**

T. 31 S. T. S. R. 9 W. R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 31881

C O N T. - - - - -

Douglas County
Surveyors Office
Stephen Flause
John Pike
Oct. 8, 1992
C.S. 64/32

Section corner for Sections 16, 17, 20 & 21 175
 8" D. Fir now 12" D.B.H. w/fully healed double blaze bears
 S.45°E., 15.3 ft. (as per Rec.)
 5" D. Fir now 8" D.B.H. w/fully healed double blaze bears
 S.21°W., 29.5 ft. (as per Rec.)
 10" D. Fir now 19" D.B.H. w/fully healed double blaze bears
 N.53°W., 18.1 ft. (as per Rec.)
 Note: Monument is on slight bench area of gradual NE slope and on East-
 West cutting lines, a partial cut to the South, a recent clear cut to North

FD. OK BY C. SWEEDEN, JAN. 2003 176
M 141-39

Section Corner for 9, 10, 15 and 16
 Found - 3/4" I.D. Ironpipe firmly set protrudes 7" on Northerly edge
 of found brass cap monument.
 A 2 1/2" dia. brass cap on a 1 3/8" dia. I.Pipe firmly set and
 protrudes 5" from ground. (1967 DCSO) Ren. No. 94
 Orig. BT, a Fir 30" dia., now a 40" DBH D.Fir with a fully
 healed single blaze bears S.39°E., 43.5 ft. (Rec. S.42°E.,
 52.8 ft., a possible slope face measurement)
 18" Fir now a rotted and broken 7 ft. tall Fir stob with
 possible face axe marks visible (no scribing) bears S.40°W.,
 31.1 ft. (Rec. S.40°W., 30.4 ft.) Ren. No. 22
 40" Fir now a roothole of a fallen and out of position Fir bears
 approx. S.71°W., 25.8 ft. Ren. No. 22
 48" D.Fir now a 54" DBH D.Fir with a fully healed single blaze
 bears S.02°E., 34.9 ft. (Rec. S.02°W., 34.9 ft.) Ren. No. 94
 New BTs - 50" dia.4 ft. tall D.Fir stump with an "X" axed in the bark
 facing the corner position, bears N.88°E., 38.9 ft. (A
 Georgia Pacific metal tag on stump has a dist. of 36.5 ft.,
 possibly a face measurement)
 5" DBH D.Fir blazed and scribed "X BT" bears N.57°W., 20.9 ft.
 Monument is on steep Northerly slope just North of a clear cut old growth
 boundary running East-West. Monument is approx. 250± East
 Southeast and 150 ft. above an improved BLM road.

10/8/92

1/4 Corner for Sections 34 and 35 *FD. OK BY D. EDWARDS JAN. 2003* 177
CS 65/46-1
 Found - 1967 DCSO brass cap on a 1 1/2" Iron Pipe, protruding 14" above
 ground. Ren. No. 77
 8" now 30" dia. D.Fir with a fully healed double blaze bears
 N.65°E., 15.8 ft. (Rec. N.70°E., 15.8 ft.) (Orig. BT)
 5" now 10" dia. 2 ft. high broken and rotted Chinquapin stump
 rotted blazes, no scribing found, bears N.70°W., 10.4 ft.
 (Rec. N.70°W., 9.9 ft. dist. possible blaze measurement)(Orig.)
 15" now 23 dia. D.Fir with a fully healed double blaze bears
 N.73 1/2°W., 16.0 ft. (Rec. N.76°W., 16.0 ft.) Ren. No. 77
 New BTs - 6" D.Fir double blazed and scribed "1/4S35 CS BT" bears
 N.5 1/2°E., 11.0 ft.
 9" Chinquapin double blazed and scribe "1/4 S34 CS BT" bears
 S.77°W., 9.0 ft.

10/1/92

1/4 Corner for secs. 27 and 34 178
 Found - 3/4" Iron Rod 18" below road surface. Ren. No. 67
 2 1/2" 1967 DCSO brass cap on a 1 1/2" O.D. I.Pipe, protruding 10"
 above ground, bears South 20.0 ft. from 3/4" I.P. Ren. No. 67
 8" now 14" dia. 3 ft. high D.Fir stump with axe marks, no
 blazes or scribing visible, bears N.40°E., 31.2 ft. from 3/4" I.R.
 15" now 18" dia. 2 ft. high D.Fir stump, scribe marks "B" found,
 bears N.30°E., 51.4 ft. from DCSO BC/IP W.C. Ren. No. 67
 27" now 30" dia., down D.Fir root hole bears S.27°W., 14.7 ft.
 from DCSO BC/IP W.C. BT fell on face. Ren. No. 67
 New BTs - 4" Madrone bark scribed "1/4 S27 CS BT" bears N.76 1/2°E., 40.6 ft.
 4" D.Fir double blazed and scribed "X BT bears S.16 1/2°W., 10.8 ft.
 6" D.Fir double blazed and scribed "1/4 S27 CS BT" bears
 N.58 1/2°W., 45.3 ft.

10/1/92

Douglas County Surveyors Office
 Randall Smith, Deputy - Stephen Flause - John Pike
 October, 1992
 C.S. File 64/32