

Douglas County Surveyor's Record of  
Government Corners Renewed

T. 32 S. T. S. R. 1 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

19

1/4 Corner to Section 5 only, T32-1W.

Found - 3/4" Iron Pipe (pro-rated by Leland P. Lovejoy #267, see map #82 in C. S. File 41/159, no trace set)

New BT's: 6" W. Fir S. 28° E. 19.4 ft. mkd. 1/2 S 5 CS BT.  
7" W. Fir S. 38° W. 15.4 ft. mkd. 1/2 S 5 CS BT.

This cor. lies at fence cor., fences E.-S, & 159' W. of SE Cor. Sec. 32, T31-1W.

20

Wit. Corner to Sec. Cor. to Sections 33 and 34, only, T31-1W.

Found - No trace of Corner Stone, See Ren. #2. of T. 31-1

28", now 32" D. Fir, almost dead, N. 45° E. 29.7 ft., shows good scar.

40" D. Fir, now burnt stob, S. 40° E., faint burnt scribe visible.

12" Maple, now dead, N. 25° W. 19.8 ft., rotten face, old axe work and faint marks.

This corner now lies on E. edge of Elk Creek in dangerous place, therefore, Set Wit. Corner 50.0 ft. E. of True Corner Mkd:

County Surveyor's Office	W. C. 50.0' West to	T 31 S R 1 W
1968		S 33   S 34
		T 32 S S 4

New BT's: 10" Ash S. 6 1/2° W. 11.4 ft. mkd. W.C. T32S R1W S4 CS BT.

9" Ash N. 66° W. 16.8 ft. mkd. W.C. T31S R1W S34 CS BT.

This corner lies on top of creek bank 2.50 ft. S. of fence line.

21

Closing Corner Sec. 6, T32-1 & Sec. 1, T32-2W. Township Corner.

Found - Broken Stone at Township Corner, no marks visible.

55" D. Fir, now 33" splintered stob, S. 55° E. 3.3 ft., scribe visible.

35" D. Fir, now down & out of place, S. 37° W. 9.9 ft., now root hole, found scribe CC T32S R2W.

15" D. Fir, now rotten stump, N. 70° E. 7.3 ft.

Set - Brass Cap at Twp. Cor. Mkd:	County	R	T 31 S	R
	Surveyor's	2	S 31	1
	Office	W	S 1   S 6	W
	1968		T 32 W	

New BT's: 32" D. Fir S. 37° W. 33.6 ft. mkd. CC T32S R2W S1 CS BT.

32" D. Fir S. 33° E. 26.2 ft. mkd. CC T32S R1W S6 CS BT.

This cor. lies 15.8 ft. E. of 1/4 Cor. Sec. 31, T31-1W., below.

22

1/4 Corner to Section 31 only, T31-1W.

Found - 30", now 36" D. Fir, N. 50° E. 17.8 ft., shows good scar with parts of scribing visible, also faint bark scribe "1/2 SBT".

Corner Tree & S.E. BT., down & out of place, A lot of trees fell out of the same area & slid down the mountain.

Set - Brass Cap at Cor. Mkd:	County Surveyor's Office	T 31 S R 1 W
	1968	1/4 S 31
		T 32 S R 2 W.

New BT's: 18" D. Fir N. 21° E. 55.8 ft. mkd. 1/4 S31 CS BT.

This corner lies 15.8 ft. W. of Township Corner, see above.

23

Section Corner to Sections 4 and 3 only, T32-1W.

Found - No trace of Corner Stone or S.W. BT.

10", now 14" Laurel, S. 35° E. 13.2 ft., shows scar.

5", now 8" D. Fir, N. 47° E. 5.9 ft., rotten face, scribe vis.

Set - Brass Cap at Cor. Mkd:	County Surveyor's Office	T 31 S R 1 W
	1968	S 34
		T 32 S S 4   S 3

New BT's: 6" Live Oak S. 74° W. 35.4 ft. mkd. T32S R1W S4 CS BT.

8" Live Oak N. 51° W. 26.2 ft. mkd. T31S R1W S34 CS BT.

S.E. BT. O. K. and Tagged.

24

1/4 Corner to Section 34 only, T31-1W.

Found - No trace of Stone or S. E. Bearing Tree.

30", now 30" D. Fir, N. 70° E. 19.8 ft., opened for scribe "4S".

Set - Brass Cap at Cor. Mkd:	County Surveyor's Office	T 31 S R 1 W
	1968	1/4 S 34
		T 32 S

New BT's: 13" D. Fir N. 42° W. 20.6 ft. mkd. "1/4 S34 CS BT".

N. E. Bearing Tree O.K. and Tagged

John M. Powell  
Frank Jones & W. Penley  
July, 1968  
C. S. File No. 54/71