

Douglas County Surveyor's Record of  
Government Corners Renewed

T. 32 S. T. S. R. 1 W. R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21001

Angle Point 37.0 ft. West of  $\frac{1}{4}$  Cor. to Sec. <sup>35</sup>36, T31-1W, (See Ren. #48.)  
Found - Stone, 6x12x8 at Angle Point.  
14" D.Fir, now stob, N.67°E. 15.8 ft., shows good scars.  
14" D.Fir, now stob, S.80°E. 24.4 ft., scribe visible, "AP BT".  
Set - Brass Cap at A.P. Cor.Mkd: County Surveyor's Office, 1968  
T 31 S R 1 W  
A P  
T 32 S

New BT's: 14" D.Fir S. 20° W. 33.7 ft. mkd: A P CS BT.  
16"D.Fir S. 30° E. 22.6 ft. mkd: A P CS BT.

Note - This cor. lies 37' west of  $\frac{1}{4}$  cor. Sec. 35, T31-1.,Ren.#48.

49

Section Corner to Sections 34 and 35 only, T31-1W.  
Found - Mound of Stone at corner, See Ren. #1, T31-1W.  
12",now Maple, N.46 $\frac{1}{2}$ °W. 16.5 ft., scribe visible "34 BT".  
6",now 10" Maple, N.64° E. 34.6 ft., rotten face, "BT" visible.  
6",now 6" Maple, opened & rotten, N. 34°W. 26.4 ft.  
S. W. BT., 20" Fir, not found.  
Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1968  
T 31 S R 1 W  
S 34 S 35  
T 32 S S 3

Reblzd.& Rescbd: 10" Maple N. 64° E. 34.6 ft. mkd. T31S R1W S35 CS BT.  
New BT: 24" D.Fir S. 79° W. 36.5 ft. mkd. T32S R1W S3 CS BT.

50

Section Corner to Sections 3 and 2 only, T32-1W.  
Found - GLO Brass Cap at corner, properly marked in 1922.  
20", now 36" D.Fir, S.45°W. 7.3 ft., shows scar.  
12",now 14" D.Fir, S. 55° E. 31.0 ft., shows good scar.  
6",now down D. Fir, N. 5° W. 19.1 ft. (Old BT's, tagged & O.K.)  
New BT: 17" D.Fir N. 15° E. 50.7 ft.mkd. T31S R1W S35 CS BT.  
Note - This corner lies 187.4 ft. west of A.P. Corner, See Ren. #49.  
Aug. 1968

51

North  $\frac{1}{4}$  Corner to Section 6 only, T32-1W.  
Set - Brass Cap Mkd: T31S, T32S, R1W  
N  $\frac{1}{4}$  S 6  
1970 O.P.E. 4906

Mkd: 28" Cedar BT bears S.6 $\frac{1}{2}$ °W. 82.3 ft.  
10" Doug. Fir BT bears S.85°W. 23.6 ft.  
Sec.Cor. 31/32 bears N.89°36'E. 157.61 ft. (See Map RM 2 - 21)

52

Center  $\frac{1}{4}$  Corner to Section 6.  
Set - Brass Cap Mkd: T32S, R1W, WM  
C  $\frac{1}{4}$  S 6  
1970 O.P.E. 4906

Corner on East shoulder of State Highway #227.  
Mkd: 10" Doug. Fir BT bears N.31°E. 72.0 ft.  
16" Cedar BT bears S.80 $\frac{1}{2}$ °W. 74.0 ft.

53

Sec.Cor. to Secs. 31 & 32 only, T31-1W.  
Found - Brass Cap, U.S. G.L.O., properly marked, See Ren.#10.  
12" White Fir BT bears N.38°E. 51.5 ft.  
48" Cedar BT., Hown, scribe not visible bears N.4°W 16.0'  
Mkd: 26" D.Fir BT. bears N.25°W. 89.0 ft.

54

1/4 Corner for Secs. 17 and 16-  
Found - County Surveyors Brass cap mkd. T32S R1W 1/4 S17 S16 1968.  
Brass cap was found out of the ground, apparently moved during logging operations. The remains of the orig. BT's noted as found by Co. Surveyor's office in 1968 have also been destroyed. Ren. #31  
Reset - Brass cap at the corner point as determined from the bearing trees mkd. by the County Surveyor in 1968 as follows:  
a 14" now 15" Hemlock, not R. Fir, bears N.89°E., 65.1 ft., with scribing "14/ S16 CS BT" visible on unhealed blaze.  
A 12" now 14" Hemlock, not R.Fir, bears S.45°W., 26.8 ft. with scribing "1/4 S17 CS BT" visible on unhealed blze. We do not mark any new BT's.

55

John M. Powell  
Frank Jones & W. Penley  
August, 1968  
C. S. File No. 54/71

Bruce A. Shaner  
For: Ump.Nat'l.For.  
Oct. 31, 1970  
RM 2 - 21

Gary Langlitz  
P. Earle  
CS 56/51  
6/4/74

JAN. 1973

MARCH 71

122

10/31/70

RE-RENEWED CORNER NO.