

Douglas County Surveyor's Record of
Government Corners Renewed

32

T. S.

1 R.W.W.M.

MOKE-CHAPMAN CO., EUGENE, ORE. 21881

Raymond
Wytcherly

1/4 Cor. Secs. 17 & 18

125

- Found - 1980 brass cap per M 79-68 (Ren #98) from which
D.Fir 18" dia., bears (S.24°E., 26.0 ft.) face
healed over.
D.Fir 21" dia., bears (S.77°W., 17.9 ft.) face
healed over.
New BTs - Cedar 8" dia., bears N.74°E., 25.1 ft., scribed "¼
S 17 BT"
Cedar 6" dia., bears N.21°W., 8.7 ft., scribed "¼ S
18 BT"
Maple 7" dia., bears N.74°W., 18.7 ft., scribed "¼
S 18 BT"

For: Boise
Cascade Corp.

May 2004

1/4 Cor. Secs. 7 & 18

Ren # 11

126

- Found - 1963 County Brass cap, from which County BT's
Cedar 37" dia., bears S.1°E., (S.3°W., 17.5 ft.) face
healed over.
W.Fir 19" dia., (bears N.74°W., 51.2 ft.) face healed
over.
New BTs - Pine 9" dia., bears S.75°E., 7.91 ft. scribed "¼ S 18
BT"
Fir 6" dia., bears N.29°E., 17.56 ft. scribed "¼ S 7
BT"

M 144-49

Cor. Secs. 16, 17, 20, & 21

127

Burton W. Holt reestablished this corner in 1974 by double
proportioning. Holt corrected his 1974 reestablishment
in 1979. His 1974 survey had measurement errors.
He reset a brass cap and marked BTs. Mark F. Smalley,
renewed this corner in 2002 He marked new BTs. The
Jackson County Surveyor's Office recovered the original
¼ corner of sections 20 and 21, in 1984 (Jackson County
first re-establishment). This original corner is closer
to the section corner than the double proportioning
control used by Holt in 1979. Ken W. Hoffine, L.S. 2291,
received an opinion from BLM in 1998, that if the 1979
proportioned corner position was within a few feet of a
re-proportioning of the corner, BLM would accept the
1979 position (C.S. File No. 63/166 [T32S, R1W], Douglas
County). Surveyor Hoffine found the 1979 monument to be
3.6 feet from a re-proportioned position based on the
original ¼ corner of sections 20 and 21 and he accepted
the 1979 monument. I therefore accept Holt's 1979 sec.
corner monument as the location for the section corner.

Leonard Herzstein

USFS

8/8/2005

C.S. File 65/54-35

- Found - 3" dia iron pipe, firmly set, projecting 6" above
ground, with a 3" dia brass cap attached,
(Properly) mkd.
10" D.Fir snag, bears N.12°E. 9.9 ft (rec N.19°E.),
with a healed blaze. (Ren. #75)
A roothole bears S.72°W., 44.0 ft, with 16" D.Fir
alongside with no marks visible. (Ren. #75)
8" I.Cedar snag, bears N.84°W., 38.4 ft (rec.
N.79°W.), with scribe marks "S 17 BT" visible
on a partially healed blaze. (Ren. #75)
16" D.Fir cut stump, bears N.64½°E., 19.6 ft (rec.
N.69°E.), with no marks visible. (Ren. #118)
14" white fir, bears S.33°E. 10.7 ft (rec. S.30°E.)
with scribe marks "S21 BT" & a ¼" dia. brass
washer, stamped "LS 2354", visible on a
partially healed single blaze.
4" D.Fir, bears S.12°W., 14.9 ft (rec. S.16°W.),
with Roseburg Resources tag.
8" D.Fir, bears N.10°W., 20.1 ft, with scribe marks
"S17 BT" and a 3/4" diameter brass washer,
stamped "LS 2354", visible on a partially
healed single blaze.

cont. next page