

**Douglas County Surveyor's Record of
Government Corners Renewed**

T 32 T. S. R 2 R.W.W.M.

ROKE-CHAPMAN CO., EUGENE, ORE. 21891

74

$\frac{1}{4}$ Corner to Secs. 23 and 24
Found, firmly set, the 14x8x10 stone, projecting 3" and mkd. " $\frac{1}{4}$ " on West face. Recorded as 24x12x8" by C.L. Campbell in 1902.
I replaced said stone with a 1x36" G.I. pipe set 26" in the ground with a 2 $\frac{1}{2}$ " bronze disc mkd.: Jackson County 1975 T32S R2W $\frac{1}{4}$ S 23/24.
 Orig. BT's fd. as follows:
 A White Fir, 25" dia., with healed blaze, bears record, N.86°E. 29.7 ft. to center of tree.
 A White Fir, 30", with healed blazes, bears S.24°W., 28.38 ft. to center of tree. Record, S.33°W., 28.38 ft.
 I deposit orig. stone alongside as a memorial, mkd. new trees C.S. B.T. and take measurements to center of trees at lower blaze:
 White Fir, 13" bears S.6 $\frac{1}{2}$ °E., 19.15 ft.
 White Fir, 12", bears N.63 $\frac{1}{2}$ °W., 13.27 ft.
 Corner lies 40 ft. north of small draw, and about 1,000 ft. north of location marker on 30" dia., Fir snag, alongside road. 6/17/75

v. Frost, G. Cunningham, D. Gaylord
 Approved by Ed McGinty, Jackson County Surveyor
 June 17, 1975
 C.S. 58/101

75

$\frac{1}{4}$ Corner to Secs. 24 and 25.
 Fd., 13x10x10" stone (record, 18x12x10") firmly set, projecting 5" and mkd. " $\frac{1}{4}$ " on North face, as recorded by C.L. Campbell in 1902.
 I replace said stone with a 1x36" G.I. pipe set 30" in the ground with a 2 $\frac{1}{2}$ " bronze disc mkd.: Jackson County 1975, T32S R2W $\frac{1}{4}$ S 24 25.
 An orig. BT, now a sawed D.Fir stump, 28", containing reverse impression of scribed (partial) "T", bears record N.55°E., 25.08 ft.
 The SW BT now gone.
 Deposit orig. stone alongside corner as a memorial, mkd. the following trees C.S. B.T. and take measurements to center of trees at lower blaze:
 D. Fir, 14 ins. dia., bears N.48 $\frac{1}{4}$ °E., 28.37 ft.
 W. Fir, 5 ins. dia., bears S.80°W., 20.01 ft.
 Corner lies on South slope, about 100 ft. north of road. 6/17/75

76

$\frac{1}{4}$ Corner for Secs. 11 and 12.
 Found - The orig. corner monument, an 18" Yew tree, now a 10" snag, firmly in place at the corner point, with scribing "1/4 S12" visible on the unhealed East face. The west face has been burnt out, no marks remaining.
 A 26" Fir, now 36" D. Fir stump, well-healed.
 The orig. NW bearing tree is gone.
 We leave the orig. corner tree intact and mark the following new BT:
 A 24" D. Fir bears S.2°W., 51.7 ft. scribed "1/4 S11 CS BT" on a double blaze.
 An 11" Hemlock bears S.57°W., 68.1 ft. scribed "1/4 S11 CS BT" on a double blaze.
 At a point which bears South 4.0 ft. from the true corner, we set a reference monument as follows:
 A 1" x 30" Iron pipe, " in the ground, with brass cap attached
 Marked: Douglas Co. Surveyor Reference Monument
 1976

↑
 North 4.0 feet
 S11 | S12
 1/4
 T 32 S R 2 W

Gary L. Langlitz
 A. Vic Cangie
 Debbie L. Stewart
 6/29/76
 C.S. 59/15

Co. Surveyors

M. Lenora Ladig
 K. Cheney
 Pete L. Earle
 June 29, 1976
 C.S. 59/15

77

Section Corner for Secs. 14, 13, 23, 24.
 Found - A small mound of stone with a 1963 County surveyors Brass cap bent and on ground. Ren. #3
 An orig. 28" now 47" Fir snag bears S.33°W., 42.2 ft. with "R2W" visible in open blaze.
 An 8" now 16" Fir bears N.46°W., 45.4 ft. Tree alive with well-healed blaze.
 A 20" now 24" Fir bears N.25°W., 84.0 ft. Tree alive with healing blaze.
 Set - At true corner point: A new 1" x 36" I. Pipe with Brass cap stamped:
 "Douglas Co. Surveyor" T 32 S R 2 W
 1976 S 14 | S 13
 S 23 | S 24

RE-RENEWED SEE CORNER NO. #85

Note - Corner falls in edge of old dirt road. Placed Brass cap flush with ground. Placed sign post 4 ft. south of corner.
 New BT - A 8" Fir bears S.34°E., 26.0 ft. with "T32S R2W S24 CS BT" in double blaze. 6/29/76