

Douglas County Surveyor's Record of  
Government Corners Renewed

T 32

T. S. R 2

R. W. W. M.

MOKE-CHAPMAN CO., EUGENE, ORE. 21891

102

R. B. Kimberling  
D. Stewart  
Doug. Co. Surveyors  
Office  
No. 3, 1977  
C.S. 59/42

Corner #3 - Belle S. Mineral Survey.  
Found - A 22" now 32" Fir stump bears N.24 3/4°E., 24.3 ft. with scribe marks on cut out undercut and bottom portion of well healed blaze still intact on stump.  
A 6" now 18" D. Fir bears N.40 3/4°E., 36.6 ft. with a well healed blaze.  
Set - A 1" x 36" I.P. with brass cap set 10" above ground marked:  
"Douglas County Surveyor" T 32 S R 2 W  
1977 B.S. 3 | X X  
S.P. 3 | M.T. No.1-3  
New BT - An 18" D. Fir bears S.42°E., 15.1 ft. Double blazed and scribed "SP 3 MT No.1-3 BS 3 792 CS BT".  
Note - Corner is 30 ft. S.E. of mining road.

11/3/77

103

R. B. Kimberling  
P.L. Earle  
Doug. Co. Surveyors  
Office  
April, 1978  
C.S. 59/46

Corner #2-2 of Yellow King, Mineral Survey #792. Sec. 4  
Found - A rotted Fir post, 2 ft. long, 6 inches square, with scribing "YK" on one side. I dig and find rotted w/od in a 6 inch square hole, 2 ft. deep. I use as corner.  
A 22" now 30" Fir snag, 30 ft. high, bears N.21 1/2°W., 18.8 ft. is good to orig. face with a well healed single blaze.  
A 36" now 48" Fir stump bears S.74 1/2°W., 33.2 ft. (Rec. 32.1 ft. is good to orig. face), with a well healed single blaze.  
Set - A 1" x 36" I.P. with brass cap set 2" above ground and marked:  
"Douglas County Surveyor"  
YK No.  
2-2  
YK No.  
1-3  
New BT's-A 7" D. Fir bears N.2 1/2°E., 15.1 ft. with a crooked trunk. I drive a nail in a notch at the center of the crown, double blaze and scribe "YK No 1-3 YK no 2-2-792 CS BT".  
A 11" Hemlock bears S.83°W., 36.4 ft. I double blaze and scribe "YK No 1-3 YK No 2-2-792 CS BT".  
Corner is at West edge of clearcut.

4/3/78

104

Gary L. Langlitz, Doug. Co. Surveyors office  
Peter L. Earle and Frank C. Silagy  
April 6, 1978  
C.S. 59/46

Corner #1 - Belle S. Mineral Survey  
Found - No trace of original fir corner post.  
An Orig. 20" D. Fir, now a 30" snag, with scribing "S1 visible on previously opened blaze, bears N.16°W., 31.75 ft.  
An orig. 14" D. Fir, now an 18" snag with wellhealed single blaze bears N.16°E., 36.90 ft. (Rec. N.13°38'E., 36.90 ft.)  
Set - At a location which agrees with the previously described BTs WE SET a 1" x 30" I.P. 24" in the ground with brass cap attached marked:  
Douglas Co. Surveyor T 32 S  
1978 B S 1  
M S 792  
R 2 W  
New BT's-A 12" D. Fir scribed "BS 1 MS 792 CS BT" on a double blaze bears N.40°W., 9.2 ft.  
A 10" D. Fir, scribed "BS 1 MS 792 CS BT" on a double blaze, bears N.73 1/2°E., 27.4 ft.

4/6/78

105

Corner #4 - Belle S. Mineral Survey #792  
Found - No trace of original fir corner post.  
An orig. 7" D. Fir now a 14" snag with fragmented scribing "79" found on rotten face, bears N.67 1/2°E., 37.4 ft. (Rec. N.67°25'E., 29.00ft.)  
And an orig. 8" now 12" D. Fir alive and in good condition bears S.46°W., 14.90 ft. (Rec. S.46°08'W., 14.90 ft.) we open for verification and find good scribing "92".Growth rings date scribing at approx. 60 years.  
Set - At a location which agrees with the previously described bearing trees, We SET a 1" x 30" Iron pipe 26" in the ground with brass cap attached marked:  
Douglas Co Surveyor T 32 S  
1978 M S 792  
New BT - A 15" D. Fir scribed "BS 4 MS 792 CS BT" on a double blaze, S.3°E., 34.3 ft.  
Corner located approx 10 ft. west of a small creek.

B S 4  
R 2 W