

Douglas County Surveyor's Record of
Government Corners Renewed

T 32 T. S. R 2 R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 97101

C O N T. - - - - -

New BT - 11" Yew, S. 31°40'E., 32.0 ft. "T32S R2W S29 BT" #/32 113
6" Madrone, S. 6°52'W., 5.5 ft. "T32S R2W S30 BT"
Attached 3/4" brass washer marked "LS 866" to lower blaze of each new BT.

Center 1/4 Corner for Section 29. 114
Set - 2" x 30" Alum. pipe 28" into the ground and marked the 2 1/
attached brass cap: T32S R2W C 1/4 S29 PLS 866 1980.
Constructed mound of stones around the pipe.

New BTs - 10" D. Fir, S. 35°27'E., 9.4 ft. scribed "1/4 S29 BT" 113
21" Pine, N. 6°53'W., 14.7 ft. scribed "1/4 S29 BT".
Attached 3/4" brass washer marked "LS 866" to lower blaze of each new BT.

1/4 Corner for Sections 29 and 32. 115
Found - 12" x 12" x 5" stone with 1/4 on north side of stone.
Rotten stump hole, S. 25°30'E., 15.7 ft.
Rotten Hemlock stump, N. 26°W., 7.0 ft. "1/4 S" visible.
Set - 2" x 30" Alum. pipe with 2 1/2" Alum. cap stamped as T32S R2W
1/4 S29 S32 PLS 866 1980" at position of found stone.
Constructed mound of stones around pipe. Buried stone along side
pipe.

New BTs - 15" W. Fir, N. 83°30'E., 14.5 ft. scribed "1/4 S29 BT" 115
8" D. Fir, N. 3°45'W., 19.7 ft. scribed "1/4 S29 BT"
8" Chinquapin, S. 67°36'E., 11.7 ft. scribed "1/4 S32 BT"
Attached 3/4" brass washer marked "LS 866" to lower blaze of each new BT.

Center 1/4 Corner for Section 30. 116
Set - 2" x 30" Alum. pipe with 2 1/2" Alum. cap marked T32S R2W C 1/4
S 30 PLS 866 1980. Built cairn to cap
New BTs - 8" Hemlock, S. 12°35'W., 1j.9 ft. "C 1/4 S30 BT"
13" Hemlock, N. 33°51'E., 19.1 ft. "C 1/4 S30 BT"
Attached 3/4" brass washer marked "LS 866" to lower blaze of each new BT.

1/4 Corner for Sections 30 and 31. 117
Found - 54" D. Fir, N. 57°15'W., 12.8 ft. Good scar (60° magnetic)
34" Snag, S. 18°57'W., 23.4 ft. "1/4" visible.
Set - 2" x 30" Alum. pipe with 2 1/2" alum. cap at record magnetic
bearing and distance from closer bearing tree.
Cap marked: T32S R2W 1/4 S30 S31 PLS 866 1980.
Record and bearings from original survey do not result in single intersection
Built mound of stones around pipe.
New BT - 8" Hemlock, S. 25°55'W., 40.4 ft. "1/4 S31 BT".
Attached 3/4" brass washer marked "LS 866" to lower blaze of BT.

1/4 Corner for Section 30 only. (west) 118
Found - Original 12" x 12" x 12" stone, loosley set and broken in two,
no marks.
16" Madrone, N. 3°06'E., 27.3 ft. hollow.
50" snag, S. 15°36'W., 47.9 ft. Good scar.
Set - 2" x 30" Galv. I. P. with 2 1/2" brass cap marked T32S R2W
S30 PLS 866 1980, at location of stone.
New BTs - 6" Chinquapin, S. 47°04'E., 31.3 ft. scribed "1/4 S30 BT"
7" D. Fir, N. 14°46'E., 70.7 ft. scribed "1/4 S30 BT"
Attached 3/4" brass washer marked "LS 866" to lower blaze of each new BT.

Center 1/4 Corner for Section 1 119
Found - 2" diam. I.P. loose in the ground with brass cap marked:
T32S R2W W.M. C 1/4 S1 1970 OPE 4906", set by Shaner in 1970.
30" D. Fir, S. 67 1/2°E., 31.3 ft. with scribe marks "C 1/4
S1 BT" visible on partly healed blaze. See Ren. #63
Roothole, S. 23°W., (Rec. S. 20°W.) 118.0 ft. with 30" D. Fir stump
alongside, with scribe marks "C 1/4 S1 BT" visible on partly
healed blaze.
Set - RESET I.P. in orig. location, projecting 2" above, 3 ft. diam.
mound of stone.
New BT - 8" W. Fir, N. 47°E., 78.7 ft. marked "C 1/4 S1 CS BT"
Corner is 60 ft. east of F.S. Rd. #3216-A.

William Ruppert
For: U. S. Forest
Service
May 1980
M 84 - 5
C.S. 58/ 143 (n)

William Ruppert
For: U. S. Forest
Service
May 1980
M 84 - 6
C.S. 58/143 (n)

Leonard Herzstein,
Deputy, Doug. Co.
Surveyors Off. (U.S.
Forest Serv.)
A.Arciniega; R. Riley
Sept. 16, 1980
C.S. 61/11

9/16/80