

Douglas County Surveyor's Record of
Government Corners Renewed

T. 32 S. T. S. R. 3 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

39

1/4 Section Corner common to Sections 7 and 18.

During logging and slash burning, the Incense Cedar Bearing Tree was knocked over & face burned out. The 48" Sugar Pine bearing tree is now a stump. The 18" x 10" Stone is at its original location.

To replace the Incense Cedar, I scribed an 18" Doug. Fir Stump S. 82° 30' W. 9.3 feet from Original Stone.

John Madding, Prof. Eng.
by Bate Plywood Co.
November 1963
C. S. File No. 51/270

40

1/4 Section Corner Common to Sec. 18, T32-3W. & Sec. 13, T32-4W.

Area of this corner was logged and Orig. Stone lost. Found - Both Fir bearing trees, which are now stumps, with faces grown over. I chopped out both faces and exposed original scribing.

Replaced - Orig. Stone with Iron Pipe.

41

1/4 Cor. to Sec. 4, T32-3 & Sec. 33, T31-3W.

Found - I. Pipe at 1/4 Cor. & Scribed Stake, See Ren. #24.
11" D. Fir N. 1° E. 24.5 ft., shows scribed "BT" 1/4".
17" D. Fir S. 41° W. 11.0 ft., shows good scars.

Set - Brass Cap alongside I.P. for 1/4 Cor. Mkd:

1/4	S 33	T31S
	S 4	T32S

 R3W

Co. Surveyor's Office, 1966

FD OK 10/94 - M121-13

Sec. Cor. To Secs. 5 & 6, T32-3W. & Secs. 31 & 32, T31-3W.

Found - I. Pipe at Sec. Cor. See Ren. #10, T31-3W.
12" Fir Snag N. 46 1/2° E. 33.0 ft. (bear. S.B. N. 49° E.) scribed.
14" Fir Stump N. 66 1/2° W. 104.3 ft. (bear. S.B. W. 65° W. 140 ft.)
Scribing visible.

Orig. 36" Fir S. 22° E. 59.4 ft. (bear. S.B.S. 20° E.) bark scribe "BT" & other faint scribing visible.

No trace of S. W. BT.

Set - Brass Cap alongside I.P. at Cor. Mkd:

S 31	S 32	T31S
S 6	S 5	T32S

 R3W

County Surveyor's Office, 1965

New BT's: 15" Fir S. 12° E. 31.3 ft. scribed T32S R3W S5 CS BT.
14" Pine S. 35° W. 24.6 ft. scribed S 6 CS BT.
6" Pine N. 38° W. 17.0 ft. scribed S31 CS BT.
28" Fir N. 16° W. 94.0 ft. scribed T31S R3W S31 CS BT.

RE-RENEWED

#20342

John M. Powell
Frank Jones & Joe Brady
Dec. 1965 & Jan. 1966
C. S. File No. 52/63

43

1/4 Corner to Sec. 5, T32-3W & Sec. 32, T31-3W.

Found - I. Pipe for 1/4 Corner, See Ren. #6, T31-3W.
7" Chinq., now 10" S. 47° E. 9.2 ft., opened for scribe "BT".
10" Fir, now 14", N. 47 1/2° W. 33.9 ft., shows good scars.
(Distance should be 34.9 ft.)

Set - Brass Cap alongside I. Pipe & Mkd:

T 31 S
1/4 S 32 R
S 5 3
T 32 S W

County Surveyor's Office, 1966

New BT: 8" D. Fir S. 60° W. 33.0 ft. scribed 1/4 S5 CS BT.

FD CC. BT's
8/91 G. N. Y. G. R. W.
M114-7

44

Township Corner, T31-32S, Ranges 3 & 4W.

Found - 8" Thorn S. 77° E. 48.8 ft., scribe visible "S6 CS BT"
10" Hemlock, now 12", S. 33 1/2° W. 185.5 ft., scribe visible "BT"
24" Fir Stump N. 12° W. 142.0 ft.

I. Pipe at corner was out of ground, See Ren. #22

Set - Brass Cap at Twp. Cor. Mkd:

T 31 S
R S 36 S 31 R
4 S 1 S 6 3
W T 32 S. W

County Surveyor's Office, 1966

New BT's: 6" D. Fir N. 2° E. 120.3 ft. scribed S31 CS BT.
11" Hemlock S. 75° E. 62.9 ft. scribed T32S R3W S6 CS BT.

Note - Best way to reach this corner is to wade Cow Creek in the summertime.

FDOK
By R. Brown
4-93 M112-72