

Douglas County Surveyor's Record of  
Government Corners Renewed

T. 32 S. T. S. R. 3 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

79

$\frac{1}{4}$  Corner to Section 14, only.  
Found -  $\frac{3}{4}$ " Iron Pipe at  $\frac{1}{4}$  Corner & Stone mkd. " $\frac{1}{4}$ " on north side, Ren#18A.  
28" D.Fir stump, burnt, N.22°E. 15.8 ft.  
24" D.Fir Stump, N.22°W. 22.4 ft., scribe visible.  
26" D.Fir Stump S.22°W. 15.5 ft., bark scribed.  
Set - Brass Cap at Cor. Mkd: County Surveyor's T 32 S R 3 W  
Office S 14  
1969  $\frac{1}{4}$

New Bearing Objects, as follows:



$\frac{1}{4}$  Corner to Sections 22 and 23.  
Found - 16x10x8" Corner stone Mkd. " $\frac{1}{4}$ " on west face.  
Orig. 16", now 21" Cedar S.3°E. 15.8 ft., shows good face.  
Orig. 24", now 30" Y. Pine, S.15°W. 11.9 ft., shows good scribing.  
Set - Brass Cap at Cor. Mkd: County Surveyor's T 32 S R 3 W  
Office, 1969  $\frac{1}{4}$  S 22 | S 23  
This corner lies on a steep northwest slope. No New BT's needed.

80

$\frac{1}{4}$  Corner to Sections 23 and 26.  
Found 16x8x5" Corner Stone and 1" Iron Pipe, See Ren. #37.  
Orig. 30", now 42" Fir Stump. N.50°E. 50.0 ft., shows good face.  
Orig. 30", now 36" Cedar Stump, S.37°W. 22.0 ft., shows poor face.  
Markham's 10" Fir, now 10" snag, N.71°E. 9.0 ft., shows burnt scribing.  
DO NOT SET BRASS CAP  
New BT's: 28" R.Fir N.9°W. 111.8 ft. mkd: " $\frac{1}{4}$ " S23 CS BT.  
36" Cedar N.20°E. 115.8 ft. mkd: " $\frac{1}{4}$ " S23 CS BT.  
This corner lies in a logging unit and no BT's. in range in Section 26.  
Also road bears West 272 feet.

81

$\frac{1}{4}$  Corner to Sections 30 and 31.  
Found - 18x12x10" Stone, firmly set, mkd. " $\frac{1}{4}$ " on north face.  
Orig. 24" D.Fir, now stump, N.33°W. 12.5 ft., scribe visible #225  
Orig. 16" D.Fir, now stump, S.87°E. 34.3 ft.  
Set - Brass Cap at Cor. Mkd: County Surveyor's T 32 S R 3 W  
Office S 30  
1969 S 31 Doug. Co.  
Jack. Co.  
New BT's: 31" D.Fir N. 7° E. 58.9 ft. mkd: " $\frac{1}{4}$ " S30 CS BT".  
45" D.Fir N.81°E. 38.6 ft. mkd: " $\frac{1}{4}$ " S30 CS BT".  
No trees in Sec. 31 for good control, too far away in clear cut unt

82

$\frac{1}{4}$  Corner to Sections 29 and 32.  
Found - 18x14x6" Stone, firmly set, mkd: " $\frac{1}{4}$ " on north face.  
Orig. 36", now 44" D.Fir, N. 8° E. 15.8 ft., shows good scar.  
Orig. 30" D.Fir, now rotted stump, S.42°W. 11.2 ft., opened for scribing.  
Set - Brass Cap at Cor. Mkd: County Surveyor's T 32S R 3 W  
Office S 29  
1969 S 32 Doug. Co.  
Jack. Co.  
New BT: 6" D.Fir S. 50° E. 25.4 ft., mkd: " $\frac{1}{4}$ " S32 CS BT".

83

Section Corner to Sections 20 - 21 - 28 - 29.  
Found - Possible Corner Stone but no marks.  
Orig. 16" Chinquapin, now down, S.58°W. 13.0 ft., scribe visible.  
No trace of other BT's. or stone because of Road work.  
Set - Brass Cap at Cor. Mkd: County Surveyor's T 32 S R 3 W  
Office S 20 | S 21  
1969 S 29 | S 28  
New BT's: 40" D.Fir N.52°E. 104.8 ft. mkd: T32S R3W S21 CS BT.  
12" D.Fir N.55°W. 21.9 ft. mkd: T32S R3W S20 CS BT.  
16" D.Fir S.39°W. 41.7 ft. mkd: T32S R3W S29 CS BT.  
21" D.Fir S.55°E. 34.2 ft. mkd: T32S R3W S28 CS BT.  
This corner lies 40 ft. south of logging road.

84

7/17/69

John M. Powell  
Frank Jones & W. Penley  
July, 1969 C.S. File No. 54/91

RE-RENEWED, SEE CORNER NO. #185