

Douglas County Surveyor's Record of
Government Corners Renewed

T 32 T. S. R 3 R. W. W. M.

FOX-CHAPMAN CO., EUGENE, ORE. 97101

232

1/4 Corner for Section 25 only. (East)
Found - Flush with the ground, the orig. 6x8x16 granite stone mkd. with cross on top & "1/4" on West side by F. Mensch in 1912. Sawed fir stump, 60" diam., bears S177°W., 35.6 ft. to center, (Record 34.32 ft.)
Burned, sawed fir stump shell, 42" diam., containing reverse impression of scribe mks, in small segment of exposed (reverse) face, bears N.21°W., 54.9 ft. to center.(Rec. 55.44 ft.)
2" dia. I.P. projecting 10" with 3" diam. brass cap bears S.23°E., 1.15 ft. Ren. #51 C.S. 55/87
Set - Replace said stone with and deposit it alongside a 1x36 in. gal. I.P. set flush, with a 2 1/2 in. diam. Brass cap mkd. "T32S R3W R2W 1/4s 25 | C.S. 1988".
New BTs - 13" D. fir bears S.14 1/4°W., 55.94 ft.
8" Chinquapin bears S.55 3/4° E., 27.24 ft.
New BTs mkd. "CS" "BT" and take measurements to center of trees at lower blaze. Note: No other available trees in Section 25. All appear to be dead or dying. Corner lies near top of West sloping ridge about 300 ft., S. S.30°W. of end of logging road and an estimated 350 ft. West (downhill) of landing alongside USFS road.

Edward McGinty
Jackson Co. Surveyor
R. Frost and
S. Beecher Techs.
Sept. 29, 1988
C.S. 63/82

9/29/88

233

1/4 Corner on West line Section 30 of T.32-2
Found - Projecting 10" in ring of stone, the 2" diam., galv. I.P. with 2 1/2" diam. brass cap set on M 84 - 6. Ren. #199
An orig. BT mkd. by C Campbell in 1902, now a sawed madrone stump, 18" diam., containing partial scribed "3" & "BT" in rotted face bears N.3°E., 27.41 ft. to center of stump. (Record, N.1 1/2°E., 29.70 ft.)
An orig. BT, subsequently relegated to a "former bearing tree" on a 1913 GLO resurvey; now a burnt fir snag, 48" diam., containing old axe work, bears S.15 1/2°W., 47.63 ft. to center of tree. (Rec. S.17°W., 50.16 ft.)
The orig. stone could not be found, nor the yew bearing tree reported in 1913.
As all trees in the vicinity of the corner have been destroyed by recent (1987) forest fire; Set references as follows:
5/8" x 24" rebar set 22" in the ground with yellow plastic cap mkd. "Jackson C.S bears N.66°E., 8.19 ft.
5/8" x 24" rebar set 22" in the ground with yellow plastic cap mkd. "Jackson C.S. bears S.50°E., 6.45 ft. located at the base of a 48" diam. fir stump.
Corner lies on steep (65%) southwest slope, about 225 ft. southwest of rd. 11/3/88

Edward McGinty
Jackson County
Surveyor
R. Frost and
S. Beecher, Techs.
C.S 63/82
Nov. 3, 1988

234

1/4 Corner for Sections 35 and 36
Found - A 2" iron pipe with 3" brass cap in stone mound and marked as shown in diagram.
A 16" fir snag bears S.74°W., 42.5 ft. (vis. scribe)
A 8" hemlock, dead and down bears N.18°E., 14.6 ft.
A 40" D. fir stump bears S.67°E., 14.5 ft.
New BTs - A 40" D. fir stump bears S.60°E., 15.1 ft. (This stump was orig. BT)
A 36" D. fir stump bears N.72°W., 40.7 ft.
Bearings and distances are to 40d spike set in tip of stumps.
Note: No live BTs available due to Angel Fire.
Note: No record of previous renewal in Douglas County records)

Gerald Nygren
For; U.S.F.S.
July 1989
C.S. 63/85

235

1/4 Corner for Section 3; and 34 of T.31-3
Found - 1" iron pipe with a 2 1/2" brass cap 10" above ground, properly mkd. Ren. No. 47
Roothole N.39 1/2°E., 18.6 ft. 12" D. fir down and rotted. Ren. No. 13, T.31-3
Roothole S.71 1/2°E., 12.3 ft. 10" D. fir down and rotted. Ren. No. 13 of T.31-3
20" D. fir N.28°W., 23.8 ft. healed blazes. Ren. No. 47
10" W. fir S.71 1/2°W., 18.8 ft, (dead) healed blazes. Ren. No. 47
1 1/2" iron pipe alongside brass capped pipe. Ren. No. 13, T.31-3
New BT - 8" W. fir S.21°W., 13.9 ft. scribed "1/4 S 3 BT" nailed alum. washer mkd. "Artman RLS 2268" flush to BT face.
(See also corner report, Ren. No. 210)

James Artman
LS No. 2268
For: USFS
Dec. 1990
C.S. 63/124

12/90