

Douglas County Surveyor's Record of
Government Corners Renewed

32

T. S.

3

R. W. W. M.

RORE-CHAPMAN CO., EUGENE, ORE. 21861

Leonard Herzstein
USFS
Aug/Sept 2007
M154-54
C.S. 65/61-12A-E

1/4 Cor. Sec. 16 only

244

Found - 1 1/4" outside dia iron pipe firmly set,
projecting 14" above the ground, with a
2 1/2" dia brass cap (properly) marked
From which the BTs marked by Wenderoth in 1946
36" W.Fir, bears N.63°E., 58.4 ft, with healed
double blaze. Tree was rescribed by Powell
in 1969 (rec. 1946, N.62°55'E., 58.1 ft;
1969, 58.1 ft; 1975, N.64°E.)
12" yew, bears N.33 1/2°W., 76.7 ft, with
fragmentary scribe marks visible on
partially healed double blaze (rec. 1946,
N.33°43'W.; 1975, N.34°W., 76.6 ft).

Closing corner of section 20 & 21

245

Found - 1 1/2" outside dia. iron pipe, firmly set, projecting
8" above old roadbed, with a 2 1/2" dia brass cap
(properly) marked
From which the BTs marked by Wenderoth in 1945:
7" yew in Dismal Creek logjam, with USFS tags.
20" hemlock, bears S.79°W., 100.5 ft, with healed
double blaze (rec. 1945, S.80°45'W., 111.5 ft;
1969, S. 80 3/4°W., 111.5 ft).
And bearing tree marked by Powell in 1969: *Ren 73*
20" D.Fir, bears N.14°15'E., 7.9 ft, with healed
double blaze (rec. 1969, N.8°E., 7.3 ft; 1975,
N.8°E., 7.1 ft; 1980, N.14°E., 7.0 ft). This
tree is on the old roadbed.
And bearing trees marked by Clark in 1980: *Ren 183*
24" D.Fir, S.52°15'E., 17.9 ft, with healed double
blaze (rec. S.51°E., 17.7 ft). This tree is on
the old roadbed.
SW bearing tree has been washed away.
I bury the monument, a 32"x1" I.D. iron pipe,
flared at the base, 32" in the ground. Per the
BLM Manual, I add marks "AM" for Amended
Monument & marks "LS 2150" "2007" to the brass cap.

THE TRUE CLOSING CORNER OF SECTIONS 20 & 21 *See narrative CS 65/61-12A*

Old corner bears S.0°20'13"E., 16.22 ft. from true corner.
At the true intersection with the south line of section 16, I set
a 2 1/2" inside dia. iron pipe, 32" long, set 26" in the ground,
with a 3 ft dia mound of stone to the cap. A 3 1/4" attached brass
cap, pre-stamped "U.S.DEPT. OF AGRICULTURE FOREST
SERVICE" "UNLAWFUL TO DISTURB CADASTRAL SURVEY" is marked T32S R3W
S16/S20 S21 CC LS 2150 2007.

From which existing bearing trees:

24" D.fir, bears S.27°45' E., 30.7 ft, marked by Clark
in 1980 with healed double blaze. This tree is on
the old roadbed and the blaze faces N.52°W.
20" hemlock, bears S.70°15'W., 104.7 ft, marked by
Wenderoth in 1945 with healed double blaze.

And new accessories I mark:

3/8" rebar, 12" long, bears N.84°59'E., 26.52 ft,
driven flush with the old roadbed with red plastic
cap attached marked "CP USFS"
6 ft alum post, bears S.87°E, 3.1 ft, driven 1.5 ft
in the road ditch with Forest Service signs #54-2
"Property" & #54-9 "Land Survey Monument" attached
9" W.Fir, bears S.21°45'W., 32.1 ft, scribed "T32SR3W
S20 CC BT" on a single blaze. This tree is in the
road ditch.

The corner falls on the cut bank of the old Dismal Creek road,
approximately 6 ft from the west edge of the road. Bearings for
this establishment are from my traverse, rounded to the nearest
15 minutes, except for the rebar with red plastic cap which is
rounded to the nearest minute. Bearing trees are measured to the
center of the root crown. Tree diameters are at breast height.
New bearing trees have a 34 brass washer, stamped "LS 2150",
nailed to the "BT" portion of the blaze.