

Douglas County Surveyor's Record of
Government Corners Renewed

32 T. S. 4 R. W. W. M.

RE-RENEWED, SEE CORNER NO. 48 10

Set this corner from ~~an old B.T. (10")~~ which is N.68°E., 8 links. The other 8" Chinquapin S.65°W., 4 lks. is entirely destroyed. Set 4" x 4" Chinquapin post and marked a new B.T.

A 24" Fir N.48°W., 12 ft. marked $\frac{1}{4}$ S. 1, T.32S., (SAME #1)
R.4", C.S.B.T.

A. Boyer D.U.S.
Tit.
Red Shelleberger
Dick Dehrie
Sept. 23, 1940.

CLOSING CORNER TO SECTIONS 17 & 20 on West side. 11

Found stumps of both old B.T's

Drive $\frac{3}{4}$ " pipe for corner.

Scrib A 5" Chinquapin N. 87° 25' E 53.5 ft. 113

A 8" Chinquapin S.21° 47' E. 78.8 ft.

SECTION CORNER TO SECTIONS 5-6-31-32. cor. 5-6. 12

Find old B.T. and stake.

Drive 1" pipe for corner.

Scrib A 6" Chinquapin ~~####~~ N.44°26'W. 9.0 ft.

7" chinquapin n.45°00'E. 42.6 ft.

7" madrone S.47°00'E. 22.2 ft.

7" Madrone S.45°55'W. 26.5 ft. c.s. 40/246

$\frac{1}{4}$ CORNER BETWEEN SECTIONS 5 & 6. 13

Find one old B.T.

Drive 1" pipe for corner.

Scrib A. 30" Fir S.14°45' E. 46.8 ft. #140

A. 36" Fir S.47°15'W. 114.0 ft.

Section Corner to SECTIONS 18 -19-13-24. Sec. 18 & 19. 14

Find old B.T. badly rotted.

Drive $5\frac{7}{8}$ " bolt for corner.

Scrib A 8" Fir S.23°45' W. 13.2 ft. 51

A 6" chinquapin S.46°40'W. 25.0 ft.

A 6" Chinquapin N.51°16'W. 8.0 ft.

$\frac{1}{2}$ CORNER BETWEEN SECTIONS 13 & 18. West side Sec. 18. 15

Set halfway between corners.

Drive 1" bar for corner.

Scrib A 18" Fir S.16°00'E. 25.0 ft. 124

A 16" Fir N.76°15'W. 29.7 ft. - C.S. FILE # 39/158

$\frac{1}{4}$ COR. BETWEEN 17-20 16

Found an old B.T. and rescribe, set a new B. T., Drive $\frac{3}{4}$ " Pipe for cor.

28" Madrone bears S 79° 47' W 13.3 ft. dist. (old B. T.) c.s. 54/114

10" Fir bears S 47° 08' W 47.8 ft. dist. (new B. T.) O.K. J.M.P. MAY 5, 1970

CLOSING COR. SECS. 8- 17 WEST SIDE 17

Found both onld B. T. badly decayed. Drove 1" I. Pipe for the corner.

O. B. T. 12" Madrona bearing S 52° E 25.0 ft. dist.

16" Madrona bearing N 75° E 17.8 ft. dist.

New B. T. 30" fir bearing N 75° 48' E 36.0 ft. dist. FD OK 5-91

30" Fir bearing S 35° 05' E 29.0 ft. dist. M 113-10

CLOSING COR. TO SECS. 7- 18 EAST SIDE. 18

No sign of corner or B. T. set at intersection of line N-S & W

Drove 1" I. Pipe for the Cor. Scribed the following B. T.

4" Live Oak bearing N 9° 30' W 38.1 ft. dist.

4" live Oak bearing S 15° 57' W 59.2 ft. dist.

$\frac{1}{4}$ COR. WEST SIDE OF SEC. 17 19

Set 1" I. Pipe halfway between corners, scribed following B. T.

8" Chinquapin bearing S 43° 32' E 12.3 ft. dist.

30" Fir bearing N 39° 00' E 12.4 ft. dist.

May 6, 1970 - Found - 8" Chinq., now 13" S.42 $\frac{1}{2}$ °E. 12.3 ft. scb.mks.visible

30", now 33" D. Fir, N.69°E. 12.4 ft., tree opened & face painted.

Unrecorded $\frac{3}{4}$ " Iron Pipe at $\frac{1}{4}$ Corner.

9" Laurel N.62 $\frac{1}{2}$ °W. 10.6 ft., scribed "CS BT".

Trees for Section 17 tagged.

By J.M.Powell

C.S. 54/114

C.S. File 54/114

Geo. J. Wenderoth
Dep. Co. Surveyor.
October 1946.
Witness Clifford Worley.

c.s. 39/158

George J. Wenderoth - Deputy County Surv.

c.s. 44/119