

Douglas County Surveyor's Record of
Government Corners Renewed

32

T. S.

5

R. W. W. M.

Geo. J. Wenderoth
June, 1957
C.S. File No. 45/154

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

1/2 Corner Sections 22 & 23.

Car Axle: 16 inch W. Oak N 62°30'W 46.5.
18 inch Balm S 81°05'E 114.7.

Center 1/4 Corner of Section 23.

One Inch Iron Pipe: 32 inch Cedar N 2°W 66.4.
24 inch Fir N 76°15'W 51.8.

97A cor. ok. AUG. 1967 J.M.P. REN.

SEE PAGE FOLLOWING #44
NO. SKID EDPROT. PLC. #59

RE-RENEWED CORNER NO. #206

James W. Byron
Doug. Co. Rd. Dept.
Dec. 1956
Rd. Dr. 48/No. 36

1/4 Section Corner to Section 12, R5W, & Section 7, R4W, #218

Found - 2" X 2" X 12" I. Bar at base of Ewood Post, Check bearing & distance to 18" Fir as renewed by Stewart, 1922. BT has been opened several years ago, no scribing visible at this time. The N. W. BT. is gone. Ren # 84

Set Brass Cap alongside I. Bar marked S12/S7 T32S R4W County Surveyor's Office, 1956.

From Which: 12" Live Oak bears N.85°E. scribed 1/4 S7 CS BT.
I rescribed Stewart's N.56°E. 143.0 ft. BT. 1/4 S7 CS BT.

cor. ok. - AUG. 1967 J.M.P. Dec. 13, 1956

Section Corner Common to Section 11, 12, 13, & 14.

Found - 2" I. P. at Fence Corner & S.W. BT. as renewed by Geo. Wenderoth.

Blazed & Scribed: 10" R. Fir S12 CS BT N.65°E. 15.0 ft.

8" R. Fir S13 CS BT S.51°E. 57.4 ft.

20" W. O. S11 CS BT N.29°W. 29.0 ft. T32S R5W.

#158 110

REN # 58 & 59

RE-RENEWED CORNER NO. #158

James W. Byron, Deputy
Milo Godfrey
S. A. Bilow
Aug. 1958
For C. & D. Lumber Co.
C.S. File No. 49/112 M 12 - 51

Closing Corner to Sections 31 & 32.

Found - 1" Iron Pipe & BT's. as recorded by Wenderoth.

One of Theil's BT's. 10" Laurel N.38°W. 21.1 ft., has open face, good scribing "BT".

Set Brass Cap alongside 1" Iron Pipe Mkd: S31/S32 T32S R5W County Surveyor's Office 1958.

Note - I destroy all evidence of Standard Corner & BT's. S31/S32. I reset old corner Stone alongside Brass Cap. 6/5

New BT.: 5" W. Fir S.65°W. 11.6 ft. scribed CC S31 - 32 CS BT.

111

112

South 1/4 Corner for Section 31.

Orig. BT's not found at midpoint & on true line between Section Corner to East & Section Corner to West. See C.S. File No. 49/112.

Set Brass Cap at Corner Mkd: County Surveyor's Office, 1958

South 1/4 S31 T32S R5W.

New BT's: 10" R. Fir bears N.37°E. 3.5 ft. scribed 1/4 S31 CS BT.

10" Laurel " N.27 1/2°W. 33.2 ft. scribed 1/4 S31 CS BT.

(SAME AS #122)

Richard L. Templin, Jr.
Sept. 1958
C.S. File No. 42/389

Township Corner common to Twps. T32/R5; T32/R4; T31/R4; T31/R5.

Found - 3" Iron Pipe (unmarked)

24" Fir S.62 3/4°W. 39.5 ft. blaze healed.

50" Fir Stump S.74 1/2°E. 25.5 ft. scribing visible.

40" Fir Stump N.65°E. 20.0 ft. blaze healed.

16" Fir Stump N.16°W. 54.0 ft. blaze healed.

10" Fir N.79 3/4°E. 9.8 ft. scribing visible.

Scribed: 6" Cedar N.27°W. 16.6 ft. mkd. S36 RE3024 BT.

113

1/4 Sec. Cor. common to Secs. 1 T32/R5 & Secs. 6 T32/R4.

Found - 12" Fir N.54°W. 52 lks. scribing visible.

Set - 2" Iron Pipe Mkd. RE3024.

Scribed - 22" Fir S15 1/2°W. 44.0 ft. mkd. 1/4 S1 RE3024 BT.

#215

RE-RENEWED CORNER NO. #215

George J. Wenderoth, Deputy
2/5/59
C.S. # 49/92

Closing Corner to Sections 5 & 6, N. Corner T.32S. R.5W.

30" Fir S.39°E. 21.8 ft., Marks showing, Rescribe.

8" Yew S.63°W. 25.7 ft., Down, Scribe Plain

Mark 23" Cedar N.8°53'W. 36.0 ft. and Drive 1" Iron Pipe.

114-A

RE-RENEWED CORNER NO. #138