

Douglas County Surveyor's Record of
Government Corners Renewed

T. 32 S. T. S. R. 5 W. R.W.W.M.

ROKE-CHAPMAN CO., EUGENE, ORE. 21881

165

1/4 Corner to Sections 35 and 36.
Found - Unrecorded 1" Iron Pipe at Corner. SEE 45/54
6" Yew, now 10", N. 42° E. 13.9 ft., scribe visible "1/4 S36".
20" D.Fir S. 6° W. 14.5 ft., now out & covered with log deck.
Set - Brass Cap at 1/4 Cor. Mkd: County Surveyors T 32 S R 5 W
Office, 1967 S 35 | S 36
New BT's: 15" D.Fir N. 68° E. 60.0 ft. mkd. 1/4 S36 CS BT.
24" D.Fir S. 57° W. 57.4 ft. mkd. 1/4 S35 CS BT.
Note - This corner lies under log on east edge of old log deck. #195

166

Cl. Corner to Sections 35 and 36. F.D. OK 8/93 BENTZ 1993-0078
Found - 16", now 34" D.Fir, N. 21° E. 39.6 ft., Tree had been opened, scribe visible, "T32S". Fd. O.K. by L.P. SMITH MAY 14, 1982
40", now 45" Pine N. 81° W. 38.3 ft.
Set - Brass Cap at Cor. Mkd: County Surveyors T 32S R 5 W
Office 1967 C C S 35 | S 36 M 92-34
S 1
T 33S R 5 W
New BT's: 9" Laurel N. 31° W. 8.3 ft. mkd. CC T32S R5W S35 CS BT.
11" D.Fir N. 17° E. 8.3 ft. mkd. CC T32S R5W S36 CS BT.
Note - This corner lies east of A.P. (7), 1965 351.7 ft.

167

Cl. Corner to Sections 3 and 2., T33-5W.
Found - 6x8x6 corner stone mkd. (CC) See Ren. #2, T33-5W.
12", now 18" B. Fir, N. 70° E. 21.8 ft., shows bark scribing, "T32S R5W BT", plus a good original face.
12" D.Fir, now 16" Stump, S. 62° E. 22.4 ft., shows good bark scribe of "T33S R5W".
Set - Brass Cap at CC. Mkd: County Surveyors T 32 S R 5 W
(Set beside Corner Stone) Office C C
1967 S 3 | S 2
New BT's: 28" D.Fir S. 28° W. 31.9 ft. mkd. T33S R5W S3 CC CS BT.
22" Cedar S. 7° E. 49.0 ft. mkd. T33S R5W S2 CC CS BT.
Note - This corner lies in an old cutting unit on E. slope.

168

1/4 Corner to Sections 34 and 35, T32-5W, ONLY
Found - Corner Stone 8x10x4, no markings. See Ren. #7, T32-5W.
10", now 14" Fir, N. 23 1/2° E. 17.2 ft., shows good bark scribing, plus a good original face.
6" S. Pine, now 10" Snag, N. 51° W. 23.1 ft., shows good scribing.
No trace of S. W. BT.
Set - Brass Cap at 1/4 Cor. Mkd: County Surveyors T 32 S R 5 W
Office 1967 S 34 | S 35 NOT A CLOSING CORNER
C C
T 33 S R 5 W
New BT: 10" D. Fir N. 20° W. 24.0 ft. mkd. T32S R5W S34 CC CS BT.
Note - This corner was renewed by Irving, 1930, & he bark scribed N. E. Orig. BT. which has a good face.
This corner lies on steep east side of hill.

169

Closing Corner to Sections 32 & 33 only.
Found - 60" Fir Stump N. 59° E. 22.1 ft. mkd: CC T32S R5W S33 CS BT.
1" Axle at Corner set by Norman Price, 1953, See Map C.S. 41/184.
New BT's: 10" D. Fir N. 24° E. 20.6 ft. mkd. CC T32S R5W S33 CS BT.
12" D. Fir N. 1° W. 17.2 ft. mkd. CC T32S R5W S32 CS BT.

170

1/4 Corner to Sections 21 and 22.
Found - 5/8" Iron Rod at 1/4 Corner, & reference monuments, as follows:
Hub & Tack S. 21 1/2° W. 66.6 ft. & sight on 3 trunk Ash.
Sight on 16" W.Oak, S. 35° E. as noted.
Hub & Tack on this line, however not found.
Said corner falls at correct sta. of 194450 in St. Hwy. R/W.
New BT: 8" W. Oak S. 44 1/2° E. 85.5 ft. scribed 1/4 S22 CS BT..
Power Pole No. E2908 S. 20° W. 41.2 ft, PK Nail in base of pole.
Note - Corner lies North of R/W fence 32.0 ft. - SEE COR. No. 79

Jean M. Powell
and Joe Brady
August, 1967
C. S. File No. 53/52