

Douglas County Surveyor's Record of  
Government Corners Renewed

T. 32 S. T.S. R. 5 W. R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

For: H. Mehl, III  
Robert Dollar  
10/1/68  
C. S. File  
55/91

177  
1/4 Corner common to Sections 5 and 6.  
Found - G.L.O. Brass Cap & Iron Pipe removed by logging operation.  
Sawed Cedar Stump 30", S. 41\* E. 37 lks.  
Sawed Cedar Stump 32", N. 19\* W. 51 lks.  
6" Fir BT S. 88\* E. 38 1/2 lks., good condition.  
10" Fir BT N. 78\* W., 54 lks., good condition but face covered  
by log pile.  
Set - 1" x 42" Iron Rod 36" in the ground.  
Rescribed: 10" Fir above the log pile. The scribing read 1/4 S, R.S. 749 BT.

John M. Powell & Crew  
C.S. File  
No. 54/114

Section Corner to Secs. 12 & 13, R5W & Secs. 7 & 18, R4W.

Found - 1/2" I. Pipe at Corner, See Ren. #81 + 82  
9", now 13" Live Oak, N. 4° E. 105.8 ft., shows good scar.  
10", now 22" Fir, S. 60 1/2° E. 60.3 ft., shows good scar.  
Note - 13" Live Oak to be cut down.  
New BT: 6" D. Fir N. 2° E. 87.5 ft., mkd: T32S R4W S 7 CSBT".  
Power Pole N. 21 1/2° W. 24.0 ft., Pole No. E3457 (ABALO)

178  
FD 2 2nd (Jan 24, 1969)  
See C.S. 42/114  
For March 1984  
Corner Report  
L.E. MANNING,  
Doub. Cr.  
7/18/69  
Duo 1/2  
Pino 1/2

Section Corner to Secs. 24 & 25 only, T32-5W.

Found - 1" Iron Pipe at Section Corner, See Ren. #75.  
40" D. Fir South 40.1 ft., opened for scribe "3".  
Hit 2 Laurels (Orig. BT's.) for Bear. & Dist., rotted, possible shoots  
from old trees found, no scribing.  
New BT: 18" D. Fir N. 11 W. 58.9 ft. mkd: "T32S R4W S24 CS BT".  
6/17/70

179

1/4 Corner to Sec. 18, T 32-4W. and Sec 13, T32-5W.

Found - 1" Iron Rod at 1/4 Corner, See Ren. #15, T32-4W.  
Scribed Post "1/4 S 18 - 13"  
16" Fir, now stump, N. 76° W. 29.7 ft., scribe visible.  
No trace of S.E. BT, skid road.  
New BT: 13" D. Fir S. 48° W. 48.3 ft. mkd: "1/4 S13 CS BT".  
No other trees available.

#229

180

Location Tag on Fir Stump near old logging road bears west 80.0 ft.

6/17/70

1/4 Corner to Sections 8 and 9.

Considerable evidence of earlier search for the corner,  
however, the heartwood is very rotten on all larger Madrones, so it  
has been assumed the original corner is lost.

Set - 1" x 40" Iron rod set for the 1/4 corner, from which bears:  
a 22.5" D.B.H. Incense Cedar, N. 53° 24' E. 16.4 ft. mkd:  
1/4 Cor. Sec. 9, T32S, R5W, RS841, B.T.  
a 23.7" D.B.H. Douglas Fir N. 38° 25' W. 72.3 ft. mkd:  
1/4 S, Sec. 8, RS 841, B.T.

12/11/70

181

Center of Section 30. (Geo. Baker's Corner - Set 1947)

Set - 4" squared Oak Stake and a 1-1/2" x 7' galv. Iron  
Fence Post, set 24" in the ground. See C.S. 40/5

This corner found by R. M. Thompson, 1969, See C.S. 55/235

182

CE 1/16 Corner, Section 30.

Found - 1-1/2" Galv. Fence Post 2' high (no record) S. 1° 12' W.  
92.53 feet.

Monuments set by Baker & Wenderoth destroyed by Road Const.  
Found Log from Baker's B.T. (22" W. Fir, with scar) in debris pile,  
Stump not found.

I reset corner from Baker's record meas. to west & Wenderoth's  
record meas. to north.

Set - 1" I. Pipe, scribe #3683 BT on:  
12" W. Fir, S. 72° E. 31.6 ft.  
22" D. Fir, N. 30° E. 78.2 ft.

See Narrative on how this corner was set in C.S. File No. 55/235

183

Brandt, R. W.  
For: Robert  
Dollar Co.  
C.S. File  
No. 55/178

MARCH 71

Robert M. Thompson  
For: K. B. Robertson  
Sept. 16, 1969 (Filed 2/14/72)  
C.S. 55/235 Map M 44 - 37