

Douglas County Surveyor's Record of  
Government Corners Renewed

T. 32 T. S. R. 5 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

1/4 Corner of Sections 15 and 22.  
Corner renewed by proportionate measurements.  
Set - 1 1/2" Iron pipe at 1/4 Corner.

**RE-RENEWED, SEE CORNER NO. #205**  
184  
3/2/72

Gerald D. Riley  
March, 1972  
C.S. File 55/189

Angle Point Corner common to Sections 36, T32-5 & Sec. 31, T32-4.  
(Original Corner 30, 31, 25 and 36.)

185

Original Post (missing) from which a:

- 8" Fir, bears S.25°W., 18 lks. missing.
- 12" Fir, bears S.50°E., 73 lks.; missing (destroyed by Nicklin 1896), root holes in place.
- 6" Fir, bears N.66°E., 43 lks.; missing (destroyed by Nicklin 1896), covered by fresh logging slash.
- 12" Hemlock, bears N.40°W., 20 lks.; missing.
- 1896 Post (missing) by Carl S. Nicklin.
- 1900 Hemlock Post, (missing) by Oscar Thiel from which a:
  - 24" Fir, bears N.22°E., 86 lks.; now 16" x 10' rotten stub, in place, no face.
  - 40" Fir, bears S.83°E., 12 lks.; now 46" windfall snag, found back cast B and scribes SW.
  - 17" White Fir, (not recorded), bears N.56°W., 54.0 ft.; face opened scribes T32 S R5W S visible at 50 years.

Oregon State Board of Forestry  
Arnold Gibson  
Lloyd D. Smith  
May 30, 1972  
C.S. File 55/233

Set - 1 1/2" x 36" galv. iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY AP T32S S36 R5W T32S S31 R4W 1972 RS 359" in ground, and from which a:

- 11" Fir, bears N.44°E., 15.2 ft. to face; scribed T32S R4W S31 AP BT.
- 10" Fir, bears N.80°W., 20.1 ft. to face; scribed T32S R5W S36 AP BT RS 359.

Set - 4" x 4" x 72" white painted Cedar Post 2.5 ft. S.44°E., of corner pipe. Oregon State Forestry Department metal location post on 11" Fir N.44°E., 15.2 ft. Also poster on 10" Fir N.80°W., 20.1 ft.

5/30/72

+

1/4 Corner East Boundary Section 36, T32-5W.

186

Set- Ore.St.Bd. of Forestry 1 1/2"x36" Galv. I.P. with 3" Bronze Cap 34" in ground.

- 7" Fir S.22°W. 22.3 ft.
- 20" Fir N.65°W. 67.9 ft, Yellow Metal Location Poster, RS359.
- 12" Cedar S.38°E. 14.8 ft., YMLP.
- 4"x4"x72" White Painted Cedar Post N.56°E. 6.4 ft.

Ore.St.Bd. of Forestry  
Gibson, A.  
Map File  
M 47 - 2

Nov. 1972

1/4 Corner, Sec. 7, T32-5 and Sec. 12, T32-6

187

Found - Brass cap set by Douglas County Surveyor, 1959. Ren. #117  
Destroyed - Original BT's

The Robt. Dollar Co.  
Ronald Brandt  
11/72  
C.S. 55/257

- 44" I. Cedar, S.11°E., 33.3 ft.
- 36" I. Cedar, S.81°W., 16.8 ft.
- New BT's - 5.52" D.F., S.68°15'W., 31.05 ft. mkd. 1/4 S. 12 PS 841 BT.
- 9.55" D.F., N.06°40'E, 16.76 ft. mkd. 1/4 S 7 PS 841 BT.

Note - Bent pipe and brass cap removed, the pipe staightened and then re-set in its initial position. The tree measurements are at DBH and horizontal distance from monument to the center of the scribed face.

Southwest Corner D.L.C. #38

188

Found - 16" Ash, N.0°42'30"E., 54.2 ft. Ren. #70 Scribe visible.

Set - 5/8" Iron Rod

Bruce R. Roger  
Nov. 1972  
M 47 - 26  
Jan. 1973