

Douglas County Surveyor's Record of  
Government Corners Renewed

T 32 T. S. R 5 R. W. W. M.

KOIKE-CHAPMAN CO., EUGENE, ORE., 21881

- C O N T -

L.E. Monrean  
P.L. [redacted] rle  
M. T [redacted] kins  
Doug [redacted] Co. Surveyors  
Oct. [redacted], 1976 C.S. 59/24 3/77

Note - The corner point was established by using a face measurement to the 50" Maple. This measurement agreed closer to point witnessed by Powell's BT's.  
New BT - A 15" Ash, bears N.40 1/2°E., 150.7 ft. Tree blazed and scribed "WC 1/4 S 12 CS BT"  
A 14" Maple (scribed by Powell, 1967) bears N.7°30'W, 7-0 ft. (Bearing and distance recorded to center of base on both BT's.)  
10/18/76

197

Richard Templin  
For: Arrant  
Lbr. Co.  
April 8, 1977  
C.S. 58/93

South 1/4 corner for Sec. 33 of T31-5.  
(Set by single proportionment)  
Set - 5/8" x 30" Iron rod set 25" in the ground with a yellow plastic cap mkd. "TEMPLIN RE 3024"  
From which:  
A Ponderosa Pine 2" bears N.03°E., 14.5 ft. mkd. "1/4 X".  
A Chinquapin, 10" bears N.68°E., 60.1 ft. mkd. "1/4 S33 RE3024 BT".  
Note: This corner falls on the south edge of an old skid road in the middle of a large clear cut logging unit. No evidence of orig. cor. fd.

198

Burton W. Holt  
For: Sun Studs, Inc.  
Aug [redacted] t, 1977  
M 6 - 44

1/4 Corner for Sec. 34 only. South Boundary.  
Set - 1 1/2" I. P. with brass cap in mound of stone, cap mkd.  
T 32 S R 5 W  
1/4 S 34  
1977 L.S. 418  
From which:  
A 7" D. Fir bears N.68°E., 28.5 ft. mkd. 1/4 S34 BT.  
A 6" Cedar bears S.50°E., 34.5 ft. mkd. 1/4 S34 BT.

199

200

M65-44

1/4 Corner for Secs. 33 and 34.  
Set - 1 1/2" I.P. with brass cap marked: T 32 S R 5 W  
1/4  
S 33 S 34  
1977 L.S. 418  
From which:  
A 10" Fir bears N.28°W., 168.2 ft. mkd. 1/4 S 34 BT.  
No other trees available.

Aug. 1977

201

Preliminary Administrative survey  
Bureau of Land Management, Medford Dist.  
April 1979

Center 1/4 Corner for Sec. 13  
Set - 5/8" x 24" Rebar  
BT's - 13" D. Fir bears S.00 1/2°E., 10.7 ft.  
17" D. Fir bears N.64 3/4°W., 17.2 ft.

202

M78-43

1/4 Corner for Secs. 13 and 24  
Set - 5/8" x 24" Rebar  
BT's - 12" D. Fir bears N.03 1/4°E., 30.8 ft. See also Ren. #73  
13" D. Fir bears S.14 1/4°E., 31.0 ft.

April 1979

203

James Booth  
Jul 1979  
M 7 - 29 A & B

1/4 Corner for Secs. 14 and 23  
CONDITION REPORT ONLY  
Found - 3/4" Iron rod, N.0°23'11"W., 113.30 ft. See also Ren. #91  
22" Cedar, good scars S.61°35'E., 81.5 ft.  
16" Cedar good scars S.11°15'E., 115.65 ft.  
Harrow tooth not found, per M 35 - 79.

July 1979

204

L.E. Monrean  
Deputy - Doug. Co.  
Surveyors Office  
K. Reed - K. Mosely  
April 23, 1980  
C.S. 61/6

1/4 Corner for Sections 21 and 22  
Found - A 5/8" punched iron rod set by OSHD in 1966 at point as determined by Wenderoth to be the 1/4 cor. S21/S22 (1 in. iron pipe set by Wenderoth in 1955 Ren. #79, was replaced with OSHD iron rod in 1966.)  
An 8" W. Oak, now a 10", with well healed double blaze bears S.44 1/2°E., 85.5 ft. Ren. #170  
A power pole #E2908 T 135 with PK nail at base bears S.20°W., 41.2 ft. Ren. #170  
An unrecorded punched 5/8" iron rod bears N.23°W., 37.0 ft. said rod in centerline of Frontage Road.  
CONT. - - - - OVER - - - -

RE-RECORDED CORNER NO. #217