

**Douglas County Surveyor's Record of
Government Corners Renewed**

T 32

T. S. R 5

R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 97401

208

1/4
Center of Section 22

Found - A 5/8" x 30" iron rod firmly set and protruding 6" from ground.
(from B. Rogers survey # M 83 - 6)
A fence corner with fences running south and east bears 18.7 ft. from 5/8" iron rod.

Set - We reference out Rogers 5/8" iron rod and place in it's position, A DCSO brass cap on a 1 3/8" x 24" iron pipe. Top of cap is 5" above ground. Cap is marked: "Douglas County Surveyor" T32S C 1/4 S22 R5W 1980. We place Rogers 5/8" I.R. inside iron pipe to which brass cap is affixed.

New Accessories:
A 16" DBH Cedar bears S.23°E., 34.9 ft. scribed "C1/4 S22 CS BT" on a double blaze.
No other suitable trees available. Set bearing objects.
A 5/8" x 30" iron rod with an alum. cap marked "Douglas Co. Surveyor B.O. 1 1980", bears N.90°E., 30.0 ft.
A 5/8" x 30" iron rod with an alum. cap; marked "Douglas Co. Surveyor B.O. 2 1980" bears N.89° 3/4° W., 25.0 ft. Cap is 5" above ground.
B.O. 1 is 0.5 ft. north of fenceline running east. Cap is 4" above ground.

Stephen J. Fluase -
Doug. Co. Surveyors Off.
Shawn Means
June 24, 1980
C.S. 61/6

209

1/4 Corner for Section 2 only of T.33-5.

Found - A 1967 DCSO brass cap properly marked on a 1" I.P. firmly set and protruding 1.0 ft. from a rough pile of stone.
A 1 1/2" I.P. is found set flush with soil on the southeast edge of the brass caps iron pipe. Ren. #164, and #3 of T.33-5
An orig. 20" Fir now a decayed 24" x 54" high Fir stump bears due South 49.1 ft. 48.2 ft. to face. (Rec. South 48.2 ft.) opened blaze has scribed "S" visible
An orig. 20" Fir, now a decayed 29" x 53" high Fir stump bears S.51°E., 43.0 ft., 42.2 ft. to face. (Rec. S.58°E. 42.2 ft.) Upon partially opening a well healed blaze, the scribing "S2 CS" is found. A BLM BT tag on this stump records the bearing from tree to monument as N.52°W.
An 8" Madrone (Rec. Laurel) is still approx 8" diam. Madrone bears S.69°W., 15.6 ft. Tree has partially healed double blaze with scribing "S2 CS" visible.

Set - Because both face measurements from orig. BTs to brass cap and 1 1/2" I.P. agree with record and bearing to due South BT is found to agree, the monument position is accepted as good. More stones are added to rough pile around monument and the brass cap now protrudes 7" above this pile.

New BT's- A 10" D. Fir bears N.74°W., 35.0 ft. scribed "CC 1/4 S2 CS BT" on a double blaze.
A 10" D. Fir bears N.41 1/2°E., 71.9 ft. scribed "CC 1/4 S2 CS BT" on a double blaze.

New trees and due South OBT stump are tagged with DCSO BT tags. Cap is located 30.0 ft. South of BLM road 31-5-35.1.

Stephen Fluase
Deputy - Doug. Co. Surveyors Office
Bill Stewart
July 29, 1980
C.S. 61/11

7/29/80

Center 1/4 Corner for Section 35

FOUND REFERENCE ONLY.
Found - 1 1/2" I.P. 12" above ground. (See C.S. 45/54)
24" D. Fir bears N.35°W., 36.5 ft. (Rec. per C.S. 45/54, N.34°30"W 36.1 ft.)
18" D. Fir bears S.60°E., 32.9 ft. (Rec. S.60°18"E., 31.8 ft.)

Wade Rogers For:
Daniel Moriarty
Jan 16, 1981
M - 12
MB7-12

1/16/81

210

1/4 Corner for Secs. 11 and 14

Found - 1" I.P. with brass cap attached protruding 9" out of ground. Cap is marked "County Surveyors Office Sec. 11 1/4 + Cor Sec. 14 L.S. 5. Ren. #72
36" now 46" pine with well healed blaze, now down and soon to be cut up by landowner. Root hole bears S.83°E., 108.7 ft. Ren. #72
Search revealed no trace of any other BTs.

New Accessories:
14" W. Oak scribed "1/4 S14 CS BT" in double blaze bears S.14 1/2°W 163.6 ft.
17" pine scribed "1/4 S14 CS BT" in single blaze, S.78°E., 48.2 ft.

FILED OK 7/9/81
R. BEAUM M113-65

211

Gregory Quibell
John Powell,
Doug. Co. Surveyors Office
July 8, 1982
C.S. 61/36