

Douglas County Surveyor's Record of
Government Corners Renewed

T 32

T. S.

R 5

R. W. W. M.

KORE-CHAPMAN CO., EUGENE, ORE. 21881

219

CONT - - - -
Doug. Co. Surveyors
Office - Randall Smith
Party Chief; S.J. Flause,
Notekeeper.
Sept. 17, 1985
C.S. 62/29

(Sec. Cor. for 20, 21, 29 and 28)
Set - Monument position accepted as found.
New Accessories:
Bearing tree tags marked to indicate changes noted in accessories
found.
Monument lies 350 ft. + south from County Rd. #303 in a north-south
line and at the east edge of an open field.

9/17/85

Center East 1/16 Section 12.

220

REFERENCED NOTES ONLY

Doug. Co. Surveyors
Office
Randall Smith and
Stephen Flause
June 6, 1986
C.S. 59/30

Found - A bent loosely set 5/8" I.R. protrudes 6" above graveled
shoulder of Upper Cow Creek Rd. (Ren. #196, M64-34)
Original 1" I.P. per M3-9 not found.
24" now 26" dia. I. Cedar with a partially opened blaze "BT" visible
bears S.66°W., 26.7 ft. (Rec. S.66°W., 26.0 ft. is a face measur-
ment orig., S.66°W., 27.2 ft. per Ren. #196)
10" now 10" dia. I. Cedar with a partially healed blaze scribing
visible "1/16 CS BT" bears N.60°W., 38.3 ft. agrees with record
Original BT per M 3- 9

Accessories for reference:

Hub and tack bears S.56°E., 45.91 ft.

Hub and Tack bears S.13½°W., 75.67 ft.

Corner lies along edge of Upper Cow Creek Rd. Future road work and new
alignment will destroy corner and BTS.

RE-RENEWED, SEE CORNER NO. #224

Section Corner for Secs. 29, 30, 31 and 32.

221

Found - 1962 BLM 3½" brass cap, properly mkd., on a 2½" O.D. iron
pipe firmly set & protruding approx. 7" from ground.
Three inches southeast from BC is a 1½" dia. axle shaft
firmly set & protruding approx 1 ft. above ground. Ren #12
Axle shaft from Ren. #12 was found and reset with BLM brass
cap in 1964 dependent resurvey.

(BLM brass cap monument leans slightly north and east, distances and
bearings below are measured to plumb position:)

Orig. BT, a Fir, 16" diam. now a rotted 31" DBH 6 ft. tall fir
stump with a 9 and other partial scribing visible on a previously
opened blaze bears N.46°E., 16.5 ft. dist. as per record. No
evidence of other original bearing trees found.

(Above listed Fir only one found from Ren. #26 and 1901 resurvey.)

14" Cedar now a 24" DBH red cedar with a fully healed single
blaze bears N.20½°E., 72.7 ft. Ren. #12

7" fir now a 24" DBH D. fir with a fully healed single blaze bears
S.46½°E., 41.8 ft. as per record. Ren. #12

16" Ash now a 19" DBH Ash with scribing "32 5" visible in an
opened and partially rehealed single blaze bears S.24°W., 99.4
ft. distant as per record. Ren. #12

8" fir now a 28" DBH D. fir with a fully healed single blaze
bears S.88°W., 12.6 ft. (Rec. S.88°W., 12.0 ft. possible
face measurement.) Ren. #12

8" fir now a 17" DBH D. fir with a fully healed single blaze
bears N.29°E., 21.8 ft. dist. as per record. 1964 resurvey

14" Fir now a 21" DBH D. fir with a fully healed single
blaze bears S.15°E., 31.0 ft. dist. as per 1964 resurvey rec.

8" Fir now an 18" DBH D. fir with a fully healed single
blaze bears S.12°W., 25.1 ft. as per 1964 resurvey record.

15" Fir now a 27" DBH D. fir with a fully healed single blaze
bears N.33°W., 52.8 ft. as per 1964 resurvey record.

Monument is just east of a road running on west side of Woodford Creek and
is approx. 300 ft. south of a private residence.

See also M101 - 16 for Donald Bentz survey and corner report.

4/30/87

Douglas County
Surveyors Office
Stephen J. Flause
R. W. Smith
April 30, 1987
C.S. 62/45