

Douglas County Surveyor's Record of  
Government Corners Renewed

32 T. S. 6 R. W. W. M.

KOIKE-CHAPMAN CO., EUGENE, ORE., 21881

H. W. Lawrence  
Oct. 2, 1954.  
C. S. File No.  
42/80.

RE-RENEWED SEE CORNER NO. 43 47  
Witness corner to secs. 25, 26, 35 and 36.  
Place a stake 311 feet north of section corner to secs. 25, 26, 35 and  
36 for witness corner. Later, I drove a  $\frac{1}{2}$  inch iron rod at the  
stake, from which:  
A B. Oak, 29 inches in dia., bears S.58°W., 20.5 feet dist. marked  
WITNESS COR BT 1543.  
Actual section corner is in Cow Creek.

Geo. Wenderoth  
Aug., 1957  
C.S. File #  
49/8

9186 - FD OK PER BENZ, M102-39 48  
 $\frac{1}{4}$  Corner to Sections 24 & 25.  
Found -  $\frac{3}{4}$  inch iron pipe in pile of rocks. REN. #52  
Also 42 inch W. Oak S 71°24'W 232.8 feet, Bark scribed.  
I scribe 18 inch W. Oak N 25°37'E 124.6 feet. Do not know who put in this  
corner but is in line with Section Corner on East.

Wallace Owen  
Asst. Engineer  
For Robert Dollar  
Co.  
April 18, 1958  
C.S. File No. 42/354

49  
Corner Common to Sections 31 & 32 Only.  
Found - The Corner in poor condition from which:  
Orig. 24" Laurel N.15°E., 7 lks, now missing SAME AS 64-B  
Orig. 8" Laurel N.20°W., 30 lks, now a rotten stub.  
Set the Corner from the 8" Laurel using compass & chain.  
Drove a  $\frac{7}{8}$  inch rod & scribed:  
6" Laurel N.26°30'W. 18.1 ft. S31 RS 424 BT.  
5" Laurel N.28°30'E., 32.3 ft. S32 RS 424 BT.

James W. Byron  
M. Godfrey  
S. Bilow  
May 21, 1958  
C.S. File #49/91

50  
 $\frac{1}{4}$  Section Corner to Sections 33 & 34.  
Found -  $\frac{3}{4}$ " Iron Rod at Fence Corner & Both BT's. recorded by REN. #23  
B.B.I., 1949. Both are now stumps & each has good  
scribing & check bearing & distance.  
New BT's: 13" W.O. bears N.88 $\frac{1}{2}$ °W. 107.6 ft. scribed  $\frac{1}{4}$  S33 CS BT.  
7" W.O. bears N.83 $\frac{1}{2}$ °E. 52.2 ft. scribed  $\frac{1}{4}$  S34 CS BT.

H. W. Lawrence, Eng'r  
Wolf Creek  
Dec. 21, 1951  
C. S. File No. 40/397

51  
Section Corner to Secs. 23, 24, 25, & 26.  
Set at intersection of corner lines.  
Drove a  $\frac{3}{4}$ " Iron Pipe 30" long, 24" into the ground, from which:  
A Y. Pine 32" diam. bears N.56°E., 14.2 ft. mkd. S24 BT. 76  
A Y. Pine 12" diam. bears S.48°E., 3.6 ft. mkd. S25 BT.  
A B. Oak 13" diam. bears S.46°W., 15.0 ft. mkd. S26 BT.

James W. Byron, Deputy  
Milo Godfrey  
S. A. Bilow  
September, 1958  
C. S. File No. 49/91

52  
 $\frac{1}{4}$  Section Corner between 24 & 25.  
Drove a  $\frac{3}{4}$ " Pipe 30" long, 24" into the ground, from which:  
A B. Oak 26" diam. bears N.50°E., 108.9 ft. mkd.  $\frac{1}{4}$  S24 BT. 48  
A B. Oak 32" diam. bears S.71°W., 230.8 ft. mkd.  $\frac{1}{4}$  S25 BT.  
A Mound of Stone bears South at 11 ft. from this Set  $\frac{1}{4}$  Corner.

53  
Section Corner to Sections 25 & 36, T32S R6W, & Secs. 30 & 31, T32S R5W.  
Found - All BT's. & Corner Tree as recorded by Theil, 1901. All are  
now Snags. All check for bearings & distances. I find good  
scribing on all BT's, except S.E. BT. & it shows old &  
rotted face.

I pull the Corner Tree over & Set Brass Cap alongside Base Marked.  
RE-RENEWED SEE CORNER NO. 91A  
T32S County Surveyor's Office, 1958.  
New BT's: 25" Cedar bears N.14°W. 69.5 ft. scribed S25 T32S R6W CS BT.  
10" Cedar bears S.34°W. 72.1 ft. scribed S36 T32S R6W CS BT.  
8" R. Fir bears S.80°E. 57.0 ft. scribed S31 T32S R5W CS BT.  
8" R. Fir bears N.69°E. 80.1 ft. scribed S30 T32S R5W CS BT.