

Douglas County Surveyor's Record of  
Government Corners Renewed

32

T. S.

6

R. W. W. M.

KOME-CHAPMAN CO., EUGENE, ORE. 21881

James W. Byron, Deputy  
S. A. Bilow  
Milo Godfrey  
June 12, 1959  
C. S. File No. 49/91

Section Corner to Sections 8, 9, 16, & 17.

Found - Orig. 10", now 18" Fir S.38°E. 9.9 ft., shows good scar,  
I do not open.

Orig. 20", now 29" Fir N. 5°W. 54.1 ft., shows good bark  
scribing "T32 S B".

Orig. 8", now 10" Down Fir N.55°E. 44.9 ft., shows good  
scribing.

No trace of Orig. S. W. BT.

Set Brass Cap at Corner Mkd: County Surveyor's Office, 1959

S 8	S 9
S 17	S 16

T. 32 S. R.6 W.

FD. O.K.  
9/1967  
J.M.P.

New BT's; 9" R. Fir bears S.27 $\frac{1}{2}$ °W. 60.5 ft. scribed S17 T32S R6W CS BT.

6" Hemlock bears N.66°E. 16.8 ft. scribed S 9 CS BT.

6" Hemlock bears N.45°W. 12.4 ft. scribed S 8 CS BT.

58

$\frac{1}{4}$  Section Corner to Sec. 12, T32S R6W, & Sec. 7, T32S R5W.

Found - Both Orig. BT's., each BT. not completely grown over,  
show good scribing "BT".

Set Brass Cap at Corner Mkd: County Surveyor's Office, 1959

$\frac{1}{4}$ S12	S 7	T32S
R6W	R5W.	

Orig. BT's. are thus from corner:

44" Cedar bears S.11°E. 33.3 ft.

36" Cedar bears S.81°W. 16.8 ft.

I do not rescribe BT's.

RE-RENEWED SEE CORNER NO. 127

59

Section Corner to Sec. 12 & 13, T32S R6W. & Sec. 7 & 18, T32S R5W.

Find - 14", now 16" Fir Snag, shows old scar, center burned, not scribing  
found, N.43°W. 19.8 ft. (scribed by Theil)

Orig. 12", now 24" Cedar S.24°E. 22.4 ft., center burned out,  
does show good scribing "32 S T".

Orig. 9", now 18" Laurel N.34°E. 31.0 ft., shows good scribing,  
"32S R5W S".

No trace of Original N. W. BT.

Set Brass Cap at Corner Mkd: County Surveyor's Office, 1959

S12	S 7	T32S
R6W	S18	R5W

New BT's: 13" Fir bears N.32°E. 39.5 ft. scribed T32S R5W S 7 CS BT.

5" Laurel " N.52°W. 24.4 ft. scribed S12 CS BT.

12" R. Fir " S.58 $\frac{1}{2}$ °E. 51.6 ft. scribed S13 T32S R5W CS BT.

38" R. Fir " South 10.0 ft. scribed S13 T32S R6W.

60

$\frac{1}{4}$  Section Corner to Sections 13 & 24.

Found - Wenderoth's 12", now 24" Cedar, previously opened, shows good  
scribing "S4" S.60°30'E. 54.0 ft. *Ren #5*

10", now 20" Cedar, shows scar, checks for bearing & distance,  
N.50°20'E. 39.3 ft.

I do not find  $\frac{1}{2}$ " Iron Pipe set by Wenderoth, said to have  
been dozed out.

Set Brass Cap at Corner Mkd: County Surveyor's Office, 1959

$\frac{1}{4}$ S13	T32S R6W
S24	

New BT's: 20" Cedar bears N.64°E. 13.7 ft. scribed  $\frac{1}{4}$  S13 CS BT.

20" Cedar bears S.61°E. 55.4 ft. scribed  $\frac{1}{4}$  S24 CSBT.

61

Sec. Cor. to Secs. 5 & 6, T32S R6W. & Secs. 31 & 32, T31S R6W.

Set  $\frac{3}{4}$ " x 18" I. P. in Rk. Md. from Orig. BT's:

8" Fir N.17°W. 58.0 ft. (down, scribe visible.)

6" Fir N.17°E. 57.8 ft. (stump)

New BT's: 13" D.Fir N.81 $\frac{1}{2}$ °W. 36.0 feet.

9" D.Fir N. 8°E. 69.9 feet.

6" D.Fir S.59°E. 45.0 feet.

8" D.Fir S.1 $\frac{1}{2}$ °W. 68.7 feet.

62

Sec. Cor. To Secs. 4 & 5, T32S R6W. & Secs. 32 & 33, T31S R6W.

Ori.

James W. Byron, Deputy  
Milo Godfrey  
S. A. Bilow  
June 24, 1959  
C. S. File No. 49/91

Clifford M. Bryden  
For Roseburg Lumber Co.  
February 1960  
Map File M 17 - 34