

Douglas County Surveyor's Record of
Government Corners Renewed

32

T. S. 6

R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

63

Sec. Cor. to Secs. 5 & 4, T32S R6W, & Secs. 32 & 33, T31S R6W.
Orig. BT's.: 5" Laurel N.47°E. 21.1 feet.
18" Fir S.34°W. 21.7 feet.
Scribed BT's: 24" D.Fir N. 6°W. 35.0 feet.
14" D.Fir N.54°E. 87.3 feet.
16" D.Fir S.63°E. 38.0 feet.

Map File
M 17 - 34

91

64

Section Corner common to Secs. 1 & 12, T32S R6W. & Secs. 6 & 7, T32S R5W.
Orig. - Cedar post, missing, from which a: 8" Cedar bears N.24°E. 59 lks.;
now 8" rotten uproot, faced, no scribes.
5" Cedar bears S.63°E. 34 lks.; missing.
7" Cedar bears S.24°W. 56 lks.; now 12" uproot, scribed,
T32S R6W S12 visible.
8" Cedar bears N.36°W. 39 lks.; now 12" uproot, face burnt, orig.
axe work remaining on lower edge of face.
48" Line Tree 8.39 chains N., found 48" uproot in place.
Resurvey - July 1902: Cedar Post, missing, from which a: 40" Fir bears
S.40°E. 27 lks.; now 42", portion of face visible in bark.
Restored - Set 1 1/2" x 36" galv. I. P. with bronze cap Mkd: "Ore. St. Bd.
of Forestry T32S R5W R6W/ S1 S6 S7 S12 1960 RE 2311". 30" in gr.
9" Cedar bears N.26 1/2°E. 82.6 ft.; scribed T32SR5W S6 BT.
23" Cedar bears N.67°W. 27.4 ft.; scribed T32S R6W S1BT RE2311.
26" Cedar bears S.34°W. 47.1 ft.; scribed T32S R6W S12 BT.
42" Fir bears S.28°E. 12.0 ft.; scribed T32S R5W S7 BT.
Ore. St. Bd. of Forestry metal location poster on 42" Fir BT.
Set 4" x 4" x 60" White painted Cedar Post 2' NE of pipe.

Oregon St. Board of Forestry
Louis W. Amort
D. Baeger, Transitman
April 29, 1960
C. S. File No. 42/341

N
E
X
T

P
A
G
E

FO OK
8/90, M112-14

Corner Common to Sections 5 and 6, T33S R6W.
(South Boundary T32-6W)

64-A

Found the corner on the township line for the N. boundary of
T.33S., R.6W., common to Sections 5 and 6 in poor condition.
The Orig. BT's. were an 8" Laurel S.46°W. 63 links, now missing.
13" Fir bears S.68°E. 78 links, now a rotten stump.
Set the corner from the Fir, using compass and chain.
Drove a 1" iron rod and scribed a 12" Fir S.23°30'E., 38.8 ft. S5RS 424 BT.
42" Fir S. 51° W., 62.8 feet S6 RS 424 BT.

FO 1/84
R. THOMPSON
RM 3-61

Corner Common to Sections 31 and 32 only, T32S R6W.

64-B

Found - Corner in poor condition. (SAME AS 49)
Orig. BT's. were a 24" Laurel N.15°E. 7 lks., now missing.
8" Laurel N.20°W. 30 links, now a rotten stub.
Set - Corner from the 8" Laurel using compass and chain.
Drove a 7/8" rod and scribed a 6" Laurel N.26°30'W. 18.1 ft.,
S31 RS 424 BT.
5" Laurel N. 28° 30' E., 32.3 feet, S32 RS 424 BT.

Wallace Owen
For Robert Dollar Co.
April 18, 1958
C. S. File No. 42/354

RE-RENEWED SET CORNER NO. 143