

Douglas County Surveyor's Record of
Government Corners Renewed

T. 32 S. T. S. R. 6 W. R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

89A

T. H. Mehl, III
The Robert Dallar Co.
May 10, 1967
C.S. File No. 55/15

Sec. Cor. to Secs. 30 & 31, T32-6W. & Secs. 25 & 36, T32-7W.
Found: 3/4" I.P. by Wenderoth, See Ren. #8.
16" Alder S. 64° 30' E. 84.9 ft. by Wenderoth
Stump of 36" Fir BT. N. 24° W. 17 lks.
Bug-killed 48" Fir, S. 52° E. 14 lks.
4" Fir BT S. 57° W. 39 lks., destroyed by road construction.
12" Fir BT S. 64° 08' W. 39.0 ft., destroyed by road const.
Set - 1 1/2" x 30" Iron Pipe 18" into the ground & mkd. BT's:
4" Chinkapin N. 40° E. 23.8 ft., scribed "X" (at breast ht.) BT.
7" White Fir S. 78° E. 77.1 ft. scribed S 31 RS749 BT.
5" Ponderosa Pine S. 28 3/4° E., 19.1 ft. scribed S31 RS749 BT.
No BT's were available in the NW or SW quads. This is an area of
snags, culls & reproduction. After five years when this area is
relogged, BT's. can be securely established in these two quads.

90A

L. V. Swearingen
For Robert Dallar
C.S. File No. 51/68
1960-1963

Section Corner to Sections 4 - 3 - 10 - 9.
Found - Orig. 36" Fir S. 66° E. 47 lks., has been blown over & logged.
After the tree was cut into logs, the stump tipped back
upright leaving a stump approx. 10' tall. Orig. bark
scribing is plainly visible on this stump.
Orig. 50" Fir N. 45° W. 111 lks. is still standing but will
probably be cut in the near future. Orig. bark scribing
on this tree has practically disappeared.
Other two original BT's. are gone.
Marked the corner with a 7/8" x 30" Hexdrill Steel driven 20" in the
ground.
New BT's: 8" Incense Cedar S. 57° E. 66.5 ft. scribed S9, R4186 BT.
4" Tan Oak N. 29 1/2° E. 15.0 ft., scribed S3 R4186 BT.

May, 1963

John M. Powell & Crew
C.S. File No. 53/52

Fd. 8/90
M 110-48

Sec. Cor. to Secs. 25 & 36, T32-6W. & Secs. 30 & 31, T32-5W.
Found - County Surveyor's Brass Cap, properly marked in 1958, Ren. #53.
25", now 27" Cedar, N. 14° W. 69.5 ft., shows scribe.
10", now 12" Cedar, S. 34° W. 72.1 ft., shows scribe.
8", now 11" D. Fir N. 6° E. 80.1 ft., shows good face.
S.E. BT. was taken out by gas line. N69°E PER FIELD NOTES 8/90 OR
New BT: 18" D. Fir S. 87° E. 72.5 ft. mkd. T32S R5W S31 CS BT.
Note - Corner lies west edge of gas line.

July 25, 1967

91A

Sec. Cor. to Secs. 19 & 30, T32-5W. & Sec. 24 & 25, T32-6W.
Found - 1 1/2" Iron Pipe at section corner, ~~See Ren. #10, T32-5W.~~ REN #20
16" W.Oak S. 43° E. 37.6 ft., good scar.
16" Pine N. 78° E. 29.2 ft., pitched over face.
22" Pine Stump N. 75° W. 39.5 ft., scribe visible "BT".
No trace of S.W. BT., skid road.
New BT: 14" Laurel S. 87° W. 49.5 ft. mkd. T32S R6W S25 CS BT.
18" Laurel N. 82° W. 71.8 ft. mkd. T32S R6W S24 CS BT.
August, 1967

92A

Sec. Cor. to Secs. 18 & 19, T32-5W. & Sec. 13 & 24, T32-6W.
Found - 3/4" Iron Pipe, See Ren. #6.
Orig. 32" D.Fir, now Stob, N. 33° E., 19.8 ft., shows scribing
14" Cedar N. 68 1/2° E. 55.2 ft., scribed S18 with good BT face.
34" Cedar S. 12° W. 44.8 ft., scribed S24 with good BT face.
Set - Brass Cap at Cor. Mkd: County Surveyors T32S R S 13 S 18 R
Office 6 S 24 S 19 5
1967 W W
New BT's: 6" D.Fir N. 27° W. 7.0 ft. mkd. T32S R6W S13 CS BT.
6" Maple S. 34° W. 33.6 ft. mkd. T32S R6W S24 CS BT.
6" W.Fir S. 11° E. 25.4 ft. mkd. T32S R5W S19 CS BT.
August, 1967

93A

CORNER
FOR No. 94
← See OPPOSITE PAGE