

Douglas County Surveyor's Record of
Government Corners Renewed

T. 32 S. T. S. R. 6 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

100

Section Corner to Sections 27 - 28 - 33 - 34.
Found - 1 1/2" Iron Rod, firmly set in ground, See Ren. #22.
Iron Bar set by Cole in 1923. At that time all original trees cut & no new ones put in. Call of 4 chs. north of creek hits very good.
New BT's: 22" D. Fir S. 25° E. 13.8 ft. mkd. T32S R6W S34 CS BT.
9" Ash West 37.4 ft. mkd. T32S R6W S33 CS BT.
24" Pine North 160.0 ft. mkd. T32S R6W S27 CS BT.
Note - This corner lies in fence corner, fence running S. & W.

FD OK 1-91
M111-34

101

Section Corner to Sections 4 - 5 - 8 - 9.
Found - 36", now 42" Pine, N. 48° W. 23.1 ft., old scribe "R6", newer scribing in wood approx. 42 years ago, "T32 S BT".
No trace of other BT's.
16" D. Fir N. 58° E. 21.8 ft., unrecorded.
Set - Brass Cap at Corner from 42" Pine mkd: T 32 S R 6 W #135
County Surveyor's Office, 1967 S 5 S 4
S 8 S 9
New BT's: 5" Laurel S. 74° W. 24.2 ft. mkd. T32S R6W S8 CSBT.
6" Chinq. S. 52 1/2° E. 12.2 ft. mkd. T32S R6W S9 CS BT.

RE-RENEWED SEE CORNER NO. #135

John M. Powell
Frank Jones & Joe Brady
Sept. & Oct., 1967
C.S. File No. 54/53

102

Section Corner to Sections 32 and 33 only, T32-6W.
Found - 2" Iron Pipe not found, has been taken, See Ren. #13.
8", now 14" Apple, N. 81° E. 39.6 ft., scribe visible, "BT".
No trace of other Apple Tree.
Set --Brass Cap at Cor. Mkd: County Surveyor's T 32 S R 6 W #157
Office 1967 S 32 S 33
S 5
New Bearing Objects: FK Nail in base of pole (power) #52448 S. 87 1/2° W. 75.6'.
FK Nail in base of power pole #E2422 S. 87° E. 43.0 ft.
Note - This corner lies on north edge of road approx. 175 ft. west of Third Street. Corner confirmed by C. R. Birchfield.

103

1/4 Corner to Section 32 only, T32-6W.
Found - 6", now 8" D. Fir, N. 70° E. 10.2 ft., shows good scar.
28" D. Fir, now stump, N. 24° W. 31.8 ft., faint bark scribe, "BT".
1/2" I. Pipe at 1/4 corner, See Ren. #29.
New BT's: 10" D. Fir N. 84° W. 36.2 ft. mkd. 1/4 S32 CSBT.
Note - This corner lies 198 ft. west of 1/4 corner to Sec. 5 only, see below.

FD OK
8/90, M112-14

104

1/4 Corner to Section 5 only, T33-6W.
Found - 1/2" Eye Molt at 1/4 corner, See Ren. #1, T33-6W.
Orig. 18" Fir, now stump with rotten face, S. 25° E. 6.6 ft.
New BT's: 10" D. Fir S. 27° E. 13.2 ft. mkd. 1/4 S 5 CS BT.
14" D. Fir S. 52° W. 14.3 ft. mkd. 1/4 S 5 CS BT.
Note - This corner lies 198.0 ft. east of 1/4 corner Sec. 32 only, Ren. #103.

FD OK
1/8
R Thompson
RM 5-26

FD BC 'OK'
8/90-112-14

105

Section Corner to Sections 5 and 4 only, T33-6W.
Found - Wagon Skein at Section Corner, see Ren. #2, T33-6W.
30", now 39" Maple, S. 7 1/2° W. 62.0 ft., shows scar.
No trace of S. W. Tree, falls in street.
New BT" 14" Maple S. 83° W. 51.2 ft. mkd. T33S R6W S5 CS BT.
Note - This corner lies 198.0 ft. east of corner to secs. 32 & 33 only, Ren. #102, approx. 25 ft. east of Third Street.

106

1/4 Corner to Sections 7 and 8.
Found - Orig. 60" D. Fir, now 62" Windfall, S. 78° E. 31.7 ft., no scribing.
Orig. 46", now 48" D. Fir, N. 60° W. 7.9 ft., shows good bark scribe.
Set -Brass Cap at 1/4 Cor. Mkd: County Surveyor's T32S R6W
Office, 1967 1/4 S 7 S 8
New BT: 8" Yew S. 78° E. 15.1 ft. scribed "1/4 S8 CS BT".
Note - This corner lies 50.0 ft. west of draw.