

Douglas County Surveyor's Record of
Government Corners Renewed

T. 32 S. T. S. R. 6 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

H.W. Lawrence
Sept. 13, 1955
C.S. File No. 42/327

North 1/4 Corner Section 34.

Set - 1" galv. iron pipe 36" long driven 28" into ground, from which:
Bearing Trees: A R. Fir 24" diam. bears N.21°E. 41.0 ft. mkd. 1/4 S27 BT 1543.
A Madrone 5 1/2" diam. bears S.22°W. 29.0 ft. mkd. 1/4 S34 BT 1543.

*Fd 1/89
in Hull
M107-43*

122

South 1/4 Corner to Section 34.

Set - 1" galv. iron pipe 36" long driven 24" into ground, from which:
Bearing Trees: Ash 1' diam. bears N.4°E. 111.3 ft.
Ash 1' diam. bears N.51°W. 72.7 ft. mkd: 1/4 S34 BT 1543.

Note - Ran the north side of the section placing the 1/4 corner at mid point.
Ran the south side of the section placing the 1/4 corner at mid point.
J. Powell found the S 1/4 corner, 10/5/67, See C.S. File No. 54/53.

123

JAN. 1972

Robert M. Thompson
For: Mohr & A. Wells
Nov. 15, 1971
C.S. 55-236 M 44 - 38

South 1/4 Corner of Section 35.

Set - 1-1/2" I. Pipe scribe "1/4 S 35 BT" on:
14" D. Fir N. 77° E. 54.0 feet
14" D. Fir S. 11° W. 40.1 feet.

124

Closing Corner to Sections 34 & 35.

Corner not found.
Set 1-1/2" I. Pipe, scribe "CC S34 (& 35) BT" on:
14" D. Fir N. 78° W. 15.5 feet
10" D. Fir N. 82° E. 29.5 feet

125

Ronald A. Brandt
For: Chadwick
Map File
M 46 - 46

Center 1/4 Corner Section 32.

RE-SET BRASS CAP WIT. CENTER 1/4 CORNER of Sec. 32,
T.32S., R.6W., W.M. as per C.S. 47/42 *REN. #45*
(Reset 40.5 ft. N.0°54'30"E. from Center)
from which bears: 23.2" Inc. Cedar N.02°17'E. (North) 87.8 ft.
scribed.
Stump of 48" W.O. S.55°22'E. (S47°) 40.2 ft.,
overgrowth on destroyed scribing used to est.
face position.

FD. OK 8/90, M112-14

126

Aug. 1972

THE Robt. Dollar Co.
Ronald Brandt
11/72
C.S. 55/257

1/4 Corner, Sec. 7, T32-5 and Sec. 12, T32-6

Found - Brass cap set by Douglas County Surveyor, 1959. Ren. #59
Destroyed Orig. BT's - 44" I. Cedar, S.11°E., 33.3 ft.
36" I. Cedar, S.81°W., 16.8 ft.
New BT's - 5.52" D.F., S.68°15'W., 31.05 ft. mkd. 1/4 S. 12 PS 841 BT.
9.55" D.F., N.06°40'E., 16.76 ft. mkd. 1/4 S 7 PS 841 BT.

127

Note - Bent pipe and brass cap removed, the pipe straightened
and then re-set in its initial position. The tree
measurements are at DBH and horizontal distance from monument
to the center of the scribed face.

JAN. 1973

Max H. Hull
For: C.A. Root
C.S. 55/288
Map File
RM 2 - 43

N. W. Corner D. L. C. No. 38.

Found - 30" B. Oak with scribe S.41°31'E. 49.5 feet.
Set - 5/8" Iron Rod and
Scribed - 6" Cedar N. 31°E. 7.92 feet.
12" Fir N. 79°W. 12.95 feet.

128

April, 1973

R.A. Brandt
For: Robert
Dollar
Co.
C.S. 55/294
M 49 - 21
Jan-May, 1973

N. 1/4, Sec. 2, (33-6)

Set 1"x36" I. Rod 4" high from which bears
14" 1" D. Fir, S 25°44'W. 18.68 ft. mkd. 1/4 S 2 PS841 B.T.
13.4" D. Fir, S 44°39'E. 28.50 ft. mkd. 1/4 S 2 PS841 B.T.
Also an old D. Fir Stump showing evidence of early corner search
bears S.28°23'E. 44.0' from the corner as set, however, compared
with the orig. BT. (bearing from the corner a 20" D. Fir S.21°E.,
26.4') the corner would be placed 11.45' East and 14.06' South
of the corner as established.

RENEWED CORNER NO. #177

129

May, 1973