

Douglas County Surveyor's Record of
Government Corners Renewed

T 32 T. S. R 6 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

151

1/4 Corner for Secs. 14 and 23.

Found - The stump & lower bole of an orig. BT although void of visible scribing, it has been substantiated as an orig. tree by the following information:
The BT involved is that "10 inch, D.F., S.01°W., 24 lks. Mkd. 1/4 S BT" of the orig. 1881 government survey. The stump & lower bole involved are the result of logging on the J.W. Payne property in the late 1950's. In felling the tree the back cut at the stump passes through overgrowth wood on an old face with fire evidence on the face (apparently occurring soon after face placement prior to wood overgrowth.). Thorough searching & examination of growth rings both at the stump & at a short long-butt which had been bucked off to remove butt rot indicated tree size at time of face placement was 10" with the direction normal to the face being N.01°E. Corner placement using this stump positions the monument N.61°W., 15.2 ft. or West 13.3 ft. & North 7.4 ft. of the single-proportion point. Evidence of the orig. BT in Sec. 14 (8" D.F., N.08°W., 55 lks.) was not found.

Set - 1" x 36" I.R. 4" high from which bears
8" Tan Oak, S.05°E., 43.95 ft. mkd. 1/4 S 23 PS 841 BT.
11" Bigleaf Maple, N.29°30'E., 30.11 ft. mkd. 1/4 S 14 PS 841 BT.
Old D.F. stump, S.01°W., 15.84 ft. (with remains of face place when tree 10" diameter).

3/1/78

Center 1/4 corner *sec. 23*

152

Set - 1" x 36" I.R. 4" high from which bears:
12" Copco Pole No. E3292, S.48°30'E., 51.0 ft. mkd. C 1/4 S 23 PS 841 RP
1" I.R. N.00°40'30"W., 528.00 ft.
1" I.R. S.89°15'44" W., 495.00 ft.

FD OK PER TEMPLU
1990-0006 2/90

153

1/4 Corner for Secs. 23 and 24.

Found - 1" I.P. apparently illplaced by a Gross Error in C.S. 53/21
See Ren. #75

From which bears

14" D. Fir, N.13°30'E., 29.4 ft. overgrowth present.
18" I.C. S.41°30'W., 37.3 ft. scribe visible, nearly overgrown.
3/4" I.P., N.00°37'16"W., 817.30 ft.
1/2" I.P. N.00°37'39" W., 1029.87 ft.

Set - 1" x 36" I.R. 4" high, in position at the midpoint of the east line, from which bears:
1" I.P/ 6" high N.02°52'25" W., 58.04 ft. set by Wenderoth, witnessed by his 2 BT's & intended to replace the lost 1/4 corner; unacceptably out-of-place.
10" D.F., S.75°E., 33.93 ft. mkd. 1/4 S 24 PS 841 BT.
13" D.F., S.22°W., 21.00 ft. mkd. 1/4 S 23 PS 841 BT.
D.F. rotten stumps N.80°E., 10.0 ft. and S.88° E., 11.0 ft. either of which could be the orig. BT. (8" D.F. N.85°E., 9.9 ft.) based on stump age, & positions, however, deterioration prevented the finding of a face or scribing or overgrowth.

Six man-days expended in orig. corner search. See map No. M 69 - 3 for call comparisons.

154

Center 1/4 Corner for Section 19

Set - Oregon State Board of Forestry 1 1/2" x 36" Galv. I. P. with 3" bronze cap 32" in ground.
BT's - 14" Fir bears N.86°E., 5.9 ft. RS 1101 and yellow metal location poster.
14" Fir bears S.15°W., 23.6 ft. RS 1101 & yellow metal location poster.
4" x 4" x 72" white painted cedar post bears S.19 1/2°E., 1.7 ft.

5/25/78

Lloyd D. Smith
For: Oregon State
Bd. of Forestry
May 25, 1978

M 71 - 79

Ronald A. Brandt, P.S. 841
For: Robert Dollar Company
March 1, 1978
M 69 - 3 C.S. 58/125