

**Douglas County Surveyor's Record of
Government Corners Renewed**

T 32 T. S. R 6 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 97501

155

Gary D. Smith
for: State of Oregon
Dept. of Forestry
July 25, 1978
71 - 79

Section Corner for Secs. 18, 17, 19 and 20.
Set - Oregon State Board of Forestry 1 1/2" x 36" Galv. I.P. with
3" Bronze cap 26" in ground in mound of rock.
BT's - 15" Fir bears N.07 1/2°W., 10.0 ft. RS 1101.
10" Fir bears S.65°W., 40.7 ft.
14" Fir bears S.20°E., 6.2 ft. with yellow metal location poster.
17" Fir bears N.49°E., 55.4 ft.
4" x 4" 72" White painted cedar post bears S.42°W., 3.8 ft.

156

1/4 Corner for Secs. 19 and 20.
Set - 12" Fir corner tree with yellow metal location poster.
BT's - 12" Fir bears S.35°E., 36.7 ft. RS 1101 with yellow metal location
poster.
16" Fir bears S.50 1/2°W., 39.8 ft.
4" x 4" x 72" White painted cedar post bears N.49°E., 4.1 ft.
5/25/78

1-79

157

Section corner for Secs. 32 and 33 only.
Found - A 1" iron pipe with brass cap attached at location determined by
Eppstein. Cap set by Powell marked "County Surveyors Office"
T32S R6W S32 S33 S5 T33S 1967. Ren. #102
An apple tree, 8" now 15" with fragmentary scribing visible bears
N.81°E., 39.0 ft. (Rec. N.81°E., 39.6 ft.) Ren. #13
Power poles referred to in ren. #102 have been replaced.

No new monument set.
New Accessories: A 27" man hole collar marked "B.O." on south edge, center
punch bears S.63°W., 23.84 ft. (Note: bearing and distance to
center punch in "B.O." mark.)
5/22/79

Section corner common for Sec. 31; and Sec. 36 of T.32-7 only. **158**

Set - 1" x 30" I. rod, flush
From which:
3" dwarf apple bears S.66°30'E., 4.41 ft.
4" peach, bears S.82°W., 14.50 ft. measured to trunk centers, not
marked.

Fenceline 25 ft. north. An 1855 closing-corner re-set using single
proportion measure.

7/79

Section corner common for Sec. 3 & 4; and Secs. 33 & 34, T.31S. R.6W.

Set: Brass Cap stamped:

33	34
4	3

 1980 RLS# 1005 **159**

BT's: A 16" Fir bears S.26° E., 4.7 ft. scribed "S3 T32 R6W"
A 12" Fir bears N.54° E., 8.7 ft. scribed "S34 T31 R6W"
A 14" Fir bears N.68° W., 8.1 ft. scribed "S33 T31 R6W"
A 12" Fir bears S.42° W., 14.9 ft. scribed "S4 T32 R6W"

160

1/4 corner common for Sec. 3; and Sec. 34 of T.31S. R.6W.

Set: 5/8" Iron Rod with cap
BT's: A 12" Douglas Fir bears N.22°E., 8.0 ft. scribed "1/4 S34 BT"
A 10" Douglas Fir bears S.62°E., 19.7 ft. scribed "1/4 S3 BT"

161

Section corner for Secs. 29, 28, 32 and 33.
Found - A cedar post approx 12" diam. & 8 ft. long. Post has rotted off
approx. 2" below ground level. See Ren. #27. The upper 5 ft. of
said post has fence wires attached from fences running south
and east; this section of post has rolled downhill and lies
6 ft. southeast of the above mentioned post remains in the ground.
An orig. 5" fir, now a 22" DBH D. fir bears S.56°E., 28.4 ft.
Tree has an opened face but no scribe marks are observed. Tree
is opened further to reveal orig. axe marks & a scribed "T"
(age verified by growth ring count)
Possible but inconclusive evidence of a stump hole is found at the
record bearing & distance of the orig. northwest bearing tree.
No evidence of the other orig. bearing trees is found.

Ronald Brandt LS#841
For: Ronald & Linda
Brandt
July 1979
M 78 - 48

Ronald A. Quimby LS#1654
For: Roseburg Lumber Co.
March 1980
M 79 - 25

S.J. Flause, Deputy
Doug. Co. Surveyors
Office
Terrie Plouff
Karen Mosely
April 6, 1981
C.S. 61/19