

Douglas County Surveyor's Record of  
Government Corners Renewed

T 32

T. S.

R 6

R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 97501

Donald Bentz  
L.S. #839  
For: Doug Robertson  
August 1990  
M 110 - 48

Center 1/4 Corner for Section 36  
Set - 5/8" x 30" iron rod with cap in 28" log. (12" exposed).  
Established BTs:  
13" D. fir S.34°W., 8.5 ft.  
9" madrone S.43°E., 31.0 ft.  
6" maple S.88°E., 31.7 ft.  
9" D. fir N.38°W., 14.9 ft.

180

8/90

Max Hull  
L.S. # 901  
For: Gregory Forest  
products  
August 1990  
M 112 - 14  
C.S. File 63 / 115

Section Corner for 31 & 32 only  
Found - 13" dia. madrone N.26½°W., 18.1 ft. blaze healed  
12" dia. madrone N.28½°E., 32.3 ft. blaze healed Ren. # 143  
Set - 5/8" I.R. w/cap mkd. "Hull R.S.901" I.R. 30" length  
New BTs - 10" D. fir S.58°E., 34.0 ft., scribed  
8" D. fir S. 23°W., 24.7 ft., scribed

181

8/90

Richard Templin  
LS. 2359  
For: Medford Corp.  
Jan. 1991  
M111 - 34  
CS 63/130

Center 1/4 Corner for Section 28  
Set - 5/8" X 30" Rebar with yellow plastic cap marked "Templin 2359"  
BT's - 12" D fir N.6°E., 4.4 ft. scribed "C1/4S28" "BT"  
24" D fir S.42°E., 17.6 ft. scribed "C1/4S28" "BT"  
8" D fir S.22°W., 4.4 ft. scribed "C1/4S28" "BT"  
10" D fir N.74°E., 323 ft. scribed "C1/4S28" "BT"

182

1/91

Douglas County  
Surveyors Office  
Randall Smith  
Stephen Flause  
January 7, 1992  
C.S. File 64/23

Township Corner - NE Corner Section 1  
Found - 1966 Oreg. State Board of Forestry 3" brass cap on a 1½"  
O.D. Iron pipe protruding 7" above ground. Ren. No. 88  
1" O.D. Iron pipe protrudes 5" above ground Ren. No. 70A  
1" I.P. bears West 13.3 ft. from OSBF BC/IP (agrees w/ Ren.No. 88  
55" now 58" dia. D.Fir with a fully healed single blaze on the  
NW trunk and bark scribed "LS 359" on North trunk, bears  
S.15°W., 13.8 ft. (Rec. S.15°W., 11.5 ft. dist. to bark  
scribing. Ren. No. 88  
4" now 9" dia. 1½ ft. high Hemlock stump with a fully healed blaze,  
bears S.58°E., 28.3 ft. (agrees w/rec)  
4" now 11" dia. D.Fir with a fully healed single blaze, bears  
N.9°E., 19.0 ft. (agrees w/record)  
6" now 12" dia. 1½ ft. high D.Fir stump with a fully healed  
single blaze, bears N.86°W., 54.5 ft. (agrees w/rec)  
New BTs (Go to corner position as determined by OSBF in Ren. No. 88)  
8" dia. Hemlock double blazed and scribed "T31S F6W S36 CS BT" bears  
N.43°W., 12.1 ft.  
7" dia. Hemlock double blazed and scribed "T31S R5W S31 CS BT"  
bears N.75°E., 16.6 ft.  
Corner lies on a steep North facing slope. (See C.S. File 49/92 for  
correspondance on the establishment of corner position)

183

1/7/92

184

Douglas County  
Surveyors Office  
Randall Smith  
Stephen Flause  
January 16, 1992  
C.S. 64/23

1/4 Corner for Sections 28 and 29  
Found - 1976 3½" dia. brass cap on a 2½" O.D. iron pipe, protruding  
5" above ground. (BLM)  
Orig. Cedar, S.66°W., 37.6 ft., now gone.  
36" now 36" dia. 12 ft. high burnt and rotting D.Fir snag,  
No scribing or blazes visible, bears S.38°E., 11.9 ft. (agrees  
with record.) Ren. No. 41  
6" now 9" dia. 6 ft. high Tan Oak stump with a fully healed  
single blaze, bears S.28°W., 33.3 ft. Ren. No. 41  
12" now 13" dia. 5 ft high D.Fir stump with a fully healed single  
blaze bears S.65°W., 76.6 ft. 1980 BLM BT.  
10" now 13" dia. dead D.Fir with a fully healed single blaze bears  
N.13½°E., 49.4 ft. (Rec. N.13½°E., 57 lks., 1980 BLM) 57 ft. at  
30° might be where the distance problem came from, (an unreduced  
slope distance in ft.)  
New BTs - 3" dia. D.Fir double blazed and scribed "X BT" bears N.74°E., 38.0  
to center of trunk at upper blaze.  
10" dia. Tan Oak bark scribed "¼ S28 CS BT" bears S.89½°E., 32.0 ft  
Corner lies on a North-South cut line on a Southeast slope.

1/16/92

END