

Douglas County Surveyor's Record of  
Government Corners Renewed

T 32

T.S.

R 7

R.W.W.M.

KORE-CHAPMAN CO., EUGENE, ORE. 97101

115

1/4 Corner for Sec. 4 and Sec. 33 of T.31-7.

Found - 1966 County brass cap, properly mkd. on a 1" iron pipe, bent, loosely set and disturbed during logging activity. Ren. #39

I reset the monument from the original bearing trees:

Kristian DeGroot  
LS 1941  
For: Allen & Gibbons  
Logging, Canyonville  
November 28, 1983  
C.S. 58/229

A 36" D. fir stump bears S.67 1/2°E., 30.4 ft. with scribe marks "S4" visible on an opened blaze, (Rec. S.70°E., 29.7 ft.)  
A 30" D. fir stump bears N.67 1/2°W., 35.0 ft. with bark scribe marks "1/4 S" visible on a sawed out block (Rec. N.70°W. 33.3 ft.)  
A 1966 BT, a 9" D. fir, 8 ft. high stump, partially uprooted, bears N.42°E., 18.8 ft. with healed blaze.  
1967 BLM BT, a 12" D. fir, uprooted stump, its root hole bears N.65°E., 35.6 ft.

New BT - A 5" D. fir bears N.32 1/2°E., 67.6 ft. scribed "1/4 S33 BT" with a brass washer "LS 1941" nailed into lower blaze.

Distance to new bearing tree to a nail in root crown at the side and center of the tree. I painted 6" red bands around new bearing trees and all bearing tree faces red and attached bearing tree tags.

116

Township corner for Secs. 1; and 6 of T.32-6; 31 of T.31-6; 36 of T31-7

Found - 5/8" ironrod with al. cap properly mkd. Ren. #89

John H. Markham, Jr.  
For: C & D Lbr.  
Ray Brown party  
chief - Jim Jenks  
Witness  
Jan. 6, 1986  
C.S. 62/30

9" D. fir now 15" bears N.57°W., 10.2 ft. has good scar and is in good condition.  
16" D. fir now 25" bears S.28°W., 42.2 ft. has good scar and is in good condition.  
8" D. fir now 12" bears S.43°E., 44.6 ft. has good scar and is in good condition.  
9" D. fir now a 13" stump, with 10" above ground bears N.72°E., 44.6 ft.

New BT - 15" madrona, bears N.15°E., 65.10 ft. mkd. T 31 S. R 6 W S 117

Section corner for Secs. 2, 3, 10 and 11.

Found - 40" fir stump, N.62°E., 59.4 ft. O.B.T. Covered with metal.  
55" fir, S.16°E., 33.0 ft. O.B.T. New stump.  
40" fir, N.25°W., 46.2 ft. O.B.T. Bark scribes visible.  
17" fir, S.62°E., 48.8 ft. 1964 Cad. New stump.  
10" fir, N.24°E., 16.2 ft. 1982 Cad. Scribe visible.  
Brass cap reference monument, N.62°E., 12.9 ft. 1964 cad. Good shape.

14" Fir corner tree, original, down, broken off at ground.

New BTs - 5" incense cedar, S.9°E., 48.0 ft. scribed "T32S R7W S11 BT"  
3 1/2" D. fir, S.77°E., 24.8 ft. scribed X BT.

No trees available to the southwest. Sections 2, 10 and 11 have been clear cut. Section 11, this past Spring.

5/27/87

118

Section Corner for Sections 3, 4, 9 and 10

Found - 3 1/2" U.S. BLM brass cap on a 2 1/2" x 32" galv. I.P. from which a:  
32" D. fir BT, now a stump, with all scribes visible and well pitched over, bears N.81°W., 38.3 ft.

12" D. fir BT, now snag in rotten condition (was 16"), scribes rotted off, bears N.32°E., 16.5 ft.

16" D. fir BT, now rotten stump, scribes gone, bears S.70°E., 13.9 ft. (Rec. 13.2 ft.)

20" D. fir BT, now 10 ft. high snag, scribes were burnt off, so I RESCRIBED "T32S R7W S9 BT", bears S.54°W., 13.2 ft.

8" D. fir BT, S.48°E., 20.8 ft. is now gone.

22" D. fir BT, now stump, with scribes gone, I RESCRIBED "T32S R7W S3 BT", bears N.11 1/2°E., 40.6 ft. (Rec. 42.3 ft.) Ren. #49

16" D. fir BT, now stump with scribes visible, bears S.30°W., 28.4 ft. (Rec. 30.0 ft.)

Set - Corner area was recently logged over. Prior to logging I tied all bearing trees from existing brass cap and made additional references, then removed brass cap. After logging I replaced brass cap in exactly same place and rescribed some trees as necessary and added new one. All green trees now gone.

New BT - 36" D. fir stump BT, I scribed "T32S R7W S10 BT" bears S.39°E., 32.5 ft. Put fence post, steel, and tag alongside brass cap.

Corner lies approx. 150 ft. North of landing on main spur road.

Bruce A. Shaner  
L.S. 430  
April 17, 1989  
C. S. 63/85