

Douglas County Surveyor's Record of
Government Corners Renewed

32 T. S. 8 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

Section Corner common to Secs. 19 - 20 - 30 - 29. 22
All bearing trees were missing except the Orig. S.E. BT,
which is in very poor shape but has some Orig. scribing Visible.
I set a 7/8" x 30" Hex. drill steel driven 20" in the gr.
for the corner.

New BT's: 6" Fir N.42°W. 13.2 ft. scribed T32SR8SS194186 B.T.
4" Tan Oak N.35°E. 19.1 ft. scribed T32SR8W S204186 B.T.
10" S. Pine S.20°E. 32.6 ft. scribed T32SR8WS294186 B.T.
6" Laurel S.24°W. 28.5 ft. scribed T32SR8WS304186 B.T.
5/17/68 - To. O.K. J.M.P.

RE-PT

RECORDED

105

Lorne Swearingen
For The Robert Dollar Co.
October, 1960
C.S. File No. 51/63

1/4 Section Corner common to Secs. 5 and 6. 23
Found to be missing. One Orig. B.T. remains with scribing
visible but the tree(12" TanOak) is nearly rotted down.
I set a 7/8" x 30" Hex drill steel driven 20" in the gr. For
the corner.

New BT's: 8" Fir N.30°E. 18.3 ft. scribed S 5 1/4 S 4186 B.T.
22" Fir S.52 1/2°W. 37.2 ft. scribed S6 1/4 S 4186 B.T.

N
E
X
T

P
A
G
E

RECORDED
INDEXED
OCT 10 1960
C.S. FILE NO. 51/63